



**Property Damage Appraisers**  
**Condition Report for Assignment Number - 3050245**

**Company:** Avis Budget Liability Unit - C  
**Adjuster:** Jocelyn Ray

**Policy #:**

**Owner:** Marco Diaz

**Claim #:** 13A044259

**DMG - APPRAISAL**

**Recommendation:** Total Loss

**Year/Make/Model:** 2005/Nissan/SENTRA SE

**Type of Loss:** Collision

**License/State:** 6RJW525 CA

**VIN:** 3N1CB51D15L544896

**Interior:** Average

**Paint:** Average

**Paint Comments:**

**Engine:** 1.8L

**Mileage:** 110,528

**Approximate Special Equipment** 0.00

**Special Equipment:**

**Tires: L/F:** 7/32

**R/F:** 7/32

**Size:** 205/55R16

**L/R:** 8/32

**R/R:** 8/32

**Spare:** 0/32

**Type:** Falken

**Equipment List:**

Description

Description

Description

**Loss Recap:**

**Agreed Price:** 0.00

**Old Damage:** 0.00

**Repair Shop:** NA

**Suggested Betterment:** 0.00

**Est. Salvage Value:** 0.00

**Drivable:** No

**Agreed Price After Betterment:** 0.00

**Approximate ACV:** 0.00

**Parts Delay:** Unknown

**Approx. Number of Days to Repair:** 14

**Betterment:**

Description

Amount

0.00

**Old Damage:**

Description

Amount

**LKQ Repl. Assy.:**

Salvage Yard

City

Phone

Contact

see estimate

**Remarks:**

The vehicle was inspected at the owners residence on 5/28/2013 at 11:30a. There may be possible hidden damage after the vehicle is torndown.

The owner was present at the time of inspection. LKQ parts listed as available and cost effective. The vehicle is a Total Loss. I was unable to photo the vehicle registration, the registration was not available at the time of inspection; A photo of the glove box is attached to support.

**Appraiser:** Brandon Martini \_\_\_\_\_ **Date:** \_\_\_\_\_