

 **View Claim Summary - File Number: 07022013-1000023**

[GO BACK](#)

**Claim Summary been saved successfully...**



**Property Damage Specialist**  
P.O. Box 2002, Indio  
California, United States  
92202

## Claim Information

Claim Number : CO13008670  
Policy Number :  
Insurance Company : Robert Moreno Insurance  
Adjuster : Antoinette Simmons  
Date of Loss : 2013-05-02  
Whose Claim : Claimant  
Owner Name : VICO USA INC  
Insured Name : HAGOP KELEDJIAN  
Claimant Name : JUE HUANG  
Inspection Location : Owners Work Place

## Appraisal Information

File Number : 07022013-1000023  
Appraiser : Brandon Martini  
Reinspector : Not Assigned  
Loss Type : Collision  
Inspection Date : 2013-07-03  
Assigned Date/Time :  
Assignment Type : Full Appraisal  
ERT (Days) : 4  
Possible Supplement : Yes

## Vehicle Information

Year : 2007  
Make : Audi  
Model : A8  
Sub-model :

VIN : WAULV44E27N017386  
Plate : 6LMU822  
State : California  
Milage : 77673  
Drivable : Yes  
Primary POI :  
Secondary POI :  
Vehicle Condition : Good  
Interior Condition : Good  
Paint Condition : Good  
Engine : 4.2L

## Repair Information

Recommendation : Repairable  
Estimate 1 Total : 2252.94  
Estimate 2 Total : 0.00  
Estimate 1 Betterment : 0.00  
Estimate 2 Betterment : 0.00  
Supplement 1 Total : 0.00  
Supplement 1 Betterment : 0.00  
Supplement 2 Total : 0.00  
Supplement 2 Betterment : 0.00  
Supplement 3 Total : 0.00  
Supplement 3 Betterment : 0.00  
Supplement 4 Total : 0.00  
Supplement 4 Betterment : 0.00  
Subtotal : 2252.94  
Deductible : 0.00  
Original Net Loss : 2252.94  
Gross Total : 2252.94  
Supplement Net Loss : 0.00

## Tire Information

Make :  
Size :  
Tired Depth (in 32nds)

L/F R/F

L/R R/R

Spare :

## Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

## Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :


## Claim Remarks

The vehicle was inspected at the owners work place on 7/3/2013 at 10a. There may be possible hidden damage after the vehicle is torndown.

The owner was present at the time of inspection. LKQ parts listed as available and cost effective. The vehicle is repairable at this time.

I was unable to photo the vehicle registration, the registration was not available at the time of inspection; A photo of the

glove box is attached to support. The estimated days to repair are 4 and please call 909-917-6777 if you have any questions.







































FOR SUPPLEMENTS CALL RICH PEREA 762-275-6795 OR EMAIL  
pds9593@verizon.net

## Property Damage Specialist

P.O. Box 2002, Indio, CA 92201  
(760) 275-6795  
Fax: (760) 863-5349

Damage Assessed By: Brandon Martini

Appraised For: Antoinette Simmons

Condition Code: Good  
Date of Loss: 5/ 2/2013  
Deductible: UNKNOWN  
File Number: CO13008670  
Claim Number: CO13008670  
Type of Loss: Collision

Insured: Hagob Keledjian  
Claimant: Jue Huang  
Address: 17005 Evergreen Pl., City of Industry, CA 91745  
Telephone: Home Phone: (626) 964-5678  
Owner: Vico USA Inc.

Mitchell Service: 910125

Description: 2007 Audi A8 Quattro  
Body Style: 4D Sed  
VIN: WAULV44E27N017386  
Mileage: 77,673  
OEM/ALT: O  
Color: Black  
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW  
REAR WINDOW DEFOGGER, CRUISE CONTROL, TILT STEERING COLUMN, LEATHER SEAT  
POWER PASSENGER SEAT, TELESCOPIC STEERING COLUMN, PREMIUM SOUND SYSTEM  
ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS, ALUM/ALLOY WHEELS  
NAVIGATION SYSTEM, HIGH INTENSITY DISCHARGE HEADLIGHTS, LEATHER STEERING WHEEL  
FRONT AIR DAM, REAR AIR DAM, TINTED GLASS, GENUINE WOOD TRIM, AUTO AIR CONDITION  
TRIP COMPUTER, SUBWOOFER, TELEMATIC SYSTEMS, UNIVERSAL GARAGE DOOR OPENER  
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM  
AUTOMATIC HEADLIGHTS, SECOND ROW SIDE AIRBAG  
INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR  
SIDE HEAD CURTAIN AIRBAGS, VEHICLE THEFT TRACKING/NOTIFICATION  
DAYTIME RUNNING LIGHTS, ADAPTIVE VARIABLE SUSPENSION  
AM/FM STEREO CD CHANGER/MP3 PLAYER, DRIVER MEMORY SEAT  
ELECTRONIC STABILITY CONTROL, EXTERIOR MEMORY MIRRORS  
FRONT SEATS WITH POWER LUMBAR SUPPORT, INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM  
POWER DISC BRAKES, POWER HEATED ELECTROCHROMATIC EXTERIOR MIRRORS  
POWER LIFTGATE/TRUNK, RAIN SENSING WIPERS, REAR LOCKING DIFFERENTIAL  
REAR WINDOW DIVERSITY ANTENNA, STEERING WHEEL AUDIO CONTROLS  
SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 3/07  
Drive Train: 4.2L Inj 8 Cyl 6A AWD  
License: 6LMU822 CA  
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units	CEG Unit
<u>Front Bumper</u>								
1	004285	BDY	OVERHAUL	Frt Bumper Cover Assy	Existing		3.6 #	3.6
2	005477	BDY	REPAIR	Frt Bumper Cover			3.0* #	3.6
3		REF	REFINISH	Frt Bumper Cover			C 2.5	2.5
<u>Front Lamps</u>								
4	001724	BDY	CHECK/ADJUST	Headlamps			0.4	0.4

ESTIMATE RECALL NUMBER: 07/08/2013 08:19:04 CO13008670

Mitchell Data Version: OEM: JUN\_13\_V

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 1 of 3

Software Version: 7.1.139



Date: 7/ 8/2013 08:24 AM  
Estimate ID: CO13008670  
Estimate Version: 0  
Profile ID: Property Damage Spec  
Qual Recycled Part 900.00 \* 0.8 # 0.8T  
INC # 1.7

5 003635 BDY REMOVE/REPLACE L Front Combination Lamp Assembly  
6 BDY REMOVE/INSTALL Frt Bumper Assy  
7 One Way Auto, 626-289-6126, 98399  
8 Line Markup %20.00

180.00

Front Fender

9 000242 BDY REPAIR L Fender Panel Existing 6.0\* # 3.7  
10 REF REFINISH L Fender Outside C 2.0 2.0  
11 000262 BDY REMOVE/INSTALL L Fender Moulding Existing 0.2 r 0.2  
12 000266 BDY REMOVE/INSTALL L Fender Front Liner Existing INC r 0.3  
13 000270 BDY REMOVE/INSTALL L Fender Rear Liner Existing INC #r 0.4

Rocker/Pillars/Floor

14 001882 BDY REMOVE/INSTALL L Rocker Moulding 1.0 # 1.0

Additional Costs & Materials

15 936014 ADD'L COST Flex Additive 6.00 \* T

ADDITIONAL OPERATIONS

16 REF ADD'L OPR Clear Coat 1.4  
17 933003 BDY \* ADD'L OPR Tint Color 0.5\*  
18 933018 BDY \* ADD'L OPR Mask For Overspray 5.00 \* 0.3\*

Additional Costs & Materials

19 ADD'L COST Paint/Materials 177.00 \* T  
20 ADD'L COST Hazardous Waste Disposal 3.00 \* T

\* - Judgment Item

# - Labor Note Applies

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

## Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals					Amount	
I.	Labor Subtotals											
	Body	15.8	40.00	5.00	0.00	637.00	T				900.00	
	Refinish	5.9	40.00	0.00	0.00	236.00	T				180.00	

IV. Total Adjustments: 0.00  
Net Total: 2,252.94

Point(s) of Impact

11 Left Front Corner (P)

Insurance Co: Robert Moreno Ins - Fullerton CA  
Address: P.O. Box 5185  
Fullerton, CA 92635  
Work Phone: (714) 738-1383  
Fax Phone: (714) 738-5035

Inspection Site: Owners Work Place  
Address: 17005 Evergreen Pl.  
City of Industry, CA 91745  
Inspection Date: 7/ 3/2013

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.  
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND  
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

\*\*\*ANY DAMAGE NOT ON THIS ESTIMATE MUST BE  
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.  
FAILURE TO HAVE REINSPECTION WILL RESULT IN  
NON-PAYMENT!!!!!!!!\*\*\*

Pursuant to California Code of Regulations Section 2695.8(g)  
The insurance company named on this damage estimate warrants that all  
non-original equipment replacement parts listed herein are of like,  
kind, quality, safety, fit and performance as original equipment  
manufacturer replacement crash parts