

PROPERTY DAMAGE SPECIALIST
PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

APPRAISAL REPORT

DAMAGE ASSESSED BY: TONY NGUYEN

FILE NUMBER: TP13002170
CLAIM NUMBER: TP13002170
DATE OF LOSS: 6/13/2013
TYPE OF LOSS: LIABILITY
APPRAISED FOR: ANNI CHUNG / AYC RMIS

ASSIGNMENT DATE: None
CONTACT DATE: None
INSPECTION DATE: 6/20/2013
REC'D DATE: None

INSURED: None

CLAIMANT: ANGELO ROSEELLI

OWNER: ANGELO ROSEELLI
11422 SLENDOR WAY
MORENO VALLEY, CA 92557
(951) 902-0839

BODY SHOP: None

INSPECTION SITE: RESIDENCE
11422 SLENDOR WAY
MORENO VALLEY, CA 92557

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: No
VEHICLE DRIVEABLE: Yes

Comments:

COMPLETED INSPECTION & ESTIMATE OF CLAIMANTS MOTORCYCLE AT RESIDENCE IN MORENO VALLEY ON 6/20/13. CLAIMANT WAS PRESENT & POINTED OUT LEFT SIDE OF BIKE AS COLLISION DAMAGE. HE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES USING AVAILABLE OEM PARTS. V/O CONFIRMED THAT LEFT FRT FARING COULD POLISH OUT. APPROXIMATE REPAIR TIME IS 2 DAYS. INNER-CRANK CASE IS AN OPEN ITEM AREA PENDING TEAR-DOWN. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.

COMPARISON ESTIMATE: 0.00
APPRAISER ESTIMATE: 384.92
AGREED UPON AMOUNT: 0.00

TOWING: 0.00
STORAGE: 0.00
DEDUCTIBLE: NONE

ACTUAL CASH VALUE: 0.00
SALVAGE VALUE: 0.00
SETTLEMENT: 0.00
REPAIR VS. ACV: 0.00

DRAFT/CHECK NUMBER: 0
DRAFT/CHECK AMOUNT: 0.00
DATE ISSUED: None

ESTIMATE FEE: 0.00
TRAVEL EXPENSE: 0.00
PHOTO EXPENSE: 0.00
MISC EXPENSE: 0.00
TOTAL CHARGES: 0.00

Date: 6/25/2013 11:10 AM
Estimate ID: TP13002170
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: ANNI CHUNG / AYC RMIS
(714) 738-1383 ext. 2426

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/13/2013
Deductible: NONE
File Number: TP13002170
Claim Number: TP13002170

Type of Loss: LIABILITY

Claimant: ANGELO ROSEELLI
Owner: ANGELO ROSEELLI
Address: 11422 SLENDOR WAY, MORENO VALLEY, CA 92557
Telephone: Home Phone: (951) 902-0839

Mitchell Service: 911000

Description: 07 YAMAHA FJR 1300 TOURING
VIN: JYARP15Y27A000671
Mileage: 30,920
OEM/ALT: A
Color: BURGUNDY

Vehicle Production Date: 3/07
License: 19X0517 CA

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	REPAIR	POLISH LEFT SIDE FARING	Existing	0.00	0.5*
2	900500	BDY *	REMOVE/REPLACE	CRANK CASE COVER	New	157.25 *	1.3*
3	900500	BDY *	REMOVE/REPLACE	CRANK CASE GASKET	New	17.04 *	INC*
4	900500	BDY *	REMOVE/REPLACE	LEFT REAR FOOT PEDAL	New	20.34 *	0.3*
5	900500	BDY *	REMOVE/REPLACE	LEFT REAR PEDAL RUBBER/COVER	New	15.94 *	0.0*

* - Judgment Item

ESTIMATE RECALL NUMBER: 06/25/2013 11:09:49 TP13002170

Mitchell Data Version: OEM: APR_13_V

MAPP:APR_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
I. Labor Subtotals							II. Part Replacement Summary			
Body		2.1	75.00	0.00	0.00	157.50	Taxable Parts			210.57
							Sales Tax	@ 8.000%		16.85
	Non-Taxable Labor					157.50	Total Replacement Parts Amount			227.42
Labor Summary	2.1					157.50				
III. Additional Costs							IV. Adjustments			Amount
Total Additional Costs						0.00	Insurance Deductible			0.00
							Customer Responsibility			0.00
							I. Total Labor:			157.50
							II. Total Replacement Parts:			227.42
							III. Total Additional Costs:			0.00
							Gross Total:			384.92
							IV. Total Adjustments:			0.00
							Net Total:			384.92

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Inspection Site: RESIDENCE
Address: 11422 SLENDOR WAY
MORENO VALLEY, CA 92557
Inspection Date: 6/20/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all

ESTIMATE RECALL NUMBER: 06/25/2013 11:09:49 TP13002170

Mitchell Data Version: OEM: APR_13_V

MAPP:APR_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 2 of 3

Software Version: 7.0.485

All Rights Reserved

Date: 6/25/2013 11:10 AM
Estimate ID: TP13002170
Estimate Version: 0
Preliminary
Profile ID: * PDS

non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 06/25/2013 11:09:49 TP13002170

Mitchell Data Version: OEM: APR_13_V

MAPP:APR_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3







