

FOR SUPPLEMENTS CALL RICH PEREA 762-275-6795 OR EMAIL
pds9593@verizon.net

Property Damage Specialist

P.O. Box 2002, Indio, CA 92201
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: Brandon Martini

Appraised For: Melissa Gomez

Condition Code: Good
Date of Loss: 5/11/2013
Deductible: 500.00
File Number: CO13008917
Policy No: pdm2009780
Type of Loss: Collision
Claim Number: CO13008917

Insured: Adela Alvarado
Owner: Adela Alvarado
Address: 150 7th ST, Norco, CA 92860
Telephone: Work Phone: (951) 204-6989 Home Phone: (951) 427-0589

Mitchell Service: 913498

Description: 2004 Chevrolet Tahoe LS
Body Style: 4D Ut 116" WB
VIN: 1GNEC13VX4R193597
Mileage: 194,421
OEM/ALT: O
Color: Red
Options: AM-FM STEREO/CDPLAYER(SINGLE), PASSENGER AIRBAG, DRIVER AIRBAG
POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
ANTI-LOCK BRAKE SYS., RUNNING BOARDS, FOG LIGHTS, ALUM/ALLOY WHEELS
LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM
AUTOMATIC HEADLIGHTS, INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR
DAYTIME RUNNING LIGHTS, AM/FM STEREO CASSETTE/CD, FRONT SPLIT BENCH SEAT
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS
SECOND ROW SPLIT FOLDING BENCH SEAT, STEP BUMPER

Vehicle Production Date: 11/03
Drive Train: 4.8L Inj 8 Cyl 2WD
License: 5ZVJ055 CA

Search Code: 572

Additional Equipment: RACK

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units	CEG Unit
<u>Rear Bumper</u>								
1	301574	BDY	REMOVE/INSTALL	Rear Bumper Assy			INC	1.0
2		BDY	OVERHAUL	Rear Bumper Assy			1.4	1.4
3	301577	BDY	REMOVE/REPLACE	Rear Bumper Impact Bar	Qual Recycled Part	250.00 *	INC	1.4T
4				One Way Auto, 626-289-6126, 97345, Bar Only				
5				Line Markup %20.00		50.00		
6	301582	BDY	REMOVE/REPLACE	Rear Ctr Bumper Step Pad	12335696 GM PART	51.55	INC	0.3T

* - Judgment Item

ESTIMATE RECALL NUMBER: 05/16/2013 08:24:20 CO13008917

Mitchell Data Version: OEM: APR_13_V

Software Version: 7.1.137

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 2

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	1.4	40.00	0.00	0.00	56.00 T	Taxable Parts	301.55
						Parts Adjustments	50.00
						Sales Tax @ 9.000%	31.64
						Total Replacement Parts Amount	383.19
Labor Summary	1.4				56.00		
Taxable Labor							
					56.00		
III. Additional Costs						IV. Adjustments	Amount
Total Additional Costs						Insurance Deductible	500.00-
					0.00	Subtotal of Adjustments Exceeds Gross Total	
						Customer Responsibility	439.19-
						I. Total Labor:	56.00
						II. Total Replacement Parts:	383.19
						III. Total Additional Costs:	0.00
						Gross Total:	439.19
						IV. Total Adjustments:	439.19-
						Net Total:	0.00

Point(s) of Impact

6 Rear Center (P)

Insurance Co: Robert Moreno Ins - Fullerton CA
Address: P.O. Box 5185
Fullerton, CA 92635
Work Phone: (714) 738-1383
Fax Phone: (714) 738-5035

Inspection Site: Residence
Address: 150 7th St
Norco, CA 92860

Inspection Date: 5/15/2013

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts