

**Claim Summary been saved successfully...**



**Property Damage Specialist**

P.O. Box 2002, Indio

California, United States

92202

## Claim Information

Claim Number : CO13101963

Policy Number :

Insurance Company : Robert Moreno Insurance

Adjuster : Josh Turner

Date of Loss : 2013-06-27

Whose Claim : Insured

Owner Name : HUONG DU

Insured Name : HUONG DU

Claimant Name :

Inspection Location : RESIDENCE

## Appraisal Information

File Number : 07012013-1000023

Appraiser : Jaime Munoz

Reinspector : Not Assigned

Loss Type : Collision

Inspection Date : 2013-07-05

Assigned Date/Time : 2013-07-03 19:00:00

Assignment Type : Full Appraisal

ERT (Days) : 2

Possible Supplement : YES

## Vehicle Information

Year : 2010

Make : Honda

Model : Accord

Sub-model : EX  
VIN : 1HGCP3F77AA031886  
Plate : 6NEF804  
State : California  
Milage : 51940  
Drivable : Yes  
Primary POI : FRONT  
Secondary POI :  
Vehicle Condition : Good  
Interior Condition : Good  
Paint Condition : Good  
Engine : Good

## Repair Information

Recommendation : Repairable  
Estimate 1 Total : 771.23  
Estimate 2 Total : 0.00  
Estimate 1 Betterment : 0.00  
Estimate 2 Betterment : 0.00  
Supplement 1 Total : 0.00  
Supplement 1 Betterment : 0.00  
Supplement 2 Total : 0.00  
Supplement 2 Betterment : 0.00  
Supplement 3 Total : 0.00  
Supplement 3 Betterment : 0.00  
Supplement 4 Total : 0.00  
Supplement 4 Betterment : 0.00  
Subtotal : 771.23  
Deductible : 500.00  
Original Net Loss : 271.23  
Gross Total : 771.23  
Supplement Net Loss : 0.00

## Tire Information

Make :  
Size :

Tired Depth (in 32nds)

L/F          R/F

L/R          R/R

Spare :

## Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

## Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle :                      Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

## Claim Remarks

Completed the inspection of the owner's vehicle at residence on 7/05/13 .The owner was present during inspection. The owner pointed out related damages to front end of the vehicle, as photos show. Estimate calculated noting remanufactured parts as cost effective saving over OEM as per Insurance guidelines. The vehicle is drivable. No copy of estimate to owner .Advised owner the estimate will be send to insurance company and the claim adjuster insurance company will be in contact with owner. Height of impact was 20 inches . Approx. 2 days for repairs. There is the possibility of a supplement to follow after tear down.



Date: 7/9/2013 06:31 AM  
Estimate ID: CO13101963  
Estimate Version: 0  
Preliminary  
Profile ID: \* Robert Moreno Ins.

FOR SUPPLEMENT CALL RICH PEREA 760-275-6795 OR E MAIL  
pds9593@verizon.net

# PROPERTY DAMAGE SPECIALIST

P.O. BOX 2002, INDIO, CA 92201  
(760) 275-6795  
Fax: (760) 863-5349  
Email: pds9593@verizon.net

Damage Assessed By: JAIME MUNOZ

Appraised For: JOSH TURNER  
(714) 738-1383 ext. 2205

Condition Code: Fair  
Date of Loss: 6/27/2013  
Accident Date: 6/27/2013  
Payer: Insurance  
File Number: CO13101963  
Claim Number: CO13101963

Type of Loss: Collision  
Arrival Date: 7/5/2013  
Deductible: 500.00

Insured: HUONG DU  
Owner: HUONG DU  
Address: 4948 BALDWIN AVE., TEMPLE CITY, CA 91780  
Telephone:  
Cell Phone: (626) 537-8307

Mitchell Service: 911023

Description: 2010 Honda Accord EX  
Body Style: 4D Sed  
VIN: 1HGCP3F77AA031886  
Mileage: 51,940  
OEM/ALT: A  
Color: BLACK  
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW  
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN  
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS  
ALUM/ALLOY WHEELS, AUXILIARY INPUT, AUTOMATIC TRANSMISSION, FRONT AIR DAM  
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM  
AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS  
AM/FM STEREO CD CHANGER/MP3 PLAYER, ELECTRONIC STABILITY CONTROL  
FRONT BUCKET SEATS, FRONT SEATS WITH POWER LUMBAR SUPPORT, INTERIOR AIR FILTER  
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS  
POWER LIFTGATE\TRUNK, STEERING WHEEL AUDIO CONTROLS, SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 7/10  
Drive Train: 3.5L Inj 6 Cyl 5A FWD  
License: 6NEF804 CA  
Search Code: 975

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	103048	BDY	OVERHAUL	Frt Bumper Cover Assy			2.4 #
2	102942	BDY	REMOVE/REPLACE	Frt Bumper Cover	Remanufactured	296.00	INC #
3	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.8
4	100011	BDY	REMOVE/REPLACE	Frt Bumper License Plate Bracket	71145-TA0-A00	20.20	INC #
5	936012		ADD'L COST	Hazardous Waste Disposal		3.00 *	
6	936014		ADD'L COST	Flex Additive		3.00 *	
7	AUTO	REF	ADD'L OPR	Clear Coat			1.1
8	933003	BDY *	ADD'L OPR	Tint Color			0.5*
9	933017	BDY *	ADD'L OPR	Finish Sand And Buff			0.3*
10	AUTO		ADD'L COST	Paint/Materials		124.80 *	

ESTIMATE RECALL NUMBER: 07/09/2013 06:31:43 CO13101963

Mitchell Data Version: JUN\_13\_V  
MAPP:JUN\_13\_V  
Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 1 of 3

\* - Judgment Item  
# - Labor Note Applies  
\*\* QUAL REPL PART - Quality Replacement Parts  
C - Included in Clear Coat Calc

KEYSTONE AUTOMOTIVE  
2530 LINDSAY PRIVADO #3  
ONTARIO  
CA 91761  
(800) 421-7866 (909) 986-4586

2 \*\* HO1000255R 296.00

## Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals												
I.	Labor Subtotals						II.	Part Replacement Summary									Amount	
	Body	3.2	40.00	0.00	0.00	128.00		Taxable Parts									316.20	
	Refinish	3.9	40.00	0.00	0.00	156.00		Sales Tax	@	9.000%							28.46	
		Non-Taxable Labor				284.00		Total Replacement Parts Amount									344.66	
	Labor Summary	7.1				284.00												
III.	Additional Costs					Amount	IV.	Adjustments									Amount	
	Taxable Costs					130.80		Insurance Deductible									500.00-	
	Sales Tax			@	9.000%	11.77		Customer Responsibility									500.00-	
	Total Additional Costs					142.57												
	Paint Material Method: Rates Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00																	
							I.	Total Labor:									284.00	
							II.	Total Replacement Parts:									344.66	
							III.	Total Additional Costs:									142.57	
								Gross Total:									771.23	
							IV.	Total Adjustments:									500.00-	
								Net Total:									271.23	

**THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. ANY WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS, RATHER THAN BY THE ORIGINAL MANUFACTURER OF YOUR VEHICLE.**

**This is a preliminary estimate.**

**Additional changes to the estimate may be required for the actual repair.**

ESTIMATE RECALL NUMBER: 07/09/2013 06:31:43 CO13101963

Mitchell Data Version: JUN\_13\_V

Software Version: MAPP:JUN\_13\_V 7.0.486

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 2 of 3

Point(s) of Impact

12 Front Center (P)

Insurance Co: Robert Moreno Insurance Services  
Address: P.O. BOX 5185  
FULLERTON, CA 92838  
Telephone: (714) 738-1383  
Fax Phone: (714) 738-5035


Inspection Site: HOME  
Address: 4948 BALDWIN AVE  
TEMPLE CITY, CA 91780  
Inspection Date: 7/8/2013

Body Shop: OWNER'S CHOICE OF SHOP

\*\*\*COLLECT ALL FROM OWNER\*\*\*  
\*\*\*THIS IS NOT AN AUTHORIZATION FOR REPAIR OR  
GUARANTEE OF PAYMENT.\*\*\*  
\*\*\*ANY DAMAGE NOT ON THIS ESTIMATE MUST BE  
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.  
FAILURE TO HAVE REINSPECTION WILL RESULT IN  
NON-PAYMENT!!!!!!!!!!\*\*\*

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.  
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND  
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Pursuant to California Code of Regulations Section 2695.8(g)  
The insurance company named on this damage estimate warrants that all  
non-original equipment replacement parts listed herein are of like,  
kind, quality, safety, fit and performance as original equipment  
manufacturer replacement crash parts.





1HGCP3F77AA031886

MFD. BY HONDA OF AMERICA MFG., INC. 07/'10  
GVWR 4575LBS GAWR F 2557LBS R 2061LBS  
GVWR 2075KG GAWR F 1160KG R 935KG  
THIS VEHICLE CONFORMS TO ALL APPLICABLE  
FEDERAL MOTOR VEHICLE SAFETY, BUMPER,  
AND THEFT PREVENTION STANDARDS IN EFFECT  
ON THE DATE OF MANUFACTURE SHOWN ABOVE.  
V.I.N.: 1HGCP3F77AA031886 TYPE: PASSENGER CAR



TAG

A

AA5

- NH737M

- A

- A































