

 **View Claim Summary - File Number: 06252013-100001**[GO BACK](#)**Claim Summary been saved successfully...**

**Property Damage Specialist**  
P.O. Box 2002, Indio  
California, United States  
92202

## Claim Information

Claim Number : co13010465  
Policy Number :  
Insurance Company : Robert Moreno Insurance  
Adjuster : Preston Hobbs  
Date of Loss : -0001-11-30  
Whose Claim : Insured  
Owner Name : Ricardo Rosales Marquez  
Insured Name : Ricardo Rosales Marquez  
Claimant Name :  
Inspection Location :

## Appraisal Information

File Number : 06252013-100001  
Appraiser : Roberta Kear  
Reinspector : Not Assigned  
Loss Type : Collision  
Inspection Date : 2013-06-24  
Assigned Date/Time :  
Assignment Type : Full Appraisal  
ERT (Days) : 11  
Possible Supplement :

## Vehicle Information

Year : 2009  
Make : Toyota  
Model : Corolla  
Sub-model : Xrs

VIN : 1NXBE40EX9Z020738  
Plate : 6ZKZ354  
State : California  
Milage : 107113  
Drivable : Yes  
Primary POI : FRONT BUMPER CENTER  
Secondary POI :  
Vehicle Condition : Good  
Interior Condition : GOOD  
Paint Condition : GOOD  
Engine : GOOD

## Repair Information

Recommendation : Repairable  
Estimate 1 Total : 5704.12  
Estimate 2 Total : 0.00  
Estimate 1 Betterment : 0.00  
Estimate 2 Betterment : 0.00  
Supplement 1 Total : 0.00  
Supplement 1 Betterment : 0.00  
Supplement 2 Total : 0.00  
Supplement 2 Betterment : 0.00  
Supplement 3 Total : 0.00  
Supplement 3 Betterment : 0.00  
Supplement 4 Total : 0.00  
Supplement 4 Betterment : 0.00  
Subtotal : 5704.12  
Deductible : 500.00  
Total : 5204.12  
Original Net Loss : 5704.12  
Supplement Net Loss : 0.00

## Tire Information

Make :  
Size :

Tired Depth (in 32nds)

L/F        R/F

L/R        R/R

Spare :

## Shop Information

Shop Name :        Cali Body Werks

Address 1 :        7750 Sepulveda Blvd. unit 8

Address 2 :

City :                Van Nuys

State :               California

Zip :                  91405

Phone Number :   818-988-9804

Fax :                  818-988-9983

Agreed Price :     Yes

Federal Tax ID # : 10-2267861

## Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle :        Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

## Claim Remarks

06/24/2013 Inspected insured's 2009 Toyota Corolla at Cali Body Werks

at approximately 1:45 pm., met with both Miguel and Steve at the shop.

I noted damage to the front of the customer's vehicle, approximate

repair time is 9 days. This was a minor to moderate impact to the front of customer's vehicle with no airbag deployment. Completed lkq/qrp search and located lkq at Mikes Foreign and K&P auto Salvage, located qrp at Keystone Auto. Vehicle was already partially torn down for this inspection and I had good access to the vehicle, negotiated labor rates, repair/refinish times and polish to the doors vs blend as vehicle is black. No tow bill, noted UPD to front bumper lower spoilers, no refinish was allowed for these due to prior damage. There are no open items at this time. Vehicle is repairable. I faxed a copy of this estimate to the shop at 818-988-9983

Date: 6/25/2013 11:12 AM  
Estimate ID: CO13010465  
Estimate Version: 0  
Preliminary  
Profile ID: \* PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795 OR EMAIL  
PDS9593@VERIZON.NET

## Property Damage Specialist

P O Box 2002, Indio, CA 92201  
(760) 275-6795  
Fax: (760) 863-5349  
Email: PDS9593@VERIZON.NET

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORINO INS. - PRESTON HOBBS  
(800) 453-1588

Condition Code: Good  
Date of Loss: 6/15/2013  
Deductible: 500.00  
File Number: CO13010465  
Claim Number: CO13010465

Type of Loss: Collision

Insured: Ricardo Rosales Marquez  
Owner: Ricardo Rosales Marquez  
Address: 10515 Sharp Ave., Arleta, CA 91331  
Telephone: Home Phone: (323) 440-9256

Cell Phone: (323) 440-9659

Mitchell Service: 911092

Description: 2009 Toyota Corolla XRS  
Body Style: 4D Sed  
VIN: 1NXBE40EX9Z020738  
Mileage: 107,113  
OEM/ALT: A  
Color: BLACK  
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING  
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN  
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS  
ALUM/ALLOY WHEELS, AUXILIARY INPUT, LEATHER STEERING WHEEL  
POWER ADJUSTABLE EXTERIOR MIRROR, AUTOMATIC TRANSMISSION, FRONT AIR DAM  
REAR AIR DAM, TRIP COMPUTER, SIDE AIRBAGS, ANTI-THEFT SYSTEM  
SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER  
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER  
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER LIFTGATE\TRUNK, REAR SPOILER  
STEERING WHEEL AUDIO CONTROLS, SUNROOF/MOONROOF (POWER)

Vehicle Production Date: 3/08  
Drive Train: 2.4L Inj 4 Cyl 5A FWD  
License: 6ZKZ354 CA  
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Information Labels</u>							
1	101592	BDY	REMOVE/REPLACE	Inform Label Service Label	88723-02150	6.55	
2	103420	BDY	REMOVE/REPLACE	Inform Label Emission Control	11298-28700	1.09	
<u>Front Bumper</u>							
3	103426	REF	REFINISH	R Frt Spoiler			C 0.0*
4				UPD REQUIRED PAINT SO NO REFINISH ALLOWED ON THIS			
5	103427	REF	REFINISH	L Frt Spoiler			C 0.0*
6				UPD REQUIRED PAINT SO NO REFINISH ALLOWED ON THIS			
7	100057	BDY	REMOVE/INSTALL	Frt Bumper Cover			INC
8	100058	BDY	OVERHAUL	Frt Bumper Cover Assy			2.0 #
9	103023	BDY	REMOVE/REPLACE	Frt Add w/Fog Lamps			0.4
10	103014	BDY	REMOVE/REPLACE	Frt Add w/Spoiler			0.4

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V  
MAPP:MAY\_13\_V  
Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 1 of 5

11	100650	BDY	REMOVE/REPLACE	Frnt Bumper Cover	Qual Recycled Part	1,000.00	* INC	#r
12		REF	REFINISH	Frnt Bumper Cover			C 2.5	
13				MIKES FOREIGN REF S010 310-830-6200 COMPLETE				
14	100214	BDY	REMOVE/REPLACE	Frnt Bumper Emblem	75301-02010	41.17	INC	
15	100212	BDY	REMOVE/REPLACE	Frnt Bumper License Plate Bracket	Qual Recycled Part	0.00	* INC	
16				INCL W/LKQ ASSY				
17	100216	BDY	REMOVE/REPLACE	Frnt Bumper Grille	Qual Recycled Part	0.00	* INC	
18				INCL IN LKQ ASSY				
19	100218	BDY	REMOVE/REPLACE	R Frt Bumper End Cover	Qual Recycled Part	0.00	* INC	
20				INCL W/LKQ ASSY				
21	100219	BDY	REMOVE/REPLACE	L Frt Bumper End Cover	Qual Recycled Part	0.00	* INC	
22				INCL W/LKQ ASSY				
23	100222	BDY	REMOVE/REPLACE	R Frt Bumper Spoiler	Qual Recycled Part	0.00	* INC	#r
24				INCL W/LKQ ASSY				
25	100223	BDY	REMOVE/REPLACE	L Frt Bumper Spoiler	Qual Recycled Part	0.00	* INC	#r
26				INCL W/LKQ ASSY				
27	100228	BDY	REMOVE/REPLACE	Frnt Bumper Impact Absorber	Qual Recycled Part	0.00	* INC	
28				INCL W/LKQ ASSY				
29	100229	BDY	REMOVE/REPLACE	Frnt Bumper Reinforcement (UHSS)	Qual Recycled Part	0.00	* 0.4	#
30				INCL W/LKQ ASSY				
				<u>Grille</u>				
31	100231	BDY	REMOVE/REPLACE	Grille	53111-02450	136.83	INC	#
32	103606	BDY	REMOVE/REPLACE	Grille Nameplate	75321-12470	29.08	0.2	
				<u>Front Lamps</u>				
33	103128	BDY	REMOVE/REPLACE	R Front Combination Lamp Assembly	Qual Recycled Part	170.00	* 0.3	#r
34		BDY	CHECK/ADJUST	Headlamps			0.4	
35				K&P AUTO 909-428-6898 REF# JB6599				
36				Line Markup %20.00		34.00		
37	103129	BDY	REMOVE/REPLACE	L Front Combination Lamp Assembly	Qual Recycled Part	170.00	* 0.3	#r
38				K&P AUTO 909-428-6898 REF#JB6599				
39				Line Markup %20.00		34.00		
40	103018	BDY	REMOVE/INSTALL	R Front Combination Lamp			INC	#
				<u>Hood</u>				
41	100651	BDY	REMOVE/REPLACE	Hood Panel (HSS)	Qual Recycled Part	240.00	* 1.4	r
42		REF	REFINISH	Add For Hood Underside			C 1.2	
43		REF	REFINISH	Hood Outside			C 2.3	
44				K&P AUTO 909-428-6898 REF#(2 AVAIL)				
45				Line Markup %20.00		48.00		
46	103028	BDY	REMOVE/REPLACE	Hood Insulator Retainer 7@1.49	90467-A0003	10.43		
47	100659	BDY	REMOVE/REPLACE	Hood Latch	53510-02330	49.88	0.3	
				<u>Cooling</u>				
48	103173	BDY	REMOVE/REPLACE	Cooling Radiator	** QUAL REPL PART	167.00	* 1.8	#
49				KEYSTONE AUTO 562-944-6422				
				<u>A/C /Heater/Ventilation</u>				
50	101840	MCH	REMOVE/REPLACE	Air Cond Condenser Assy -M	** QUAL REPL PART	205.00	* 1.3	#
51		MCH	REMOVE/REPLACE	Evacuate & Recharge A/C -M			1.4	
52				KEYSTONE AUTO 562-944-6422				
				<u>Front Fender</u>				
53	100437	BDY	REMOVE/INSTALL	R Fender Mudguard			0.2	
54	100438	BDY	REMOVE/INSTALL	L Fender Mudguard			0.2	
55	100749	BDY	REPAIR	R Fender Panel	Existing		4.0* #	
56		REF	REFINISH	R Fender Outside			C 1.6	
57	100750	BDY	REPAIR	L Fender Panel	Existing		4.0* #	
58		REF	REFINISH	L Fender Outside			C 1.6	
59	100740	BDY	REMOVE/REPLACE	R Fender Liner	53875-02260	95.08	0.4	
60	100741	BDY	REMOVE/REPLACE	L Fender Liner	53876-02260	95.08	0.4	
				<u>Front Inner Structure</u>				
61	100763	BDY	REMOVE/REPLACE	Front Body Upper Tie Bar	53205-02150	94.87	INC	
62		REF	REFINISH	Upper Tie Bar			0.5	

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V

Software Version: MAPP:MAY\_13\_V

7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

63	100767	BDY	REMOVE/REPLACE	Front Body Hood Latch Support	53208-02110	54.31	0.2
64		REF	REFINISH	Hood Latch Support			0.5
<u>Air Bag System</u>							
65	101809	MCH	REMOVE/REPLACE	Disable & Enable Air Bag System -M			0.3
66				REQUIRED DUE TO FRAME PULL			
<u>Additional Costs &amp; Materials</u>							
67	936000		ADD'L COST	Freon & Oil		45.00	*
68	936003		ADD'L COST	Coolant		15.00	*
<u>Electrical</u>							
69	101142	BDY	REMOVE/REPLACE	Horn Assembly	86520-01050	63.58	0.2
<u>Rocker/Pillars/Floor</u>							
70	102988	BDY	REMOVE/INSTALL	R Rocker Moulding			0.4
71	102989	BDY	REMOVE/INSTALL	L Rocker Moulding			0.4
<u>Front Door</u>							
72	102566	BDY	REPAIR	R Frt Door Repair Panel (HSS)	Existing		0.5* #
73				POLISH TO MATCH - BLACK VEHICLE			
74	102567	BDY	REPAIR	L Frt Door Repair Panel (HSS)	Existing		0.5* #
75				POLISH TO MATCH - BLACK VEHICLE			
<u>Additional Costs &amp; Materials</u>							
76	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*
77	936014		ADD'L COST	Flex Additive		8.00	*
<u>FRAME</u>							
78	933006	FRM	ADD'L OPR	FRAME/RACK SET UP			2.0*
79	933035	FRM	ADD'L OPR	UNIBODY PULL			2.0*
<u>MANUAL ENTRIES</u>							
80	900500	BDY *	REMOVE/REPLACE	Mask Jams for primer	** QUAL REPL PART	2.50	* 0.2*
81	900500	MCH *	REPAIR	RESET ELECTRICAL COMPONENTS, INCLUDES AIRB Existing			1.0*
<u>ADDITIONAL OPERATIONS</u>							
82		REF	ADD'L OPR	Clear Coat			2.7
<u>ADDITIONAL REFINISH OPERATIONS</u>							
83	933003	REF	ADD'L OPR	TINT COLOR			0.5*
<u>Additional Operations</u>							
84	933005	BDY	ADD'L OPR	Restore Corrosion Protection		8.00	*
85	933017	BDY *	ADD'L OPR	Finish Sand And Buff			1.5*
86				.5 PER SHEET METAL PANEL			
<u>ADDITIONAL REFINISH OPERATIONS</u>							
87	933018	REF	ADD'L OPR	MASK FOR OVERSPRAY		5.00	* 0.3*
<u>Additional Operations</u>							
88	933026	BDY	ADD'L OPR	LKQ Part Cleanup			1.0*
<u>Additional Costs &amp; Materials</u>							
89			ADD'L COST	Paint/Materials		428.80	*

\* - Judgment Item

# - Labor Note Applies

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

## Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals										
I.	Labor Subtotals						II.	Part Replacement Summary							Amount	
	Body	22.0	44.00	8.00	0.00	976.00		Taxable Parts							2,632.45	
	Refinish	13.7	44.00	5.00	0.00	607.80		Parts Adjustments							116.00	
	Frame	4.0	60.00	0.00	0.00	240.00		Sales Tax	@	9.000%					247.36	
	Mechanical	4.0	85.00	0.00	0.00	340.00										
	Non-Taxable Labor					2,163.80		Total Replacement Parts Amount							2,995.81	
	Labor Summary	43.7				2,163.80										
III.	Additional Costs					Amount	IV.	Adjustments							Amount	
	Taxable Costs					496.80		Insurance Deductible							500.00-	
	Sales Tax			@	9.000%	44.71		Customer Responsibility							500.00-	
	Non-Taxable Costs					3.00										
	Total Additional Costs					544.51										
	Paint Material Method: Rates															
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00															
</																

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

### Point(s) of Impact

12 Front Center (P)

Insurance Co: Robert Moreno Insurance Services  
Address: P O Box 5185  
Fullerton, CA 92838  
Telephone: (714) 578-3366  
Fax Phone: (714) 738-5035

Inspection Site: CALI BODY WORKS  
Address: 7750 SEPULVEDA BLVD. UNIT 8  
VAN NUYS, CA 91405  
(818) 988-9804  
Inspection Date: 6/24/2013

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V

MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 4 of 5



Date: 6/25/2013 11:12 AM  
Estimate ID: CO13010465  
Estimate Version: 0  
Preliminary  
Profile ID: \* PDS

Body Shop: CALI BODY WERKS  
Address: 7750 SEPULVEDA BLVD. UNIT 8  
VAN NUYS, CA 91405  
Telephone: (818) 988-9804  
Fax Phone: (818) 988-9983  
State Lic. No: TIN 10-2267861

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.  
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND  
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V  
MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 5 of 5

Date: 6/25/2013 11:12 AM  
 Estimate ID: CO13010465  
 Unrelated Prior Damage  
 Estimate Version: 0  
 Preliminary  
 Profile ID: \* PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795 OR EMAIL  
 PDS9593@VERIZON.NET

## Property Damage Specialist

P O Box 2002, Indio, CA 92201  
 (760) 275-6795  
 Fax: (760) 863-5349  
 Email: PDS9593@VERIZON.NET

## Unrelated Prior Damage

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORINO INS. - PRESTON HOBBS  
 (800) 453-1588

Condition Code: Good  
 Date of Loss: 6/15/2013

Type of Loss: Collision

File Number: CO13010465  
 Claim Number: CO13010465

Insured: Ricardo Rosales Marquez  
 Owner: Ricardo Rosales Marquez  
 Address: 10515 Sharp Ave., Arleta, CA 91331  
 Telephone: Home Phone: (323) 440-9256

Cell Phone: (323) 440-9659

Mitchell Service: 911092

Description: 2009 Toyota Corolla XRS  
 Body Style: 4D Sed  
 VIN: 1NXBE40EX9Z020738  
 Mileage: 107,113  
 OEM/ALT: A  
 Color: BLACK

Vehicle Production Date: 3/08  
 Drive Train: 2.4L Inj 4 Cyl 5A FWD  
 License: 6ZKZ354 CA

Search Code: None

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING  
 REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN  
 TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS  
 ALUM/ALLOY WHEELS, AUXILIARY INPUT, LEATHER STEERING WHEEL  
 POWER ADJUSTABLE EXTERIOR MIRROR, AUTOMATIC TRANSMISSION, FRONT AIR DAM  
 REAR AIR DAM, TRIP COMPUTER, SIDE AIRBAGS, ANTI-THEFT SYSTEM  
 SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER  
 ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER  
 KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER LIFTGATE/TRUNK, REAR SPOILER  
 STEERING WHEEL AUDIO CONTROLS, SUNROOF/MOONROOF (POWER)

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Bumper</u>							
1	100222	BDY	REPAIR	R Frt Bumper Spoiler	Existing		2.0* #
2		REF	REFINISH	R Frt Spoiler			C 0.8
3	100223	BDY	REPAIR	L Frt Bumper Spoiler	Existing		2.0* #
4		REF	REFINISH	L Frt Spoiler			C 0.8
<u>ADDITIONAL OPERATIONS</u>							
5		REF	ADD'L OPR	Clear Coat			0.3

### Additional Costs & Materials

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V  
 MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
 All Rights Reserved

Page 1 of 3

6 ADD'L COST Paint/Materials

\* - Judgment Item  
# - Labor Note Applies  
C - Included in Clear Coat Calc

## Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary	Amount
	Body	4.0	44.00	0.00	0.00	176.00			
	Refinish	1.9	44.00	0.00	0.00	83.60		Total Replacement Parts Amount	0.00
	Non-Taxable Labor					259.60			
	Labor Summary	5.9				259.60			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					60.80		Total Adjustments:	0.00
	Sales Tax		@	9.000%		5.47			
	Total Additional Costs					66.27			
	Paint Material Method: Rates								
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
	I.	Total Labor:							259.60
	II.	Total Replacement Parts:							0.00
	III.	Total Additional Costs:							66.27
		Gross Total:							325.87
	IV.	Total Adjustments:							0.00
		Unrelated Damage Net Total:							325.87

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

### Point(s) of Impact

12 Front Center (P)

Insurance Co: Robert Moreno Insurance Services  
Address: P O Box 5185  
Fullerton, CA 92838  
Telephone: (714) 578-3366  
Fax Phone: (714) 738-5035

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V

MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 2 of 3

Date: 6/25/2013 11:12 AM  
Estimate ID: CO13010465  
Unrelated Prior Damage  
Estimate Version: 0  
Preliminary  
Profile ID: \* PDS

Inspection Site: CALI BODY WORKS  
Address: 7750 SEPULVEDA BLVD. UNIT 8  
VAN NUYS, CA 91405  
(818) 988-9804  
Inspection Date: 6/24/2013

Body Shop: CALI BODY WERKS  
Address: 7750 SEPULVEDA BLVD. UNIT 8  
VAN NUYS, CA 91405  
Telephone: (818) 988-9804  
Fax Phone: (818) 988-9983  
State Lic. No: TIN 10-2267861

ESTIMATE RECALL NUMBER: 06/25/2013 11:12:26 CO13010465

Mitchell Data Version: OEM: MAY\_13\_V  
MAPP:MAY\_13\_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International  
All Rights Reserved

Page 3 of 3



















































# AUTO BODY -LABOR RATES-

PAINT AND BODY LABOR  
STRUCTURAL LABOR  
FRAME STRAIGHTENING  
MECHANICAL LABOR  
ELECTRICAL LABOR  
PAINT MATERIALS  
INSIDE STORAGE  
OUTSIDE STORAGE  
TOWING

44<sup>00</sup> PER HOUR  
65<sup>00</sup> PER HOUR  
65<sup>00</sup> PER HOUR  
110<sup>00</sup> PER HOUR  
95<sup>00</sup> PER HOUR  
36<sup>00</sup> PER PAINT  
55<sup>00</sup> PER DAY  
45<sup>00</sup> PER DAY  
PER MILE

THIS FACILITY USES HOURS PUBLISHED IN OUR FLAT RATE GUIDE WHICH REFLECTS AN AVERAGE TIME REQUIRED FOR A SPECIFIC REPAIR WHICH MAY BE MORE OR LESS ACTUAL TIME EXPENDED FOR REPAIRS.

06/24/2013



06/24/2013





