

 **View Claim Summary - File Number: 06112013-1000033**

GO BACK

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13101879
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Shelley Ambriz
Date of Loss : -0001-11-30
Whose Claim : Insured
Owner Name : FRANCISCO PEREZROMERO
Insured Name : FRANCISCO PEREZROMERO
Claimant Name :
Inspection Location :

Appraisal Information

File Number : 06112013-1000033
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement : YES

Vehicle Information

Year : 2010
Make : Jeep
Model : Comander
Sub-model : SPORT
VIN : 1J4RG4GK0AC125463
Plate : 6KHH744

State : California
Milage : 78666
Drivable : Yes
Primary POI : REAR COVER
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 488.92
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 488.92
Deductible : 0.00
Original Net Loss : 488.92
Gross Total : 488.92
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT RESIDENCE IN HEMET ON 7/3/13. INSURED WAS PRESENT & POINTED OUT REAR BUMPER AS COLLISION DAMAGE. HE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES TO REPAIR BUMPER. A UPD ESTIMATE ATTACHED FOR LIFTGATE DAMAGE. APPROXIMATE REPAIR TIME IS 2 DAYS. REAR BUMPER REBAR AND BODY ARE OPEN ITEM AREA PENDING TEAR-DOWN. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.

Date: 7/7/2013 01:29 PM
Estimate ID: CO13101879
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: SHELLEY AMBRIZ / SLA
(714) 738-1383 ext. 2396

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/8/2013
Deductible: 500.00
File Number: CO13101879
Claim Number: CO13101879

Type of Loss: Property Damage

Insured: FRANCISCO ROMERO PEREZ
Owner: FRANCISCO ROMERO PEREZ
Address: 230 LINDA LANE, HEMET, CA 92544
Telephone: Work Phone: (951) 488-4690

Home Phone: (951) 488-4096

Mitchell Service: 910587

Description: 2010 Jeep Commander Sport
Body Style: 4D Ut
VIN: 1J4RG4GK0AC125463
Mileage: 78,666
OEM/ALT: A
Color: SILVER
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, LUGGAGE RACK, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
FOG LIGHTS, ALUM/ALLOY WHEELS, AUXILIARY INPUT, SATELLITE RADIO, 4WD OR AWD
FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER, THIRD ROW SPLIT BENCH SEAT
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC PARKING AID
ELECTRONIC STABILITY CONTROL, FENDER FLARES, FRONT BUCKET SEATS
KEYLESS ENTRY SYSTEM, LIMITED SLIP DIFFERENTIAL, POWER DISC BRAKES
POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK, REAR WINDOW WIPER
SECOND ROW SPLIT FOLDING BENCH SEAT, STEERING WHEEL AUDIO CONTROLS

Vehicle Production Date: 11/09
Drive Train: 3.7L Inj 6 Cyl 4WD
License: 6KHH744 CA

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	001723	BDY	OVERHAUL	Rear Bumper Assy			2.0
2	003171	BDY	REPAIR	Rear Bumper Cover	Existing		2.0*
3	AUTO	REF	REFINISH	Rear Bumper Cover			C 2.6
4	AUTO	REF	ADD'L OPR	Clear Coat			1.0
5	933003	BDY *	ADD'L OPR	Tint Color			0.5*

ESTIMATE RECALL NUMBER: 07/07/2013 13:29:09 CO13101879

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 7/7/2013 01:29 PM
 Estimate ID: CO13101879
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS
 115.20 *

6 AUTO ADD'L COST Paint/Materials

* - Judgment Item
 C - Included in Clear Coat Calc

Prior Damage:
 LIFTGATE

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary	Amount
	Body	4.5	45.00	0.00	0.00	202.50			
	Refinish	3.6	45.00	0.00	0.00	162.00		Total Replacement Parts Amount	0.00
	Non-Taxable Labor					364.50			
	Labor Summary	8.1				364.50			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					115.20		Insurance Deductible	500.00-
	Sales Tax @ 8.000%					9.22		Subtotal of Adjustments Exceeds Gross Total	
	Total Additional Costs					124.42		Customer Responsibility	488.92-
	Paint Material Method: Rates								
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
							I.	Total Labor:	364.50
							II.	Total Replacement Parts:	0.00
							III.	Total Additional Costs:	124.42
								Gross Total:	488.92
							IV.	Total Adjustments:	488.92-
								Net Total:	0.00

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
 6 Rear Center (P)

ESTIMATE RECALL NUMBER: 07/07/2013 13:29:09 CO13101879

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Date: 7/7/2013 01:29 PM
Estimate ID: CO13101879
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 230 LINDA LN
HEMET, CA 92544
Inspection Date: 7/3/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/07/2013 13:29:09 CO13101879

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 7/7/2013 01:28 PM
Estimate ID: CO13101879
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Unrelated Prior Damage

Damage Assessed By: TONY NGUYEN

Appraised For: SHELLEY AMBRIZ / SLA
(714) 738-1383 ext. 2396

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/8/2013

Type of Loss: Property Damage

File Number: CO13101879
Claim Number: CO13101879

Insured: FRANCISCO ROMERO PEREZ
Owner: FRANCISCO ROMERO PEREZ
Address: 230 LINDA LANE, HEMET, CA 92544
Telephone: Work Phone: (951) 488-4690

Home Phone: (951) 488-4096

Mitchell Service: 910587

Description: 2010 Jeep Commander Sport
Body Style: 4D Ut
VIN: 1J4RG4GK0AC125463
Mileage: 78,666
OEM/ALT: A
Color: SILVER
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW

Vehicle Production Date: 11/09
Drive Train: 3.7L Inj 6 Cyl 4WD
License: 6KHH744 CA

Search Code: None

REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, LUGGAGE RACK, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
FOG LIGHTS, ALUM/ALLOY WHEELS, AUXILIARY INPUT, SATELLITE RADIO, 4WD OR AWD
FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER, THIRD ROW SPLIT BENCH SEAT
VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC PARKING AID
ELECTRONIC STABILITY CONTROL, FENDER FLARES, FRONT BUCKET SEATS
KEYLESS ENTRY SYSTEM, LIMITED SLIP DIFFERENTIAL, POWER DISC BRAKES
POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE/TRUNK, REAR WINDOW WIPER
SECOND ROW SPLIT FOLDING BENCH SEAT, STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	001712	BDY	REMOVE/INSTALL	Liftgate Handle			0.6 #

ESTIMATE RECALL NUMBER: 07/07/2013 13:28:20 CO13101879

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 1 of 3

Software Version: 7.0.486

All Rights Reserved

Date: 7/7/2013 01:28 PM
 Estimate ID: CO13101879
 Unrelated Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

2	002475	BDY	REPAIR	Liftgate Shell	Existing	1.0*
3	AUTO	REF	REFINISH	Liftgate Outside		C 2.4
4	002485	BDY	REMOVE/REPLACE	Liftgate Adhesive Nameplate	55157091AD	38.75 0.2
5	001713	BDY	REMOVE/INSTALL	Liftgate Trim Panel		INC
6	001408	BDY	REMOVE/INSTALL	Liftgate Wiper Arm	Existing	0.2 #r
7	001409	BDY	REMOVE/INSTALL	Liftgate Wiper Arm Lifter	Existing	0.1 #r
8	AUTO	REF	ADD'L OPR	Clear Coat		1.0
9	AUTO		ADD'L COST	Paint/Materials		108.80 *

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Prior Damage:
 LIFTGATE

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Taxable Parts				
Body	2.1	45.00	0.00	0.00	94.50	Sales Tax	@	8.000%	38.75	
Refinish	3.4	45.00	0.00	0.00	153.00				3.10	
Non-Taxable Labor					247.50	Total Replacement Parts Amount			41.85	
Labor Summary	5.5				247.50					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					108.80	Total Adjustments:				0.00
Sales Tax @ 8.000%					8.70					
Total Additional Costs					117.50					
Paint Material Method: Rates										
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00										
						I.	Total Labor:			247.50
						II.	Total Replacement Parts:			41.85
						III.	Total Additional Costs:			117.50
							Gross Total:			406.85
						IV.	Total Adjustments:			0.00
							Unrelated Damage Net Total:			406.85

ESTIMATE RECALL NUMBER: 07/07/2013 13:28:20 CO13101879

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Date: 7/7/2013 01:28 PM
Estimate ID: CO13101879
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

6 Rear Center (P)

Inspection Site: RESIDENCE
Address: 230 LINDA LN
HEMET, CA 92544
Inspection Date: 7/3/2013

ESTIMATE RECALL NUMBER: 07/07/2013 13:28:20 CO13101879

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3











