

 **View Claim Summary - File Number: 07022013-100007**

[GO BACK](#)

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010409
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Kyle Sakazaki
Date of Loss : 2013-06-13
Whose Claim : Claimant
Owner Name : VIRGINA FERNANDEZ
Insured Name : HUY TANG
Claimant Name : VIRGINA FERNANDEZ
Inspection Location : CLAIMANT RESIDENCE

Appraisal Information

File Number : 07022013-100007
Appraiser : Roberta Kear
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time : 2013-07-02 19:00:00
Assignment Type : Full Appraisal
ERT (Days) : 2
Possible Supplement :

Vehicle Information

Year : 2007
Make : Chevrolet
Model : Malibu
Sub-model : LT

VIN : 1G1ZT58N77F209876
Plate : 6KSX518
State : California
Milage : 68283
Drivable : Yes
Primary POI : REAR
Secondary POI : FRONT
Vehicle Condition : Good
Interior Condition : GOOD
Paint Condition : GOOD
Engine : 3.5L 6 CYL

Repair Information

Recommendation : Repairable
Estimate 1 Total : 692.07
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 692.07
Deductible : 0.00
Original Net Loss : 692.07
Gross Total : 692.07
Supplement Net Loss : 0.00

Tire Information

Make : BRIDGESTONE
Size :
Tired Depth (in 32nds)

L/F R/F

L/R R/R

Spare :

Shop Information

Shop Name : NO SHOP INFORMATION

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

7/3/2013 - I INSPECTED THE CLAIMANT'S 2007 CHEVROLET MALIBU LT AT THE CLAIMANT'S RESIDENCE, 673 CLELA AVE, LOS ANGELES AT APPROX 11:45 AM. CONTACT WAS WITH THE CLAIMANT VIRGINIA.

I NOTED DAMAGE TO BOTH THE FRONT & REAR OF THE VEHICLE. APPROX REPAIR TIME IS 2 DAYS & THE VEHICLE IS DRIVABLE.

POI #1 WAS A MINOR TO MODERATE IMPACT TO THE REAR OF THE VEHICLE.

CUSTOMER STATED THAT SHE WAS PUSHED INTO ANOTHER VEHICLE AND THE FRONT WAS A MINOR TO MODERATE IMPACT TO THE FRONT OF THE VEHICLE WITH NO AIRBAG DEPLOYMENT. I WROTE A UPD ESTIMATE FOR THE FRONT OF CUSTOMER'S VEHICLE AS I NEED ADJUSTER TO CONFIRM THAT FRONT BUMPER IS RELATED.

LKQ/QRP SEARCH FOUND A REAR BUMPER ASSY AT LKQ OF SOCAL, 800-525-3667, REF #99501979.

NO BETTERMENR WAS APPLIED. NO TOW BILL.

NO SHOP INFORMATION.

OPEN ITEMS INCLUDE SHOP LABOR RATES, EXPENSES, DETRIM & POSSIBLE ADDITIONAL DAMAGE AFTER TEARDOWN.

THIS VEHICLE IS REPAIRABLE.

Date: 7/ 8/2013 03:16 PM
Estimate ID: CO13010409-C
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
PDS9593@VERIZON.NET

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORENO INSURANCE KYLE SAKAZAKI

Condition Code: Good
Date of Loss: 6/13/2013
Deductible: NONE
File Number: CO13010409-C
Claim Number: CO13010409-C

Type of Loss: Property Damage

Insured: TANG HUY
Claimant: VIRGINIA FERNANDEZ
Address: 673 CLELA AVE, LOS ANGELES, CA 90023
Telephone: Home Phone: (562) 230-8059
Owner: VIRGINIA FERNANDEZ
Address: 673 CLELA AVE, LOS ANGELES, CA 90023
Telephone: Home Phone: (562) 230-8059

Cell Phone: (323) 264-8851

Mitchell Service: 910161

Description: 2007 Chevrolet Malibu LT
Body Style: 4D Sed
VIN: 1G1ZT58N77F209876
Mileage: 68,283
OEM/ALT: A
Color: GRAY MET

Drive Train: 3.5L Inj 6 Cyl 4A FWD
License: 6KSX518 CA

Search Code: None

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS, VARIABLE ASSISTED STEERING
ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS
DAYTIME RUNNING LIGHTS, AM/FM STEREO CD, FRONT BUCKET SEATS
KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER LIFTGATE\TRUNK
STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rear Bumper</u>							
1	001649	BDY	OVERHAUL	Rear Bumper Cover Assy			1.5
2	001004	BDY	REMOVE/REPLACE	Rear Bumper Cover	Qual Recycled Part	250.00 *	INC r
3		REF	REFINISH	Rear Bumper Cover			C 2.5
4				LKQ LAKENOR, 800-525-3667, REF#99501979			
5				Line Markup %20.00		50.00	
<u>Additional Costs & Materials</u>							
6	936012		ADD'L COST	Hazardous Waste Disposal		3.00 *	
7	936014		ADD'L COST	Flex Additive		8.00 *	
<u>ADDITIONAL OPERATIONS</u>							
8		REF	ADD'L OPR	Clear Coat			1.0
9	933003	BDY *	ADD'L OPR	Tint Color			0.5*

ESTIMATE RECALL NUMBER: 07/08/2013 15:16:24 CO13010409-C

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

10 ADD'L COST Paint/Materials 112.00 *

* - Judgment Item
C - Included in Clear Coat Calc
r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary	Amount
	Body	2.0	42.00	0.00	0.00	84.00		Taxable Parts	250.00
	Refinish	3.5	42.00	0.00	0.00	147.00		Parts Adjustments	50.00
								Sales Tax @ 9.000%	27.00
	Non-Taxable Labor					231.00		Total Replacement Parts Amount	327.00
	Labor Summary	5.5				231.00			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					123.00		Insurance Deductible	0.00
	Sales Tax			@	9.000%	11.07		Customer Responsibility	0.00
	Total Additional Costs					134.07			
	Paint Material Method: Rates								
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00								

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

6 Rear Center (P), 12 Front Center (S)

Insurance Co: ROBERT MORENO INSURANCE SERVICES
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

ESTIMATE RECALL NUMBER: 07/08/2013 15:16:24 CO13010409-C

Mitchell Data Version: OEM: MAY_13_V

MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Date: 7/8/2013 03:16 PM
Estimate ID: CO13010409-C
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: CLAIMANT'S RESIDENCE
Address: 673 CLELA AVE
LOS ANGELES, CA 90023
Inspection Date: 7/3/2013

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

ESTIMATE RECALL NUMBER: 07/08/2013 15:16:24 CO13010409-C

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 7/8/2013 03:16 PM
 Estimate ID: CO13010409-C
 Unrelated Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA, 760-275-6795 OR EMAIL
 PDS9593@VERIZON.NET

Property Damage Specialist

P.O. BOX 3237, INDIO, CA 92201
 (760) 275-6795
 Fax: (760) 863-5349
 Email: PDS9593@VERIZON.NET

Unrelated Prior Damage

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORENO INSURANCE KYLE SAKAZAKI

Condition Code: Good
 Date of Loss: 6/13/2013

Type of Loss: Property Damage

File Number: CO13010409-C
 Claim Number: CO13010409-C

Insured: TANG HUY
 Claimant: VIRGINIA FERNANDEZ
 Address: 673 CLELA AVE, LOS ANGELES, CA 90023
 Telephone: Home Phone: (562) 230-8059
 Owner: VIRGINIA FERNANDEZ
 Address: 673 CLELA AVE, LOS ANGELES, CA 90023
 Telephone: Home Phone: (562) 230-8059

Cell Phone: (323) 264-8851

Mitchell Service: 910161

Description: 2007 Chevrolet Malibu LT
 Body Style: 4D Sed
 VIN: 1G1ZT58N77F209876
 Mileage: 68,283
 OEM/ALT: A
 Color: GRAY MET

Drive Train: 3.5L Inj 6 Cyl 4A FWD
 License: 6KSX518 CA

Search Code: None

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
 REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
 TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
 LEATHER STEERING WHEEL, FRONT AIR DAM, TINTED GLASS, VARIABLE ASSISTED STEERING
 ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS
 DAYTIME RUNNING LIGHTS, AM/FM STEREO CD, FRONT BUCKET SEATS
 KEYLESS ENTRY SYSTEM, POWER DISC BRAKES, POWER LIFTGATE/TRUNK
 STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Front Bumper</u>							
1	002868	BDY	REPAIR	Frnt Bumper Cover	Existing		2.0* #
2		REF	REFINISH/REPAIR	Frnt Bumper Cover			C 1.3*
3				MODIFIED REFINISH WITH FULL CLEAR COAT			
4	002325	BDY	REMOVE/REPLACE	Frnt Bumper License Plate Bracket	15274497 GM PART	32.63	0.2
<u>ADDITIONAL OPERATIONS</u>							
5		REF	ADD'L OPR	Clear Coat			1.0

Additional Costs & Materials

ESTIMATE RECALL NUMBER: 07/08/2013 15:16:24 CO13010409-C

Mitchell Data Version: OEM: MAY_13_V
 MAPP:MAY_13_V

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Software Version: 7.0.485

Page 1 of 3

6	ADD'L COST	Paint/Materials
---	------------	-----------------

*** - Judgment Item**
- Labor Note Applies
C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	Taxable Parts				32.63
Body	2.2	42.00	0.00	0.00	92.40	Sales Tax @ 9.000%				2.94
Refinish	2.3	42.00	0.00	0.00	96.60	Total Replacement Parts Amount				35.57
Non-Taxable Labor					189.00					
Labor Summary	4.5				189.00					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					73.60	Total Adjustments:				0.00
Sales Tax @ 9.000%					6.62					
Total Additional Costs					80.22					
Paint Material Method: Rates										
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00										
						I.	Total Labor:			189.00
						II.	Total Replacement Parts:			35.57
						III.	Total Additional Costs:			80.22
							Gross Total:			304.79
						IV.	Total Adjustments:			0.00
							Unrelated Damage Net Total:			304.79

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

6 Rear Center (P), 12 Front Center (S)

Insurance Co: ROBERT MORENO INSURANCE SERVICES
Address: P.O. BOX 5185
FULLERTON, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Date: 7/ 8/2013 03:16 PM
Estimate ID: CO13010409-C
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: CLAIMANT'S RESIDENCE
Address: 673 CLELA AVE
LOS ANGELES, CA 90023
Inspection Date: 7/ 3/2013

ESTIMATE RECALL NUMBER: 07/08/2013 15:16:24 CO13010409-C

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3







































AUTO 12/14/2011 TO 12/14/2012 11 6KSX518

VEHICLE IDENTIFICATION NUMBER
1G1ZT58N77F209876

BODY TYPE MODEL
4D

DATE ISSUED
12/18/2011

CYLS

120

DATE FIRST SOLD

00/00/2006

CLASS

CH

MAKE
CHEV

YEAR

2009

Y. MAKE

2007

TOTAL FEES PAID
\$150

1900

FERNANDEZ VIRGINIA
OR PRADO EZEQUIEL
673 CLELA AVE
LOS ANGELES CA 90022-3119



R0069
L0051

RI0121520114102

STATE OF CALIFORNIA
DEPARTMENT OF MOTOR VEHICLES
VALIDATED REGISTRATION CARD
READ REVERSE SIDE - IMPORTANT INSTRUCTIONS

G 61399228 07/02/2013