



Property Damage Appraisers

Total Loss Condition Report for Assignment Number - 3050133

Company: Financial Pacific - Rocklin CA

Owner: VIRGNIA ULIBARRI

Adjuster: IRENE BAKER

Policy #:

Claim #: 0415004420

DMG - APPRAISAL

Recommendation: Total Loss

Year/Make/Model: 2003/Toyota/Camry XLE

Type of Loss: Collision

License/State: CANDAO CA

VIN: 4T1BF32K73U044531

Interior: Average

Paint: Average

Paint Comments:

Engine: 3.0L

Mileage: 84,962

Approximate Special Equipment 0.00

Special Equipment:

Tires: L/F: 7/32

R/F: 7/32

Spare: 0/32

Size: 215/60R16

L/R: 8/32

R/R: 8/32

Type: Cooper

Dealer Quotes:

<u>Name</u>	<u>City</u>	<u>Phone</u>	<u>Contact</u>	<u>InStock</u>	<u>Amount</u>
-------------	-------------	--------------	----------------	----------------	---------------

Adjustments:

<u>Description:</u>	<u>Amount</u>
Detail	0.00
Paint	0.00
Tires	0.00
Upholstery	0.00
Old Damage	0.00
	<u>0.00</u>

Salvage Bids:

<u>Name</u>	<u>City</u>	<u>Phone</u>	<u>Contact</u>	<u>Amount</u>
Hi Way Auto	San Bernardino	(909) 887-9332	Ray	750.00
Quick Cars	S. California	(714) 994-4430	Carole	888.00
One Way Auto	Alhambra	(626) 289-6126	James	907.00

Salvage Location:

<u>Location</u>	<u>Charges To Date</u>	<u>Rate Per Day</u>	<u>Towing Charges</u>	<u>Owner Interested in Retaining Salvage</u>
with owner	0.00	0.00	0.00	No

Book Quotes:

<u>Description</u>	<u>=</u>	<u>=</u>
	<u>0.00</u>	<u>0.00</u>

**Property Damage Appraisers****Total Loss Condition Report for Assignment Number - 3050133****Company:** Financial Pacific - Rocklin CA**Owner:** VIRGNIA ULIBARRI**Adjuster:** IRENE BAKER**Policy #:****Claim #:** 0415004420**DMG - APPRAISAL****ACV Calculations:**

<u>Description:</u>	<u>Amount</u>
1)Book Value: Average	0.00
2)Average of Quotes	0.00
3)Average Lines 1 & 2	0.00
4)Adjustments	0.00
5)Suggested ACV	0.00
6)Sales Tax @ 0.000 %	0.00
7)Grand Total	0.00

Remarks:

The vehicle was inspected at the owners residence on 5/15/2013 at 11:30a. There may be possible hidden damage after the vehicle is torndown.

The owner was present at the time of inspection. LKQ parts listed as available and cost effective. The vehicle is a Total Loss. I was unable to photo the vehicle registration, the registration was not available at the time of inspection; A photo of the glove box is attached to support.

Appraiser: Brandon Martini _____ **Date:** _____