

Date: 6/26/2013 05:48 PM
 Estimate ID: C013101933
 Estimate Version: 0
 Preliminary
 Profile ID: PDS

For Supplements Call Rich Perea 760-275-6795 or email
 pds9593@verizon.net

Property Damage Specialists

PO Box 2002, Indio, CA 92202
 (760) 275-6795
 Fax: (760) 863-5349

Damage Assessed By: Keagan Miles

Date of Loss: 6/21/2013
 Deductible: 500.00
 File Number: C013101933
 Claim Number: C013101933

Insured: Scott Allen Wasko
 Owner: Scott Allen Wasko
 Address: Box 888, Palm Springs, CA 92260

Mitchell Service: 911455

Description: 2012 Mercedes-Benz Sprinter 3500 High Roof

Body Style: VanCrgo 170" WB
 VIN: WD3PF4CC8C5624351

Mileage: 23,776

OEM/ALT: O

Color: White

Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, TILT STEERING COLUMN
 ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FRONT AIR DAM, TINTED GLASS
 VARIABLE ASSISTED STEERING, ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS
 KEYLESS ENTRY SYSTEM, PASSENGER SIDE SLIDING DOOR, POWER DISC BRAKES

Drive Train: 3.0L Turbo Inj 6 Cyl Dsl RWD
 License: 6XTV499 CA

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rocker/Pillars</u>							
1	101433	REF	REFINISH	R Door Opening Panel			C 3.3
2	101434	REF	REFINISH	L Door Opening Panel			C 3.3
3	101453	BDY	REPAIR	R Door Opening Panel	Existing		1.0*
4	101410	BDY	REMOVE/REPLACE	R Ctr Pillar Garnish	906 692 27 00 7J69	104.00	0.6
5	101411	BDY	REMOVE/REPLACE	L Ctr Pillar Garnish	906 692 26 00 7J69	104.00	0.6
<u>Air Bag System</u>							
6	100237	MCH	REMOVE/REPLACE	Air Bag Module-Driver Front -M	906 860 12 02	1,770.00	INC
7	102236	MCH	REMOVE/REPLACE	Air Bag Clockspring -M	906 464 01 18	236.00	1.1
8		REF	REFINISH/REPAIR	Air Bag Clockspring -M			
9	100239	MCH	REMOVE/REPLACE	Air Bag Module-Passenger Front -M	ORDER FROM DEALER	1,290.00	INC
<u>Steering Wheel/Column</u>							
10	101174	MCH	REMOVE/REPLACE	Steering Wheel -M	906 464 02 01 9E37	152.00	INC
11	101176	MCH	REMOVE/REPLACE	Steering Electronic Control Module -M	906 462 01 30	290.00	1.2
<u>Windshield</u>							
12	100171	GLS	REMOVE/REPLACE	W/Shield Glass	906 670 09 01	432.00	3.2 #
13	101902	BDY	REMOVE/REPLACE	W/Shield Rear View Mirror	639 810 05 17	40.00	INC
14	101904	BDY	REMOVE/REPLACE	R W/Shield Sun Visor	906 810 01 10	42.00	0.2
15	101905	BDY	REMOVE/REPLACE	L W/Shield Sun Visor	906 810 00 10	42.00	0.2
<u>Instrument Panel</u>							
16	101304	MCH	REMOVE/REPLACE	Inst Panel -M	906 680 00 06 9E80	560.00	7.0

ESTIMATE RECALL NUMBER: 06/26/2013 17:47:59 C013101933

Mitchell Data Version: OEM: MAY_13_V

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 1 of 4

Software Version: 7.0.485

17	101283	BDY	REMOVE/REPLACE	Ctr Inst Panel Bezel	906 680 00 17 9B27	28.50	INC
18	101337	BDY	REMOVE/REPLACE	Ctr Inst Panel Console	906 680 00 31 7J69	73.00	
19	100180	BDY	REMOVE/REPLACE	CD Changer	211 870 38 89	1,180.00	0.7
<u>Front Seat</u>							
20	100247	MCH	REMOVE/REPLACE	Pass Side Seat Assy -M	000 910 63 01 9G66	740.00	0.5
21	100250	MCH	REMOVE/REPLACE	Driver Side Seat Assy -M	000 910 61 01 9G66	1,280.00	0.5
<u>Seat Belts</u>							
22	101048	BDY	REMOVE/REPLACE	R Frt Seat Belt	906 860 07 85 9A86	212.00	0.4 #
23	101049	BDY	REMOVE/REPLACE	L Frt Seat Belt	906 860 23 85 9A86	212.00	0.4 #
<u>Front Door</u>							
24	101075	BDY	REPAIR	R Frt Door Shell	Existing		2.0* #
25		REF	REFINISH	R Frt Door Outside			C 2.6
26	101076	BDY	REPAIR	L Frt Door Shell	Existing		3.5* #
27		REF	REFINISH	L Frt Door Outside			C 2.4
28	101077	BDY	REMOVE/INSTALL	R Frt Rear View Mirror			0.3
29	101078	BDY	REMOVE/INSTALL	L Frt Rear View Mirror			0.3
30	101099	BDY	REMOVE/REPLACE	R Frt Door Adhesive Nameplate	906 817 33 14	20.00	0.2
31	101100	BDY	REMOVE/REPLACE	L Frt Door Adhesive Nameplate	906 817 33 14	20.00	0.2
32	101101	BDY	REMOVE/INSTALL	R Frt Door Adhesive Moulding	Existing		0.2 r
33	101102	BDY	REMOVE/INSTALL	L Frt Door Adhesive Moulding	Existing		0.2 r
34	100296	BDY	REMOVE/REPLACE	R Frt Door Trim Panel Assy	906 727 01 71	154.00	0.2
35	100297	BDY	REMOVE/REPLACE	L Frt Door Trim Panel Assy	906 727 00 71	154.00	0.2
36	101500	BDY	REMOVE/INSTALL	R Frt Otr Door Handle			0.4
37	101501	BDY	REMOVE/INSTALL	L Frt Otr Door Handle			0.4
38	102202	GLS	REMOVE/REPLACE	R Frt Door Moveable Glass	906 725 03 10	214.00	1.4
39	102203	GLS	REMOVE/REPLACE	L Frt Door Moveable Glass	906 725 02 10	214.00	1.4
40	102206	BDY	REMOVE/INSTALL	R Frt Door Window Frame	Existing		0.3 #r
41	102207	BDY	REMOVE/INSTALL	L Frt Door Window Frame	Existing		0.3 #r
<u>Side Door</u>							
42	102220	BDY	REPAIR	R Side Door Shell	Existing		3.0*
43		REF	REFINISH	R Side Door Outside			C 2.8
44	102499	BDY	REMOVE/INSTALL	R Otr Door Handle			0.6 #
<u>Van Side Panel</u>							
45	102302	BDY	REMOVE/INSTALL	R Van Side Rear Panel	Existing		15.0 r
46		MCH	REMOVE/REPLACE	R Add To R&I/R&R Side Curtain Air Bags-M			0.7
47				Addt Labor is for repair			
48		REF	REFINISH/REPAIR	R Van Side Rear Panel			C 6.2*
49				MODIFIED REFINISH WITH FULL CLEAR COAT			
50		BDY	ADD'L LABOR OP	R Van Side Rear Panel			3.0*
51	102394	BDY	REMOVE/INSTALL	L Frt Van Side Panel	Existing		12.0 #r
52		MCH	REMOVE/REPLACE	L Add To R&I/R&R Side Curtain Air Bags-M			0.7
53	102403	BDY	REMOVE/INSTALL	L Van Side Rear Panel	Existing		15.0 r
54	101746	BDY	REMOVE/INSTALL	R Quarter Wheel Opening Mldg			INC
55	101748	BDY	REMOVE/INSTALL	R Van Side Panel Mudguard			INC
56	101750	BDY	REMOVE/INSTALL	R Frt Lwr Van Side Protect Moulding	Existing		0.2 r
57	101759	BDY	REMOVE/INSTALL	R Frt Van Side Adhesive Moulding	Existing		0.2 r
58	101767	BDY	REMOVE/INSTALL	R Rear Van Side Adhesive Moulding	Existing		0.2 r
<u>Roof</u>							
59	100599	BDY	REMOVE/INSTALL	Ctr Roof Panel	Existing		11.0 #r
60				To Reapply Bonding Adhesive.			
61	100611	BDY	REMOVE/INSTALL	Rear Roof Panel	Existing		8.0 #r
62	100633	BDY	REPAIR	Frnt Roof Panel	Existing		2.5* #
63		REF	REFINISH	Frnt Roof Panel Outside			C 2.5
64				Remove burns			
65	100565	BDY	REMOVE/REPLACE	Frnt Roof Headliner	ORDER FROM DEALER	272.00	3.0
<u>Back Door</u>							
66	100117	REF	REFINISH	R Add For Jambs & Interior			C 1.2
67	100118	REF	REFINISH	L Add For Jambs & Interior			C 1.2
68	101629	BDY	REPAIR	R Back Door Shell	Existing		2.0*

ESTIMATE RECALL NUMBER: 06/26/2013 17:47:59 C013101933

Mitchell Data Version: OEM: MAY_13_V

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Software Version: 7.0.485

Page 2 of 4

69		REF	REFINISH	R Back Door Outside				C	2.4
70	101630	BDY	REPAIR	L Back Door Shell	Existing				2.0*
71		REF	REFINISH	L Back Door Outside				C	2.2
72	101631	BDY	REMOVE/REPLACE	Back Door Adhesive Emblem	906 758 00 58		21.00		0.2
73	101632	BDY	REMOVE/REPLACE	Back Door Adhesive Nameplate	906 817 23 14		20.00		0.2
74	101634	BDY	REMOVE/REPLACE	Back Door Adhesive Nameplate	906 817 51 14		19.50		0.2
75	101638	BDY	REMOVE/INSTALL	L Back Door Garnish	Existing				0.2 r
<u>ADDITIONAL OPERATIONS</u>									
76		REF	ADD'L OPR	Clear Coat					5.0
<u>Additional Costs & Materials</u>									
77			ADD'L COST	Paint/Materials			1,443.20	*	
<u>MANUAL ENTRIES</u>									
78	900500	REF *	REFINISH/REPAIR	Replace E-Coat Type Finish to all Interior Panels	Existing				10.0*
79	900500	BDY *	REMOVE/REPLACE	Structural Adhesive and Caulk and Bonding Material	New		300.00	*	4.0*

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary			
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
Body	95.3	48.00	0.00	0.00	4,574.40	Taxable Parts			10,196.00
Refinish	45.1	48.00	0.00	0.00	2,164.80	Sales Tax	@	7.750%	790.19
Glass	6.0	48.00	0.00	0.00	288.00				
Mechanical	11.7	75.00	0.00	0.00	877.50	Total Replacement Parts Amount			10,986.19
Non-Taxable Labor					7,904.70				
Labor Summary	158.1				7,904.70				
III. Additional Costs					Amount	IV. Adjustments			
Taxable Costs					1,443.20	Insurance Deductible			
Sales Tax					@ 7.750% 111.85	Customer Responsibility			
Total Additional Costs					1,555.05				
Paint Material Method: Rates									
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I.	Total Labor:		7,904.70
						II.	Total Replacement Parts:		10,986.19
						III.	Total Additional Costs:		1,555.05
							Gross Total:		20,445.94
						IV.	Total Adjustments:		500.00-
							Net Total:		19,945.94

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

ESTIMATE RECALL NUMBER: 06/26/2013 17:47:59 C013101933

Mitchell Data Version: OEM: MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 4

Inspection Site: Arcaro's A/B
340 Del Sol
Palm Springs, CA
Inspection Date: 6/25/2013

COLLECT ALL FROM OWNER

***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***

***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

Pursuant to California Code of Regulations Section 2695.8(g)

The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

Property Damage Specialists
PO Box 2002, Indio, CA 92202
(760) 275-6795
Fax: (760) 863-5349

APPRAISAL REPORT

DAMAGE ASSESSED BY: Keagan Miles

FILE NUMBER: C013101933
CLAIM NUMBER: C013101933
DATE OF LOSS: 6/21/2013
TYPE OF LOSS:
APPRAISED FOR:

ASSIGNMENT DATE: None
CONTACT DATE: None
INSPECTION DATE: 6/25/2013
REC'D DATE: None

INSURED: Scott Allen Wasko
Box 888
Palm Springs, CA 92260

CLAIMANT: None

OWNER: Scott Allen Wasko
Box 888
Palm Springs, CA 92260

BODY SHOP: None

INSPECTION SITE: Arcaro's A/B
340 Del Sol
Palm Springs, CA

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: No
VEHICLE DRIVEABLE: No

Comments:

Inspected vehicle at Arcaros A/B 340 Del Sol, Palm Springs, CA. Vehicle is a complete burnout inside. Metal panels written to R+I to replace structural adhesives and caulks and all bodning materials. Structural integrity of the burned metal may be compromised and panels may require replace. SRS components replaced because of safety compromise by fire. Estimate written for all noted damaged items. PLEASE NOTE***** There are many open items that can not be determined on initial inspection. Including wiring harness etc. Called two MB dealers and they said that they could not provide a price on a harness for 14 days because it is made specifically for each vehicle and that delivery of the part can take 6-8 weeks. One dealer informed me that it is not their policy to provide part numbers. Contacted my supervisor and he informed me that harnesses can cost in the range of 1500-5000. He also contacted MB of Palm Springs and talked to the sales manager and came up with an approx value of 30k based on what similar vehicles have gone for at auction. It is my opinion that this vehicle would result in a TL b/c of the noted damages and all the open items. Conditioning valuation completed and rated as normal b/c of burned condition.

COMPARISON ESTIMATE: 0.00
APPRAISER ESTIMATE: 19,945.94
AGREED UPON AMOUNT: 0.00

TOWING: 0.00
STORAGE: 0.00
DEDUCTIBLE: 500.00

ACTUAL CASH VALUE: 0.00
SALVAGE VALUE: 0.00
SETTLEMENT: 0.00
REPAIR VS. ACV: 0.00

DRAFT/CHECK NUMBER: 0
DRAFT/CHECK AMOUNT: 0.00
DATE ISSUED: None

ESTIMATE FEE: 0.00
TRAVEL EXPENSE: 0.00
PHOTO EXPENSE: 0.00
MISC EXPENSE: 0.00
TOTAL CHARGES: 0.00

CCC Valuescope Basic Claim Information Form



CCC VALUESCOPE.

Report Retrieval Method	<input type="checkbox"/> Email	<input type="checkbox"/> Fax	<input type="checkbox"/> Other (Specify)
CCC Phone: 1-800-621-8070		CCC Fax: 1-800-621-7070	CCC Email: CCCValuescopeRequest@cccis.com
Office ID Number		Claim Number	
Adjr Name (First & Last)		Appr Name (First & Last)	
Adjr Contact#		Insured's Name	
Owner's Name Scott Allen Wasko		Owner's Phone 760-835-8005	
Loss ZIP Code 92260		Loss State CA	
Loss Type <input checked="" type="checkbox"/> Other <input type="checkbox"/> Theft		Coverage code <input type="checkbox"/> Collision <input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Liability <input type="checkbox"/> Other	
3rd Party Claim <input type="checkbox"/> Yes <input type="checkbox"/> No		Leased Vehicle <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date of Loss		Exch#Policy # 6/21/13	
Adjuster ID#		Claim Class	
PA Appr ID#			
VIN WD3PF4CC8C5624351			
Year 2012		Make MERCEDES	Model SPRINTER 3500 HIGH ROOF
Body Style <input type="checkbox"/> 2DR <input type="checkbox"/> 4DR <input type="checkbox"/> Hatchback <input type="checkbox"/> Convertible <input type="checkbox"/> Wagon <input type="checkbox"/> Pickup <input type="checkbox"/> Van <input checked="" type="checkbox"/> Utility <input type="checkbox"/> 1/2 Ton <input type="checkbox"/> 3/4 Ton <input checked="" type="checkbox"/> 1 Ton <input type="checkbox"/> Short Bed <input type="checkbox"/> Long Bed <input type="checkbox"/> Cab & Chassis <input type="checkbox"/> Fleetside <input type="checkbox"/> Fenderside			
Engine Size 3.0L Cylinders <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input checked="" type="checkbox"/> 6 <input type="checkbox"/> 8 <input type="checkbox"/> 10 <input type="checkbox"/> 12 <input type="checkbox"/> Turbo <input type="checkbox"/> Diesel			
Mileage ("UNK" if unknown) 23776 Transmission <input type="checkbox"/> Automatic <input type="checkbox"/> S6 <input checked="" type="checkbox"/> S5 <input type="checkbox"/> S4 <input type="checkbox"/> S3 <input type="checkbox"/> OD <input type="checkbox"/> 4W <input type="checkbox"/> PO			
Power Options <input checked="" type="checkbox"/> PS Power Steering <input checked="" type="checkbox"/> PB Power Brakes <input checked="" type="checkbox"/> PW Power Windows <input type="checkbox"/> PL Power Locks <input type="checkbox"/> SP Power Driver Seat <input type="checkbox"/> PC Power Passenger Seat <input type="checkbox"/> PA Power Antenna <input type="checkbox"/> PM Power Mirrors <input type="checkbox"/> PT Power Trunk/Tailgate <input type="checkbox"/> PP Power Adjustable Pedals <input type="checkbox"/> PD Power Sliding Door <input type="checkbox"/> DP Dual Power Sliding Doors Décor/Convenience <input checked="" type="checkbox"/> AC Air Conditioning <input type="checkbox"/> DA Dual Air Conditioning <input type="checkbox"/> CL Climate Control <input type="checkbox"/> RD Rear Defogger <input checked="" type="checkbox"/> IW Intermittent Wipers <input checked="" type="checkbox"/> TW Tilt Wheel <input type="checkbox"/> TL Telescopic Wheel <input type="checkbox"/> CC Cruise Control <input type="checkbox"/> KE Keyless Entry <input type="checkbox"/> CN Console/Storage <input type="checkbox"/> CO Overhead Console <input type="checkbox"/> EC Entertainment Center <input type="checkbox"/> NV Navigation System <input type="checkbox"/> C2 Communications System <input type="checkbox"/> HU Heads Up Display <input type="checkbox"/> WT Wood Interior Trim <input type="checkbox"/> EI Electronic Instrumentation <input type="checkbox"/> IB On Board Computer <input type="checkbox"/> MC Message Center <input type="checkbox"/> MM Memory Package <input type="checkbox"/> RJ Remote Start		Seating <input checked="" type="checkbox"/> CS Cloth Seats <input type="checkbox"/> LS Leather Seats <input type="checkbox"/> RL Reclining/ Lounge Seats <input checked="" type="checkbox"/> BS Bucket Seats <input type="checkbox"/> SH Heated Seats (2) <input type="checkbox"/> RH Rear Heated Seats <input type="checkbox"/> 3S Third Row Seat <input type="checkbox"/> 3P Power Third Seat <input type="checkbox"/> R3 Retractable Seats <input type="checkbox"/> 2P 12 Passenger Seating <input type="checkbox"/> 5P 15 Passenger Seating <input type="checkbox"/> B2 Captain Chairs (2) <input type="checkbox"/> B4 Captain Chairs (4) <input type="checkbox"/> B6 Captain Chairs (6) Radio <input checked="" type="checkbox"/> AM AM Radio <input checked="" type="checkbox"/> FM FM Radio <input checked="" type="checkbox"/> ST Stereo <input type="checkbox"/> CA Cassette <input type="checkbox"/> SE Search/Seek <input checked="" type="checkbox"/> CD Compact Disc Player <input type="checkbox"/> SK CD Changer/Stacker <input type="checkbox"/> UR Premium Radio <input type="checkbox"/> XM Satellite Radio <input type="checkbox"/> TQ Steering Wheel Touch Controls <input type="checkbox"/> M3 Auxiliary Audio Connection <input type="checkbox"/> EQ Equalizer <input type="checkbox"/> CB CB Radio <input type="checkbox"/> 8T 8 Track Tape Player Wheels <input checked="" type="checkbox"/> AW Aluminum/Alloy Wheels <input type="checkbox"/> CJ Chrome Wheels <input type="checkbox"/> W2 20" or Larger Wheels <input type="checkbox"/> DC Deluxe Wheel Covers <input type="checkbox"/> FC Full Wheel Covers <input type="checkbox"/> SA Spoke Aluminum Wheels <input type="checkbox"/> SY Styled Steel Wheels <input type="checkbox"/> WW Wire Wheels <input type="checkbox"/> WC Wire Wheel Covers <input type="checkbox"/> RW Rally Wheels <input type="checkbox"/> KW Locking Wheels <input type="checkbox"/> LC Locking Wheel Covers	
Roof <input type="checkbox"/> EG Electric Glass Roof <input type="checkbox"/> ES Electric Steel Roof <input type="checkbox"/> OR Skyview Roof <input type="checkbox"/> SD Dual Power Roofs <input type="checkbox"/> MS Manual Steel Roof <input type="checkbox"/> MG Manual Glass Roof <input type="checkbox"/> FR Flip Roof <input type="checkbox"/> TT T-Top/Panel <input type="checkbox"/> GT Glass T-Top/Panel <input type="checkbox"/> MV Manual Convertible Roof <input type="checkbox"/> VP Power Convertible Roof <input type="checkbox"/> RM Detachable Roof <input type="checkbox"/> VR Vinyl Roof <input type="checkbox"/> RF Cabriolet Roof <input type="checkbox"/> LR Landau Roof <input type="checkbox"/> LP Padded Landau Roof <input type="checkbox"/> PV Padded Vinyl Roof <input type="checkbox"/> CT Soft Top <input type="checkbox"/> HT Hard Top Safety/Brakes <input checked="" type="checkbox"/> AG Air Bag <input checked="" type="checkbox"/> RG Passenger Air Bag <input type="checkbox"/> XG Front Side Impact Air Bags <input type="checkbox"/> ZG Rear Side Impact Air Bags <input type="checkbox"/> DG Head/Roof Air Bags <input type="checkbox"/> TD Theft Deterrent/Alarm <input type="checkbox"/> VZ Night Vision <input type="checkbox"/> IC Intelligent Cruise <input type="checkbox"/> PJ Parking Sensors <input type="checkbox"/> PX Parking Sensors W/Equip <input type="checkbox"/> AB Anti-Lock Brakes (4) <input type="checkbox"/> A2 Anti-Lock Brakes (2) <input checked="" type="checkbox"/> DB 4-Wheel Disc Brakes <input type="checkbox"/> RB Rollover Protection <input type="checkbox"/> TX Traction Control <input type="checkbox"/> T1 Stability Control <input type="checkbox"/> AL Auto Level		Exterior/Paint/Glass <input type="checkbox"/> RR Luggage/Roof Rack <input type="checkbox"/> WG Woodgrain <input type="checkbox"/> WP Rear Window Wiper <input type="checkbox"/> 2T Two Tone Paint <input type="checkbox"/> D2 Deluxe 2 Tone Paint <input type="checkbox"/> HP Three Stage Paint <input type="checkbox"/> IP Clearcoat Paint <input type="checkbox"/> MP Metallic Paint <input type="checkbox"/> SL Rear Spoiler <input type="checkbox"/> FL Fog Lamps <input type="checkbox"/> TG Tinted Glass <input type="checkbox"/> DT Privacy Glass <input checked="" type="checkbox"/> BN Body Side Moldings <input checked="" type="checkbox"/> DM Dual Mirrors <input type="checkbox"/> HM Heated Mirrors <input type="checkbox"/> HV Headlamp Washers <input checked="" type="checkbox"/> MX Signal Integrated Mirrors Other <input type="checkbox"/> BD Running Board/Side Steps <input type="checkbox"/> UP Power Retractable Running Boards <input type="checkbox"/> XE Xenon Headlamps <input type="checkbox"/> AR Bed Rails <input type="checkbox"/> BL Bedliner <input type="checkbox"/> BY Bedliner (Spray On) <input type="checkbox"/> CP Fiberglass Cap <input type="checkbox"/> GG Grill Guard <input type="checkbox"/> SB Rear Step Bumper <input type="checkbox"/> SS Swivel Seats <input type="checkbox"/> SW Rear Sliding Window <input type="checkbox"/> PG Power Rear Window <input type="checkbox"/> TB Tool Box (Permanent) <input type="checkbox"/> TN Tonneau Cover – Soft <input type="checkbox"/> TZ Tonneau Cover – Hard <input checked="" type="checkbox"/> TP Trailing Package <input type="checkbox"/> WD Dual Rear Wheels <input type="checkbox"/> XT Auxiliary Fuel Tank <input type="checkbox"/> 3D 3rd Truck Door <input type="checkbox"/> 4D 4th Door Truck/Van <input type="checkbox"/> BC Bumper Cushions <input type="checkbox"/> BG Bumper Guards <input type="checkbox"/> EM California Emissions <input type="checkbox"/> SG Stone Guard <input type="checkbox"/> WI Winch	

CCC Valuescope Basic Claim Information Form (Continued)

Office ID Number	Claim Number
------------------	--------------

REFURBISHMENTS

Transmission	Purchase Price	Mileage	Engine	Purchase Price	Mileage
Tires	Purchase Price	# of Tires			
Paint	<input type="checkbox"/> Basic <input type="checkbox"/> Standard <input type="checkbox"/> Custom	Date Painted	Purchase Price		
Interior	Purchase Price	Date	<input type="checkbox"/> Leather <input type="checkbox"/> Vinyl <input type="checkbox"/> Cloth		
Camper Shell	Purchase Price	Date	Carpet Kit	Purchase Price	Date
Special Wheels	Purchase Price	Date			
Other	Description			Purchase Price	Date
<input type="checkbox"/> Restored	Restored Amount				

Package/Special Features/Additional Options (XXXX=CALL BACK)

CONDITION RATING:	Rate each of the following 0=Major Wear, 1=Normal Wear, 2=Dealer Ready, 3=Exceptional				COMMENTS
Seats	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Lightly soiled or stained.			
Carpet	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Lightly soiled or stained.			
Dashboard	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Small/few cracks or scratches.			
Headliner	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Small/few tears or light fading.			
Body	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Small/few dents or dings.			
Glass	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Minimal surface scratches and pitting			
Paint	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Small/few surface chips or scratches.			
Engine	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	No seepage evident.			
Transmission	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	Fluid may be slightly discolored.			
Front Tires	<input type="checkbox"/> 0 <input checked="" type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	5-7/32" of tread present.			
Rear Tires	<input checked="" type="checkbox"/> 0 <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3	40% or less of new			

ADJUSTMENTS

Pre Tax Adjustment 1		Add	Deduct
Pre Tax Adjustment 2		Add	Deduct
Sales Tax %	Leave blank if using AutoTax	Deductible	
Post Tax Adjustment 1		Add	Deduct
Post Tax Adjustment 2		Add	Deduct















