

Claim Summary been saved successfully...



Property Damage Specialist

P.O. Box 2002, Indio

California, United States

92202

Claim Information

Claim Number : CO13010618

Policy Number :

Insurance Company : Robert Moreno Insurance

Adjuster : Lorena Bautista

Date of Loss : -0001-11-30

Whose Claim : Insured

Owner Name : MARIA SOCORRO RODIGUEZ

Insured Name : MARIA SOCORRO RODIGUEZ

Claimant Name :

Inspection Location : RESIDENCE

Appraisal Information

File Number : 06252013-1000016

Appraiser : Jaime Munoz

Reinspector : Not Assigned

Loss Type : Collision

Inspection Date : 1906-07-05

Assigned Date/Time : 1906-06-29 13:47:00

Assignment Type : Full Appraisal

ERT (Days) : 2

Possible Supplement : YES

Vehicle Information

Year : 2007

Make : Ford

Model : Focus

Sub-model : SE
VIN : 1FAFP34N27W353690
Plate : 6PVZ138
State : California
Milage : 75289
Drivable : Yes
Primary POI : REAR
Secondary POI : REAR
Vehicle Condition : Fair
Interior Condition : Fair
Paint Condition : Fair
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 653.28
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 653.28
Deductible : 500.00
Original Net Loss : 153.28
Gross Total : 653.28
Supplement Net Loss : 0.00

Tire Information

Make :
Size :

Tired Depth (in 32nds)

L/F R/F

L/R R/R

Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

Completed the inspection of the owner's vehicle at residence on 7/05/13 .The owner was present during inspection. The owner pointed out related damages to rear end of the vehicle, as photos show. Estimate calculated noting remanufactured parts as cost effective saving over OEM as per Insurance guidelines. The vehicle is drivable. No copy of estimate to owner .Advised owner the estimate will be send to insurance company and the claim adjuster insurance company will be in contact with owner. Height of impact was 20 inches . Approx. 2 days for repairs. There is the possibility of a supplement to follow after tear down.

Date: 7/7/2013 06:34 AM
Estimate ID: CO13010618
Estimate Version: 0
Preliminary
Profile ID: * Robert Moreno Ins.

FOR SUPPLEMENT CALL RICH PEREA 760-275-6795 OR E MAIL
pds9593@verizon.net

PROPERTY DAMAGE SPECIALIST

P.O. BOX 2002, INDIO, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Damage Assessed By: Jaime Munoz

Appraised For: LORENA BAUTISTA
(714) 738-1383 ext. 2387

Condition Code: Fair
Date of Loss: 6/1/2013
Contact Date: 6/1/2013
Payer: Insurance
File Number: CO13010618
Claim Number: CO13010618

Type of Loss: Collision
Arrival Date: 7/5/2013
Accident Date: 6/1/2013
Deductible: 500.00

Insured: MARIA SOCORRO RODRIGUEZ
Owner: MARIA SOCORRO RODRIGUEZ
Address: 9644 SCHOOLING RD., PICO RIVERA, CA 90660
Telephone:
Cell Phone: (562) 479-2217

Mitchell Service: 910626

Description: 2007 Ford Focus ZX4 SE
Body Style: 4D Sed
VIN: 1FAFP34N27W353690
Mileage: 75,289
OEM/ALT: A
Color: GRAY
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, POWER ADJUSTABLE EXTERIOR MIRROR
FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM, AM/FM STEREO CD/MP3 PLAYER
FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM, POWER LIFTGATE\TRUNK

Vehicle Production Date: 7/07
Drive Train: 2.0L Inj 4 Cyl 4A FWD
License: 6PVZ138 CA
Search Code: 975

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	001480	BDY	OVERHAUL	Rear Bumper Assy			1.7
2	008810	BDY	REMOVE/REPLACE	Rear Bumper Cover Assy	Remanufactured	234.98	INC
3	AUTO	REF	REFINISH	Rear Bumper Cover			C 2.2
4	008711	BDY	REMOVE/REPLACE	Rear Bumper Impact Absorber	YS4Z 17787 AA	89.01	INC
5	936012		ADD'L COST	Hazardous Waste Disposal		3.00	*
6	936014		ADD'L COST	Flex Additive		3.00	*
7	AUTO	REF	ADD'L OPR	Clear Coat			0.9
8	933003	BDY *	ADD'L OPR	Tint Color			0.5*
9	AUTO		ADD'L COST	Paint/Materials		99.20	*

* - Judgment Item

** QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

ESTIMATE RECALL NUMBER: 07/07/2013 06:34:33 CO13010618

Mitchell Data Version: JUN_13_V
MAPP:JUN_13_V
Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

COLLECT ALL FROM OWNER

***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***

***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER.
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

AUTO 12/28/2012 TO 12/28/2013 11 6PVZ138

VEHICLE IDENTIFICATION NUMBER
1FAFP34N27W353690

BODY TYPE MODEL
4D

DATE ISSUED
01/19/2013

CYLS.		DATE FIRST SOLD		CLASS	MAKE	YR	Yr Model
00/00/0000		CD		2010	2007		
TYPE VEHL	MP	AX	WC	UNLADEN/G/GW	TOTAL FEES PAID		
170	G			\$187	1900		

RODRIGUEZ LEISETTE G
OR RODRIGUEZ MARIA S
9644 SCHOOLING RD
PICO RIVERA CA 90660-3950

REGISTERED
OWNER

FORD MOTOR CRDT CO LLC
260 INTERSTATE N PKWY NW
ATLANTA

R0069
L0048

GA

30339
RI3011620134004

STATE OF CALIFORNIA
DEPARTMENT OF MOTOR VEHICLES

6340976

TEMPORARY IDENTIFICATION
(before delivery to the purchaser)

406922

VEHICLE IDENTIFICATION NUMBER
1FAFP34N27W353690

SALESPERSON'S NUMBER
5765154

562-405-3500 • 800-39

















