

**View Claim Summary - File Number: 06272013-1000010**[GO BACK](#)**Claim Summary been saved successfully...****Property Damage Specialist**P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010730
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Steve Dernoncourt
Date of Loss : 2013-06-23
Whose Claim : Insured
Owner Name : ORACIO SALAS
Insured Name : ORACIO SALAS
Claimant Name :
Inspection Location : RESIDENCE

Appraisal Information

File Number : 06272013-1000010
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-06
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2012
Make : Toyota
Model : Corolla
Sub-model : LE
VIN : 2T1BU4EE6CC804256
Plate : 6RIA615

State : California
Milage : UNK
Drivable : Unknown
Primary POI : FRT AND REAR
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation :	Total Loss
Estimate 1 Total :	18163.88
Estimate 2 Total :	0.00
Estimate 1 Betterment :	0.00
Estimate 2 Betterment :	0.00
Supplement 1 Total :	0.00
Supplement 1 Betterment :	0.00
Supplement 2 Total :	0.00
Supplement 2 Betterment :	0.00
Supplement 3 Total :	0.00
Supplement 3 Betterment :	0.00
Supplement 4 Total :	0.00
Supplement 4 Betterment :	0.00
Subtotal :	18163.88
Deductible :	0.00
Original Net Loss :	18163.88
Gross Total :	18163.88
Supplement Net Loss :	0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT RESIDENCE IN HEMET ON 7/6/13. INSURED WAS NOT PRESENT. DAMAGE OBSERVED TO LEFT SIDE OF VEHICLE AND DEPLOYED AIRBAGS AS COLLISION DAMAGE. ESTIMATE WRITTEN AT AREAS PREVAILING RATES USING AVAILABLE OEM PARTS OVER. LKQ PARTS. ESTIMATE EXCEEDS THRESHOLD WITH VARIOUS ITEMS OPEN. VEHICLE IS A CONSTRUCTIVE TOTAL LOSS. DOORS WERE JAMMED COULD BE OPNE TO OBTAIN VIN PLATE. INSURED DID NOT KNOW LAST MILEAGE. PLEASE CALL IF YOU HAVE ANY QUESTIONS
TONY NGUYEN 714-757-0906.



Used Vehicle Valuation Report

Report Date: 07/09/2013

Effective Dates: 07/04/2013 - 07/11/2013

2012 Toyota Corolla LE Sedan 4D

VIN: 2T1BU4EE6CC804256

Reference:

Base Values				
	Excellent	Very Good	Good	Fair
MSRP	\$18,670	--	--	--
Certified Pre-Owned	\$15,400	--	--	--
Suggested Retail	\$15,400	--	--	--
Private Party	\$13,950	\$13,450	\$13,050	\$11,700
Lending Value	\$13,800	--	--	--
Auction	\$13,350	\$13,100	\$12,500	\$11,050
Trade-In	\$12,400	\$12,100	\$11,550	\$10,050
Value as of: 07/09/2013 Engine: 4-Cyl, 1.8 Liter Included Zip Code: 92544 Transmission: Automatic, 4-Spd Included Condition: Good Drivetrain: FWD Included Mileage: 23,500 Included				
Itemized Equipment (Lending Value / Suggested Retail)				
Traction Control	Included	Tilt & Telescoping Wheel	Included	
Stability Control	Included	AM/FM Stereo	Included	
ABS (4-Wheel)	Included	MP3 (Single Disc)	Included	
Keyless Entry	Included	Bluetooth Wireless	Included	
Air Conditioning	Included	Dual Air Bags	Included	
Power Windows	Included	Side Air Bags	Included	
Power Door Locks	Included	F&R Head Curtain Air Bags	Included	
Cruise Control	Included	Daytime Running Lights	Included	
Power Steering	Included	Steel Wheels	Included	
Total Itemized Equipment:				\$0/\$0

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92544. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)



Used Vehicle Valuation Report

Report Date: 07/09/2013

Effective Dates: 07/04/2013 - 07/11/2013

2012 Toyota Corolla LE Sedan 4D

VIN: 2T1BU4EE6CC804256

Reference:

Total Values including Mileage and Option adjustments				
	Excellent	Very Good	Good	Fair
MSRP	\$18,670	--	--	--
Certified Pre-Owned	\$16,350	--	--	--
Suggested Retail	\$15,400	--	--	--
Private Party	\$13,950	\$13,450	\$13,050	\$11,700
Lending Value	\$13,800	--	--	--
Auction	\$13,350	\$13,100	\$12,500	\$11,050
Trade-In	\$12,400	\$12,100	\$11,550	\$10,050

-- Assumes excellent condition.

Notes: MILEAGE UNK.

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92544. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)

CCC valuescope Basic Claim Information Form



CCC VALUESCOPE.

Report Retrieval Method	<input type="checkbox"/> Email	<input type="checkbox"/> Fax	<input type="checkbox"/> Other (Specify)
CCC Phone: 1-800-621-8070		CCC Fax: 1-800-621-7070	CCC Email: CCCValuescopeRequest@cccis.com
Office ID Number		Claim Number CO13010730	
Adjr Name (First & Last) STEVE DERNORNCOURT		Appr Name (First & Last) TONY NGUYEN	
Adjr Contact# 714-738-1383		Insured's Name ORACIO SALAS	
Owner's Name SAME		Owner's Phone 951-732-0610	
Loss ZIP Code 92544		Loss State CA	
Loss Type <input checked="" type="checkbox"/> Collision <input type="checkbox"/> Theft		Coverage code <input type="checkbox"/> Collision <input type="checkbox"/> Comprehensive <input type="checkbox"/> Liability <input type="checkbox"/> Other	
3rd Party Claim <input type="checkbox"/> Yes <input type="checkbox"/> No		Leased Vehicle <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date of Loss 6-23-13		Exch#Policy #	
Adjuster ID#		Claim Class	
PA Appr ID#			
VIN 2T1BU4EE6CC804256			
Year 2012	Make TOYOTA	Model COROLLA	
Body Style	<input type="checkbox"/> 2DR <input checked="" type="checkbox"/> 4DR	<input type="checkbox"/> Hatchback	<input type="checkbox"/> Convertible
<input type="checkbox"/> 1/2 Ton	<input type="checkbox"/> 3/4 Ton	<input type="checkbox"/> 1 Ton	<input type="checkbox"/> Short Bed
<input type="checkbox"/> Long Bed	<input type="checkbox"/> Cab & Chassis	<input type="checkbox"/> Fleetside	<input type="checkbox"/> Fenderside
Engine Size 1.8L	Cylinders	<input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 8 <input type="checkbox"/> 10 <input type="checkbox"/> 12	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel
Mileage ("UNK" if unknown) UNK			
Transmission	<input checked="" type="checkbox"/> Automatic	<input type="checkbox"/> S6 <input type="checkbox"/> S5 <input type="checkbox"/> S4 <input type="checkbox"/> S3 <input type="checkbox"/> OD	<input type="checkbox"/> 4W <input type="checkbox"/> PO
Power Options	Seating	Roof	Exterior/Paint/Glass
<input checked="" type="checkbox"/> PS Power Steering	<input checked="" type="checkbox"/> CS Cloth Seats	<input type="checkbox"/> EG Electric Glass Roof	<input type="checkbox"/> RR Luggage/Roof Rack
<input checked="" type="checkbox"/> PB Power Brakes	<input type="checkbox"/> LS Leather Seats	<input type="checkbox"/> ES Electric Steel Roof	<input type="checkbox"/> WG Woodgrain
<input checked="" type="checkbox"/> PW Power Windows	<input checked="" type="checkbox"/> RL Reclining/ Lounge Seats	<input type="checkbox"/> OR Skyview Roof	<input type="checkbox"/> WP Rear Window Wiper
<input checked="" type="checkbox"/> PL Power Locks	<input checked="" type="checkbox"/> BS Bucket Seats	<input type="checkbox"/> SD Dual Power Roofs	<input type="checkbox"/> 2T Two Tone Paint
<input type="checkbox"/> SP Power Driver Seat	<input type="checkbox"/> SH Heated Seats (2)	<input type="checkbox"/> MS Manual Steel Roof	<input type="checkbox"/> D2 Deluxe 2 Tone Paint
<input type="checkbox"/> PC Power Passenger Seat	<input type="checkbox"/> RH Rear Heated Seats	<input type="checkbox"/> MG Manual Glass Roof	<input type="checkbox"/> HP Three Stage Paint
<input type="checkbox"/> PA Power Antenna	<input type="checkbox"/> 3S Third Row Seat	<input type="checkbox"/> FR Flip Roof	<input checked="" type="checkbox"/> IP Clearcoat Paint
<input checked="" type="checkbox"/> PM Power Mirrors	<input type="checkbox"/> 3P Power Third Seat	<input type="checkbox"/> TT T-Top/Panel	<input type="checkbox"/> MP Metallic Paint
<input checked="" type="checkbox"/> PT Power Trunk/Tailgate	<input type="checkbox"/> R3 Retractable Seats	<input type="checkbox"/> GT Glass T-Top/Panel	<input type="checkbox"/> SL Rear Spoiler
<input type="checkbox"/> PP Power Adjustable Petals	<input type="checkbox"/> 2P 12 Passenger Seating	<input type="checkbox"/> MV Manual Convertible Roof	<input type="checkbox"/> FL Fog Lamps
<input type="checkbox"/> PD Power Sliding Door	<input type="checkbox"/> 5P 15 Passenger Seating	<input type="checkbox"/> VP Power Convertible Roof	<input checked="" type="checkbox"/> TG Tinted Glass
<input type="checkbox"/> DP Dual Power Sliding Doors	<input type="checkbox"/> B2 Captain Chairs (2)	<input type="checkbox"/> RM Detachable Roof	<input type="checkbox"/> DT Privacy Glass
Décor/Convenience	<input type="checkbox"/> B4 Captain Chairs (4)	<input type="checkbox"/> VR Vinyl Roof	<input type="checkbox"/> BN Body Side Moldings
<input checked="" type="checkbox"/> AC Air Conditioning	<input type="checkbox"/> B6 Captain Chairs (6)	<input type="checkbox"/> RF Cabriolet Roof	<input checked="" type="checkbox"/> DM Dual Mirrors
<input type="checkbox"/> DA Dual Air Conditioning	Radio	<input type="checkbox"/> LR Landau Roof	<input type="checkbox"/> HM Heated Mirrors
<input type="checkbox"/> CL Climate Control	<input checked="" type="checkbox"/> AM AM Radio	<input type="checkbox"/> LP Padded Landau Roof	<input type="checkbox"/> HV Headlamp Washers
<input checked="" type="checkbox"/> RD Rear Defogger	<input checked="" type="checkbox"/> FM FM Radio	<input type="checkbox"/> PV Padded Vinyl Roof	<input type="checkbox"/> MX Signal Integrated Mirrors
<input checked="" type="checkbox"/> IW Intermittent Wipers	<input checked="" type="checkbox"/> ST Stereo	<input type="checkbox"/> CT Soft Top	Other
<input checked="" type="checkbox"/> TW Tilt Wheel	<input type="checkbox"/> CA Cassette	<input type="checkbox"/> HT Hard Top	<input type="checkbox"/> BD Running Board/Side Steps
<input checked="" type="checkbox"/> TL Telescopic Wheel	<input type="checkbox"/> SE Search/Seek	Safety/Brakes	<input type="checkbox"/> UP Power Retractable Running Boards
<input checked="" type="checkbox"/> CC Cruise Control	<input checked="" type="checkbox"/> CD Compact Disc Player	<input checked="" type="checkbox"/> AG Air Bag	<input type="checkbox"/> XE Xenon Headlamps
<input checked="" type="checkbox"/> KE Keyless Entry	<input type="checkbox"/> SK CD Changer/Stacker	<input checked="" type="checkbox"/> RG Passenger Air Bag	<input type="checkbox"/> AR Bed Rails
<input checked="" type="checkbox"/> CN Console/Storage	<input type="checkbox"/> UR Premium Radio	<input checked="" type="checkbox"/> XG Front Side Impact Air Bags	<input type="checkbox"/> BL Bedliner
<input type="checkbox"/> CO Overhead Console	<input type="checkbox"/> XM Satellite Radio	<input type="checkbox"/> ZG Rear Side Impact Air Bags	<input type="checkbox"/> BY Bedliner (Spray On)
<input type="checkbox"/> EC Entertainment Center	<input type="checkbox"/> TQ Steering Wheel Touch Controls	<input checked="" type="checkbox"/> DG Head/Roof Air Bags	<input type="checkbox"/> CP Fiberglass Cap
<input type="checkbox"/> NV Navigation System	<input type="checkbox"/> M3 Auxiliary Audio Connection	<input checked="" type="checkbox"/> TD Theft Deterrent/Alarm	<input type="checkbox"/> GG Grill Guard
<input type="checkbox"/> C2 Communications System	<input type="checkbox"/> EQ Equalizer	<input type="checkbox"/> VZ Night Vision	<input type="checkbox"/> SB Rear Step Bumper
<input type="checkbox"/> HU Heads Up Display	<input type="checkbox"/> CB CB Radio	<input type="checkbox"/> IC Intelligent Cruise	<input type="checkbox"/> SS Swivel Seats
<input type="checkbox"/> WT Wood Interior Trim	<input type="checkbox"/> 8T 8 Track Tape Player	<input type="checkbox"/> PJ Parking Sensors	<input type="checkbox"/> SW Rear Sliding Window
<input type="checkbox"/> EI Electronic Instrumentation	Wheels	<input type="checkbox"/> PX Parking Sensors W/Equip	<input type="checkbox"/> PG Power Rear Window
<input type="checkbox"/> IB On Board Computer	<input type="checkbox"/> AW Aluminum/Alloy Wheels	<input checked="" type="checkbox"/> AB Anti-Lock Brakes (4)	<input type="checkbox"/> TB Tool Box (Permanent)
<input type="checkbox"/> MC Message Center	<input type="checkbox"/> CJ Chrome Wheels	<input type="checkbox"/> A2 Anti-Lock Brakes (2)	<input type="checkbox"/> TN Tonneau Cover – Soft
<input type="checkbox"/> MM Memory Package	<input type="checkbox"/> W2 20" or Larger Wheels	<input type="checkbox"/> DB 4-Wheel Disc Brakes	<input type="checkbox"/> TZ Tonneau Cover – Hard
<input type="checkbox"/> RJ Remote Start	<input type="checkbox"/> DC Deluxe Wheel Covers	<input type="checkbox"/> RB Rollover Protection	<input type="checkbox"/> TP Trailing Package
	<input checked="" type="checkbox"/> FC Full Wheel Covers	<input checked="" type="checkbox"/> TX Traction Control	<input type="checkbox"/> WD Dual Rear Wheels
	<input type="checkbox"/> SA Spoke Aluminum Wheels	<input checked="" type="checkbox"/> T1 Stability Control	<input type="checkbox"/> XT Auxiliary Fuel Tank
	<input type="checkbox"/> SY Styled Steel Wheels	<input type="checkbox"/> AL Auto Level	<input type="checkbox"/> 3D 3rd Truck Door
	<input type="checkbox"/> WW Wire Wheels		<input type="checkbox"/> 4D 4th Door Truck/Van
	<input type="checkbox"/> WC Wire Wheel Covers		<input type="checkbox"/> BC Bumper Cushions
	<input type="checkbox"/> RW Rally Wheels		<input type="checkbox"/> BG Bumper Guards
	<input type="checkbox"/> KW Locking Wheels		<input type="checkbox"/> EM California Emissions
	<input type="checkbox"/> LC Locking Wheel Covers		<input type="checkbox"/> SG Stone Guard
			<input type="checkbox"/> WI Winch

CCC Valuescope Basic Claim Information Form (Continued)

Office ID Number				Claim Number			
REFURBISHMENTS							
Transmission	Purchase Price		Mileage		Engine	Purchase Price	
Tires	Purchase Price		# of Tires				
Paint	<input type="checkbox"/> Basic	<input type="checkbox"/> Standard	<input type="checkbox"/> Custom	Date Painted	Purchase Price		
Interior	Purchase Price		Date		<input type="checkbox"/> Leather	<input type="checkbox"/> Vinyl	<input type="checkbox"/> Cloth
Camper Shell	Purchase Price		Date		Carpet Kit	Purchase Price	Date
Special Wheels	Purchase Price		Date				
Other	Description				Purchase Price	Date	
<input type="checkbox"/> Restored	Restored Amount						
Package/Special Features/Additional Options (XXXX=CALL BACK)							
CONDITION RATING: Rate each of the following 0=Below Average, 1=Normal, 2=Above Average, 3=Exceptional					COMMENTS		
Seats	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No significant fading. No tears, holes or burn marks		
Carpet	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No tears, holes or burn marks		
Dashboard	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No damage. Components intact.		
Headliner	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Small/few tears or light fading. Minimal staining or soiling		
Body	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Sheetmetal: No dents. No significant dings. No rust evident. Trim: No damage to components. No significant peeling or fading. No rust apparent		
Glass	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No scratches, pitting or chips. Seals are intact and watertight.		
Paint	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No surface chips. No significant scratches or fading.		
Engine	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Very clean. No seepage evident. No dirt or grease covered areas. Oil translucent.		
Transmission	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Fluid has red translucent color. No seepage evident.		
Front Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	8-10/32" of original tread. 69% to 90% of new. Normal wear patterns evident.		
Rear Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	8-10/32" of original tread. 69% to 90% of new. Normal wear patterns evident.		
ADJUSTMENTS							
Pre Tax Adjustment 1					Add	Deduct	
Pre Tax Adjustment 2					Add	Deduct	
Sales Tax %	Leave blank if using AutoTax				Deductible		
Post Tax Adjustment 1					Add	Deduct	
Post Tax Adjustment 2					Add	Deduct	

Date: 7/9/2013 07:19 AM
Estimate ID: CO13010730
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: STEVE DERNONCOURT / SD
(714) 738-1383 ext. 2334

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/23/2013
Deductible: 0.00
File Number: CO13010730
Claim Number: CO13010730

Type of Loss: Collision

Insured: ORACIO SALAS
Owner: ORACIO SALAS
Address: 284 MONTE VISTA WAY, HEMET, CA 92544
Telephone: Home Phone: (951) 732-0610

Mitchell Service: 911092

Description: 2012 Toyota Corolla LE
Body Style: 4D Sed
VIN: 2T1BU4EE6CC804256
OEM/ALT: A
Color: WHITE
Options:

Drive Train: 1.8L Inj 4 Cyl 4A FWD
License: 6RIA615 CA
Search Code: None

PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
TELESCOPIC STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL
AUXILIARY INPUT, IPOD ADAPTER, AUTOMATIC TRANSMISSION, FRONT AIR DAM
TINTED GLASS, TRIP COMPUTER, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, INTERIOR AIR FILTER
KEYLESS ENTRY SYSTEM, POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE/TRUNK
STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	103594	BDY	REMOVE/REPLACE	Frt Bumper Grille	53112-02280	65.14	0.3
2	103618	BDY	REMOVE/REPLACE	L Front Combination Lamp Assembly	81150-02B50	224.15	INC #
3	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
4	100750	BDY	REMOVE/REPLACE	L Fender Panel	53802-02110	174.33	2.4 #
5	AUTO	REF	REFINISH	L Fender Outside			C 2.0
6	AUTO	REF	REFINISH	L Add To Edge Fender			C 0.5
7	103820	BDY	REMOVE/REPLACE	L Fender Liner	53876-02370	91.71	INC
8	103850	MCH	REMOVE/REPLACE	Air Bag Module-Driver Front -M	45130-02400-B0	728.97	INC

ESTIMATE RECALL NUMBER: 07/09/2013 07:19:08 CO13010730

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 4

Date: 7/9/2013 07:19 AM
 Estimate ID: CO13010730
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

9	103852	MCH	REMOVE/REPLACE	Air Bag Spiral Cable	-M	84306-04080	192.78	1.1
10	101844	MCH	REMOVE/REPLACE	Air Bag Module-Passenger Front	-M	73960-02120	773.31	0.9 #
11	103997	MCH	REMOVE/REPLACE	Air Bag Module-Driver's Seat	-M	73920-02170	410.38	0.3 #
12	104000	MCH	REMOVE/REPLACE	L Frt Air Bag Side Impact Sensor	-M	89831-02110	147.17	0.3 #
13	104002	MCH	REMOVE/REPLACE	L Rear Air Bag Side Impact Sensor	-M	89831-02120	214.77	0.3 #
14	AUTO	BDY	REMOVE/INSTALL	Rear Seat Assy				INC
15	101939	MCH	REMOVE/REPLACE	R Air Bag Side Curtain Module	-M	62170-02101	810.05	0.7 #
16	AUTO	BDY	REMOVE/INSTALL	Roof Headliner				INC
17	101940	MCH	REMOVE/REPLACE	L Air Bag Side Curtain Module	-M	62180-02102	810.05	INC #
18	101623	BDY	REMOVE/INSTALL	Spare Tire/Wheel				0.2
19	101624	BDY	REMOVE/REPLACE	Wheel 2@138.62		42611-02880	277.24	0.6
20				LFT FRT & REAR				
21	104148	BDY	REMOVE/REPLACE	Wheel Cover 2@77.92		42621-02140	155.84	
22	931117	BDY	REMOVE/REPLACE	Left Front Tire		New	105.00	*
23	931119	BDY	REMOVE/REPLACE	Left Rear Tire		New	105.00	*
24	931125	BDY	ADD'L LABOR OP	Mount & Balance Tire		Sublet	24.00	* 0.0*
25	100424	MCH	REMOVE/INSTALL	Upr Instrument Panel Assy	-M			3.5
26	AUTO	REF	REFINISH	L Door Opening Panel Complete				C 3.7
27	101535	BDY	REMOVE/REPLACE	L Cowl/Dash Hinge Pillar	-S	61132-02220	203.51	10.3
28	101540	BDY	REMOVE/REPLACE	L Cowl/Dash Hinge Pillar Reinf (HSS)	-S	61109-02140	243.02	2.0
29	101375	BDY	REMOVE/REPLACE	L Rocker w/Center Pillar	-S	61312-02150	204.52	12.0 #
30	101380	BDY	REMOVE/REPLACE	L Ctr Pillar Reinforcement (HSS)	-S	61038-02913	415.07	7.5 #
31	101381	BDY	REMOVE/REPLACE	L Rocker Reinf (HSS)	-S	61404-02110	325.68	3.5
32	103541	BDY	REMOVE/REPLACE	L Frt Seat Belt		73220-02290-B1	244.34	0.2 #
33	102563	BDY	REMOVE/REPLACE	L Frt Door Shell		67002-02330	565.62	5.2 #
34	AUTO	REF	REFINISH	L Frt Door Outside				C 1.8
35	AUTO	REF	REFINISH	L Frt Add For Jambs & Interior				C 1.0
36	102979	BDY	REMOVE/REPLACE	L Rear Door Shell		67004-02220	497.33	5.2
37	AUTO	REF	REFINISH	L Rear Door Outside				C 1.8
38	AUTO	REF	REFINISH	L Rear Add For Jambs & Interior				C 1.0
39	101021	BDY	REMOVE/REPLACE	Roof Headliner		63310-02A00-B0	977.42	4.0
40	101062	GLS	REMOVE/INSTALL	Back Window				0.4 #
41	102038	BDY	REMOVE/REPLACE	L Quarter Outer Panel		61602-02170	749.36	18.0 #
42	AUTO	MCH	REMOVE/REPLACE	L Add To R&L/R&R Side Curtain Air Bags-M				0.7 #
43	AUTO	MCH	REMOVE/REPLACE	L Rear Add To R&L/R&R Side Air Bag Senso				0.3
44	AUTO	REF	REFINISH	L Quarter Panel Outside				C 1.8
45	AUTO	REF	REFINISH	L Quarter Panel Edge				C 0.5
46	AUTO	REF	REFINISH	L Add For Pillar				C 0.5
47	104220	MCH	REMOVE/REPLACE	L Rear Susp Shock Absorber	-M	48530-02B30	77.36	1.6 #
48	100882	MCH	REMOVE/REPLACE	Rear Susp Axle Beam	-M	42101-02200	1,385.79	3.4 #
49	100591	BDY	REMOVE/INSTALL	L Rear Combination Lamp				INC #
50	103785	BDY	REMOVE/INSTALL	Rear Bumper Cover				INC
51	933006	FRM	ADD'L OPR	Frame/Rack Set Up				2.0*
52	933035	FRM	ADD'L OPR	Unibody Pull				4.0*
53	933021	BDY *	ADD'L OPR	De-Nib And Finesse				2.5*
54	933002	REF	ADD'L OPR	Clear Coat				2.5*
55	933003	BDY *	ADD'L OPR	Tint Color				0.5*
56	933018	BDY *	ADD'L OPR	Mask For Overspray			5.00	* 0.2*
57	AUTO		ADD'L COST	Paint/Materials			547.20	*

ESTIMATE RECALL NUMBER: 07/09/2013 07:19:08 CO13010730

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 2 of 4

Software Version: 7.0.486

All Rights Reserved

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary			
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
Body	75.0	45.00	5.00	24.00	3,404.00	Taxable Parts			11,174.91
Refinish	17.1	45.00	0.00	0.00	769.50	Sales Tax	@	8.000%	893.99
Glass	0.4	45.00	0.00	0.00	18.00				
Frame	6.0	55.00	0.00	0.00	330.00	Total Replacement Parts Amount			12,068.90
Mechanical	13.1	75.00	0.00	0.00	982.50				
Non-Taxable Labor					5,504.00				
Labor Summary	111.6				5,504.00				
III. Additional Costs						IV. Adjustments			
					Amount				Amount
Taxable Costs					547.20	Insurance Deductible			0.00
Sales Tax		@	8.000%		43.78	Customer Responsibility			0.00
Total Additional Costs					590.98				
Paint Material Method: Rates									
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I. Total Labor:			5,504.00
						II. Total Replacement Parts:			12,068.90
						III. Total Additional Costs:			590.98
						Gross Total:			18,163.88
						IV. Total Adjustments:			0.00
						Net Total:			18,163.88
									TOTAL LOSS

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

15 Total Loss (P), 8 Left Rear Side (S), 9 Left Side (S), 10 Left Front Side (S)

ESTIMATE RECALL NUMBER: 07/09/2013 07:19:08 CO13010730

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version:

7.0.486

Copyright (C) 1994 - 2013 Mitchell International

All Rights Reserved

Page 3 of 4

Date: 7/9/2013 07:19 AM
Estimate ID: CO13010730
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 284 MONTE VISTA WAY
HEMET, CA 92544
Inspection Date: 7/9/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/09/2013 07:19:08 CO13010730

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 4 of 4











