

**View Claim Summary - File Number: 06272013-1000034****Claim Summary been saved successfully...****Property Damage Specialist**P.O. Box 2002, Indio
California, United States
92202[GO BACK](#)

Claim Information

Claim Number : co13005281
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Shannon Pontrelli
Date of Loss : 2013-02-25
Whose Claim : Insured
Owner Name : javier gonzalez
Insured Name : javier gonzalez
Claimant Name :
Inspection Location :

Appraisal Information

File Number : 06272013-1000034
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-02
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement : NONE

Vehicle Information

Year : 2001
Make : Ford
Model : Explorer
Sub-model : SPORT TRAC
VIN : 1FMZU77E61UB94934
Plate :

State : California
Milage : 146246
Drivable : Yes
Primary POI : FRT
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 0.00
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 0.00
Deductible : 0.00
Original Net Loss : 0.00
Gross Total : 0
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT RESIDENCE IN ON TEMECULA ON 7/2/13. INSURED WAS PRESENT & POINTED OUT FRONT BUMPER AREA AS COLLISION DAMAGE. HE STATED THERE WAS NO DAMAGE AND SMALL SCRATCH ON UPP COVER IS UPD. I ATTACHED A UPD ESTIMATE FOR SCRATCH ON FRT COVER. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.

Date: 7/3/2013 09:16 AM
Estimate ID: CO13005281
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: SHANNON PONTRELLI / STP
(714) 738-1383 ext. 2403

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 2/25/2013
Deductible: 0.00
File Number: CO13005281
Claim Number: CO13005281

Type of Loss: Property Damage

Insured: JAVIER GONZALEZ
Owner: JAVIER GONZALEZ
Address: 28955 PUJOL ST APT#4B, TEMECULA, CA 92592
Telephone: Home Phone: (951) 526-8699

Mitchell Service: 914626

Description: 2001 Ford ExplorerSportTrac
Body Style: 4D Ut
VIN: 1FMZU77E61UB94934
Mileage: 146,246
OEM/ALT: A
Color: WHITE
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
MANUAL AIR CONDITION, SKID PLATES, ANTI-LOCK BRAKE SYS., FOG LIGHTS
ALUM/ALLOY WHEELS, FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM
AM/FM STEREO CASSETTE/CD, ELECTRONIC SHIFT TRANSFER CASE, FRONT CAPTAINS CHAIRS
POWER DISC BRAKES

Vehicle Production Date: 11/00
Drive Train: 4.0L Inj 6 Cyl 4WD
License: 6T82929 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	900500	BDY *	ADD'L LABOR OP	NO DAMAGE	Existing		0.0*

* - Judgment Item

ESTIMATE RECALL NUMBER: 07/03/2013 09:16:18 CO13005281

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V
7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 7/ 3/2013 09:16 AM
 Estimate ID: CO13005281
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

Prior Damage:
 frt uper cover

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Labor Summary	0.0				0.00	Total Replacement Parts Amount	0.00
III. Additional Costs					Amount	IV. Adjustments	Amount
Total Additional Costs					0.00	Insurance Deductible	0.00
						Customer Responsibility	0.00
						I. Total Labor:	0.00
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	0.00
						Gross Total:	0.00
						IV. Total Adjustments:	0.00
						Net Total:	0.00

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
 12 Front Center (P)

Inspection Site: RESIDENCE
 TEMECULA, CA 92592
 Inspection Date: 7/ 2/2013

COLLECT ALL FROM OWNER
 ***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
 GUARANTEE OF PAYMENT.***
 ***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
 REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
 FAILURE TO HAVE REINSPECTION WILL RESULT IN
 NON-PAYMENT!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
 COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
 DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
 THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT

ESTIMATE RECALL NUMBER: 07/03/2013 09:16:18 CO13005281

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V
 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Date: 7/3/2013 09:16 AM
Estimate ID: CO13005281
Estimate Version: 0
Preliminary
Profile ID: * PDS

MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/03/2013 09:16:18 CO13005281

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V
7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 7/3/2013 09:16 AM
Estimate ID: CO13005281
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Unrelated Prior Damage

Damage Assessed By: TONY NGUYEN

Appraised For: SHANNON PONTRELLI / STP
(714) 738-1383 ext. 2403

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 2/25/2013

Type of Loss: Property Damage

File Number: CO13005281
Claim Number: CO13005281

Insured: JAVIER GONZALEZ
Owner: JAVIER GONZALEZ
Address: 28955 PUJOL ST APT#4B, TEMECULA, CA 92592
Telephone: Home Phone: (951) 526-8699

Mitchell Service: 914626

Description: 2001 Ford ExplorerSportTrac
Body Style: 4D Ut
VIN: 1FMZU77E61UB94934
Mileage: 146,246
OEM/ALT: A
Color: WHITE
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
MANUAL AIR CONDITION, SKID PLATES, ANTI-LOCK BRAKE SYS., FOG LIGHTS
ALUM/ALLOY WHEELS, FRONT AIR DAM, TINTED GLASS, ANTI-THEFT SYSTEM
AM/FM STEREO CASSETTE/CD, ELECTRONIC SHIFT TRANSFER CASE, FRONT CAPTAINS CHAIRS
POWER DISC BRAKES

Vehicle Production Date: 11/00
Drive Train: 4.0L Inj 6 Cyl 4WD
License: 6T82929 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	400002	BDY	REMOVE/INSTALL	Frt Bumper Assy			1.3 #
2	400004	BDY	REPAIR	Frt Bumper Cover	Existing		1.0*#
3	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.3
4	AUTO	REF	ADD'L OPR	Clear Coat			0.9
5	AUTO		ADD'L COST	Paint/Materials		102.40 *	

ESTIMATE RECALL NUMBER: 07/03/2013 09:16:18 CO13005281

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 7/ 3/2013 09:16 AM
 Estimate ID: CO13005281
 Unrelated Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Prior Damage:
 frt upper cover

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	2.3	48.00	0.00	0.00	110.40		
Refinish	3.2	48.00	0.00	0.00	153.60	Total Replacement Parts Amount	0.00
Non-Taxable Labor					264.00		
Labor Summary	5.5				264.00		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					102.40	Total Adjustments:	0.00
Sales Tax		@	8.000%		8.19		
Total Additional Costs					110.59		
Paint Material Method: Rates							
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
						I. Total Labor:	264.00
						II. Total Replacement Parts:	0.00
						III. Total Additional Costs:	110.59
						Gross Total:	374.59
						IV. Total Adjustments:	0.00
						Unrelated Damage Net Total:	374.59

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
 12 Front Center (P)

ESTIMATE RECALL NUMBER: 07/03/2013 09:16:18 CO13005281
 Mitchell Data Version: OEM: JUN_13_V
 MAPP:JUN_13_V Copyright (C) 1994 - 2013 Mitchell International
 Software Version: 7.0.486 All Rights Reserved

Page 2 of 3

Date: 7/ 3/2013 09:16 AM
Estimate ID: CO13005281
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
TEMECULA , CA 92592
Inspection Date: 7/ 2/2013

ESTIMATE RECALL NUMBER: 07/03/2013 09:16:18 CO13005281

Mitchell Data Version: OEM: JUN_13_V

Software Version: MAPP:JUN_13_V
7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3







