

 **View Claim Summary - File Number: 07032013-100007**

GO BACK

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010899
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Kelly Campos
Date of Loss : 2013-06-29
Whose Claim : Claimant
Owner Name : ANGELA RUAIN
Insured Name : BRANDI MARIE DOOLEY
Claimant Name : ANGELA RUAIN
Inspection Location : RESIDENCE

Appraisal Information

File Number : 07032013-100007
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-06
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2009
Make : Nissan
Model : Sentra
Sub-model :
VIN : 3N1AB61E69L608507
Plate : 6KGM452

State : California
Milage : 30263
Drivable : Yes
Primary POI : LEFT QUARTER PANEL
Secondary POI :
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 842.47
Estimate 2 Total : 0.00
Estimate 1 Betterment : 0.00
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 842.47
Deductible : 0.00
Original Net Loss : 842.47
Gross Total : 842.47
Supplement Net Loss : 0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF CLAIMANTS VEHICLE AT RESIDENCE IN RIVERSIDE ON 7/6/13. CLAIMANT WAS PRESENT & POINTED OUT LEFT REAR CORNER AS COLLISION DAMAGE. SHE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES TO REPAIR QUARTER PANEL AND REAR COVER. NO VISIBLE DAMAGES SEEN TO LFT REAR WHEEL. REAR INNER-STRUCTURE @ LWR QTR PANEL BEHIND COVER ARE OPEN ITEM AREAS PENDING TEAR-DOWN. NO REGISTRATION AVAILABLE HUSBAND HAS OWNER PENDING DIVORCE SETTLEMENT. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.

Date: 7/9/2013 01:08 AM
Estimate ID: CO13010899
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: KELLEY CAMPOS
(714) 738-1383

ROBERT MORENO INS
(714) 738-1383

Condition Code: Good
Date of Loss: 6/29/2013
Deductible: NONE
File Number: CO13010899
Claim Number: CO13010899

Type of Loss: LIABILITY

Insured: BRANDI MARIE DOOLEY
Claimant: ANGELA RUAIN
Owner: ANGELA RUAIN
Address: 4156 PADEN ST , RIVERSIDE , CA 92504
Telephone: Home Phone: (909) 680-2549

Mitchell Service: 910811

Description: 2009 Nissan Sentra
Body Style: 4D Sed
VIN: 3N1AB61E69L608507
Mileage: 30,263
OEM/ALT: A
Color: RED
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER
MANUAL AIR CONDITION, TILT STEERING COLUMN, FOG LIGHTS, AUXILIARY INPUT
AUTOMATIC TRANSMISSION, FRONT AIR DAM, TINTED GLASS, VARIABLE ASSISTED STEERING
SIDE AIRBAGS, ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, SIDE HEAD CURTAIN AIRBAGS
AM/FM STEREO CD, FRONT BUCKET SEATS, INTERIOR AIR FILTER, POWER LIFTGATE\TRUNK

Vehicle Production Date: 10/08
Drive Train: 2.0L Inj 4 Cyl A FWD
License: 6KJM452 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	001465	REF	BLEND	L Roof Rail			C 0.6 #
2	900500	BDY *	ADD'L LABOR OP	ROPE BACK GLASS	** QUAL REPL PART	3.00 *	0.3*
3				partial lft side			
4	001528	BDY	REMOVE/INSTALL	L Roof Drip Moulding			0.4
5	001198	BDY	REPAIR	L Quarter Outer Panel	Existing		2.0* #
6	AUTO	REF	REFINISH	L Quarter Panel Outside			C 2.1
7	001566	BDY	REMOVE/INSTALL	L Rear Combination Lamp			INC #
8	002452	REF	REFINISH	L Rear Bumper Mudguard			C 0.5
9	001569	BDY	REMOVE/INSTALL	Rear Bumper Assy			1.8 #

ESTIMATE RECALL NUMBER: 07/09/2013 01:08:14 CO13010899

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 3

Date: 7/9/2013 01:08 AM
 Estimate ID: CO13010899
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

10	001552	BDY	REMOVE/INSTALL	L Rear Bumper Mudguard		0.2
11	003349	BDY	REPAIR	Rear Bumper Cover	Existing	2.0* #
12		REF	REFINISH/REPAIR	Rear Bumper Cover		C 1.5*
13				MODIFIED REFINISH WITH FULL CLEAR COAT		
14	AUTO	REF	ADD'L OPR	Clear Coat		1.6
15	933003	BDY *	ADD'L OPR	Tint Color		0.5*
16	933018	BDY *	ADD'L OPR	Mask For Overspray		5.00 * 0.2*
17	AUTO		ADD'L COST	Paint/Materials		201.60 *

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary			
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
Body	7.4	45.00	5.00	0.00	338.00	Taxable Parts			3.00
Refinish	6.3	45.00	0.00	0.00	283.50	Sales Tax	@	8.000%	0.24
Non-Taxable Labor					621.50	Total Replacement Parts Amount			3.24
Labor Summary	13.7				621.50				
III. Additional Costs					Amount	IV. Adjustments			
Taxable Costs					201.60	Insurance Deductible			
Sales Tax					16.13	Customer Responsibility			
Total Additional Costs					217.73				
Paint Material Method: Rates									
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I.	Total Labor:		621.50
						II.	Total Replacement Parts:		3.24
						III.	Total Additional Costs:		217.73
							Gross Total:		842.47
						IV.	Total Adjustments:		0.00
							Net Total:		842.47

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
 8 Left Rear Side (P)

ESTIMATE RECALL NUMBER: 07/09/2013 01:08:14 CO13010899

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Date: 7/9/2013 01:08 AM
Estimate ID: CO13010899
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 4156 PADEN ST
RIVERSIDE , CA 92504
Inspection Date: 7/6/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/09/2013 01:08:14 CO13010899

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3









