

 **View Claim Summary - File Number: 06282013-100007**[GO BACK](#)**Claim Summary been saved successfully...****Property Damage Specialist**
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : co13009603
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Brigitte Pecache
Date of Loss : 2013-05-25
Whose Claim : Claimant
Owner Name : jennifer gonzalez
Insured Name : alejandro solarzano
Claimant Name : jennifer gonzalez
Inspection Location : RESIDENCE

Appraisal Information

File Number : 06282013-100007
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 1997
Make : Toyota
Model : Camry
Sub-model : LE
VIN : JT2BG22K6V0091838
Plate : 3WNT844

State :
Milage : 322026
Drivable : Yes
Primary POI : FRT COVER
Secondary POI :
Vehicle Condition : Fair
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation :	Repairable
Estimate 1 Total :	683.11
Estimate 2 Total :	0.00
Estimate 1 Betterment :	0.00
Estimate 2 Betterment :	0.00
Supplement 1 Total :	0.00
Supplement 1 Betterment :	0.00
Supplement 2 Total :	0.00
Supplement 2 Betterment :	0.00
Supplement 3 Total :	0.00
Supplement 3 Betterment :	0.00
Supplement 4 Total :	0.00
Supplement 4 Betterment :	0.00
Subtotal :	683.11
Deductible :	0.00
Original Net Loss :	683.11
Gross Total :	683.11
Supplement Net Loss :	0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF CLAIMANTS VEHICLE AT RESIDENCE IN LAKE ELSINORE ON 7/3/13. CLAIMANTS FATHER WAS PRESENT & POINTED OUT FRONT COVER AS COLLISION DAMAGE. HE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES USING AVAILABLE RECONDITIONED PART AT A COST EFFECTIVE SAVINGS OVER NEW OEM PARTS. I ALSO ATTACHED AN UPD ESTIMATE FOR HOOD AND LEFT FENDER. APPROXIMATE REPAIR TIME IS 3 DAYS. V/O DID NOT WANT TO OPEN HOOD HE WAS NOT SURE IT WILL SHUT AND LOCK. FRONT INNER-STRUCTURE IS AN OPEN ITEM AREA PENDING TEAR-DOWN. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.

Date: 7/7/2013 12:33 PM
Estimate ID: CO13009603
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: BRIGETTE PECACHE / BGP
(714) 738-1383 ext. 2315

ROBERT MORENO INS
(714) 738-1383

Condition Code: Fair
Date of Loss: 5/25/2013
Deductible: NONE
File Number: CO13009603
Claim Number: CO13009603

Type of Loss: LIABILITY

Insured: ALEJANDRO SOLARZANO
Claimant: JENNIFER GONZALEZ
Owner: JENNIFER GONZALEZ
Address: 18080 EUCALYPTUS AVE, LAKE ELSINORE, CA 92532

Mitchell Service: 914751

Description: 1997 Toyota Camry LE
Body Style: 4D Sed
VIN: JT2BG22K6V0091838
Mileage: 322,026
OEM/ALT: A
Color: BURGUNDY
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
ANTI-LOCK BRAKE SYS., AUTOMATIC TRANSMISSION, FRONT AIR DAM, TINTED GLASS
AUTOMATIC HEADLIGHTS, AM/FM STEREO CASSETTE, FRONT BUCKET SEATS
POWER LIFTGATE/TRUNK

Vehicle Production Date: 7/97
Drive Train: 2.2L Inj 4 Cyl A
License: 3WNT844 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	BDY	OVERHAUL	Frt Bumper Assy			2.2 #
2	400025	BDY	REMOVE/REPLACE	Frt Bumper Cover	Remanufactured	264.00	* INC #
3	AUTO	REF	REFINISH	Frt Bumper Cover			C 2.2
4				exchange Kesytone 800-421-7866			
5	400026	BDY	REMOVE/REPLACE	Frt Bumper Emblem	75311-AA020	27.64	INC
6	AUTO	REF	ADD'L OPR	Clear Coat			0.9
7	933003	BDY *	ADD'L OPR	Tint Color			0.5*
8	AUTO		ADD'L COST	Paint/Materials		99.20	*

ESTIMATE RECALL NUMBER: 07/07/2013 12:33:37 CO13009603

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 3

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Prior Damage:

HOOD,RT CORNER LITE AND LEFT FENDER

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary			Amount
	Body	2.7	45.00	0.00	0.00	121.50		Taxable Parts			291.64
	Refinish	3.1	45.00	0.00	0.00	139.50		Sales Tax	@	8.000%	23.33
	Non-Taxable Labor					261.00		Total Replacement Parts Amount			314.97
	Labor Summary	5.8				261.00					
III.	Additional Costs					Amount	IV.	Adjustments			Amount
	Taxable Costs					99.20		Insurance Deductible			0.00
	Sales Tax @ 8.000%					7.94		Customer Responsibility			0.00
	Total Additional Costs					107.14					
	Paint Material Method: Rates										
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00										

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

12 Front Center (P)

ESTIMATE RECALL NUMBER: 07/07/2013 12:33:37 CO13009603

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International

All Rights Reserved

Page 2 of 3

Date: 7/7/2013 12:33 PM
Estimate ID: CO13009603
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 18080 EUCALYPTUS
LAKE ELSINORE, CA 92532
Inspection Date: 7/3/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/07/2013 12:33:37 CO13009603

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version: 7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 7/7/2013 12:33 PM
Estimate ID: CO13009603
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Unrelated Prior Damage

Damage Assessed By: TONY NGUYEN

Appraised For: BRIGETTE PECACHE / BGP
(714) 738-1383 ext. 2315

ROBERT MORENO INS
(714) 738-1383

Condition Code: Fair
Date of Loss: 5/25/2013

Type of Loss: LIABILITY

File Number: CO13009603
Claim Number: CO13009603

Insured: ALEJANDRO SOLARZANO
Claimant: JENNIFER GONZALEZ
Owner: JENNIFER GONZALEZ
Address: 18080 EUCALYPTUS AVE, LAKE ELSINORE, CA 92532

Mitchell Service: 914751

Description: 1997 Toyota Camry LE
Body Style: 4D Sed
VIN: JT2BG22K6V0091838
Mileage: 322,026
OEM/ALT: A
Color: BURGUNDY
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN
ANTI-LOCK BRAKE SYS., AUTOMATIC TRANSMISSION, FRONT AIR DAM, TINTED GLASS
AUTOMATIC HEADLIGHTS, AM/FM STEREO CASSETTE, FRONT BUCKET SEATS
POWER LIFTGATE/TRUNK

Vehicle Production Date: 7/97
Drive Train: 2.2L Inj 4 Cyl A
License: 3WNT844 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	400059	BDY	REMOVE/REPLACE	R Signal Lamp Assembly	81510-AA010	59.65	0.2 #
2	400074	BDY	REMOVE/REPLACE	Hood Panel	Qual Recycled Part	150.00 *	1.0 r
3	AUTO	REF	REFINISH	Hood Outside			C 2.9
4	AUTO	REF	REFINISH	Add For Hood Underside			C 1.4
5	400248	BDY	REPAIR	L Fender Panel	Existing		1.0* #
6	AUTO	REF	REFINISH	L Fender Outside			C 1.7

ESTIMATE RECALL NUMBER: 07/07/2013 12:33:09 CO13009603

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 3

Date: 7/7/2013 12:33 PM
 Estimate ID: CO13009603
 Unrelated Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

7	AUTO	REF	ADD'L OPR	Clear Coat		
8	AUTO		ADD'L COST	Paint/Materials		259.20 *

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Prior Damage:
 HOOD,RT CORNER LITE AND LEFT FENDER

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary			Amount
	Body	2.2	45.00	0.00	0.00	99.00		Taxable Parts			209.65
	Refinish	8.1	45.00	0.00	0.00	364.50		Sales Tax @ 8.000%			16.77
	Non-Taxable Labor					463.50		Total Replacement Parts Amount			226.42
	Labor Summary	10.3				463.50					
III.	Additional Costs					Amount	IV.	Adjustments			Amount
	Taxable Costs					259.20		Total Adjustments:			0.00
	Sales Tax @ 8.000%					20.74					
	Total Additional Costs					279.94					
Paint Material Method: Rates											
Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00											
							I.	Total Labor:			463.50
							II.	Total Replacement Parts:			226.42
							III.	Total Additional Costs:			279.94
								Gross Total:			969.86
							IV.	Total Adjustments:			0.00
								Unrelated Damage Net Total:			969.86

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
 12 Front Center (P)

ESTIMATE RECALL NUMBER: 07/07/2013 12:33:09 CO13009603
 Mitchell Data Version: OEM: JUN_13_V
 MAPP:JUN_13_V Copyright (C) 1994 - 2013 Mitchell International
 Software Version: 7.0.486 All Rights Reserved

Page 2 of 3

Date: 7/7/2013 12:33 PM
Estimate ID: CO13009603
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * PDS

Inspection Site: RESIDENCE
Address: 18080 EUCALYPTUS
LAKE ELSINORE , CA 92532
Inspection Date: 7/3/2013

ESTIMATE RECALL NUMBER: 07/07/2013 12:33:09 CO13009603

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 3 of 3
















REGISTRATION CARD VALID FROM: 08/12/2012 TO: 08/12/2013

MAKE	TR MONTH	TR YEAR	W.P. CLASS	TRFEE TAX	TRFEE LIC	STORAGE NUMBER
TOYT	1997	1997	ES	120	11	3WNT644
BODY TYPE MODEL	SP	NO				
4D	G	TV				JT3BG22K6V0091838
TYPE VEHICLE USE	DATE ISSUED	CC MONTH	ST FEE MONTH	FAC	STICKER ISSUED	
AUTOMOBILE	08/01/12	33	08/01/12	9	H7857791	
					FR. EXP. DATE:	08/12/2012
REGISTRANT NAME					AMOUNT PAID	
LOPEZGONZALEZ JENNIFER					\$ 100.00	
18080 EUCALYPTUS AVE						
LAKE ELSINORE					CASH : 100.00	
CA 92532					CHCK :	
					CRDT :	

LIBREROLODR

THE GREAT SEAL OF THE STATE OF CALIFORNIA

034 55 0010000 0014 CS NOS 082012 11