

 **View Claim Summary - File Number: 06142013-1000026**

GO BACK

Claim Summary been saved successfully...



Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010106
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Debbie Hernandez
Date of Loss : -0001-11-30
Whose Claim : Insured
Owner Name : HORACIO COTA GASTELUM
Insured Name : HORACIO COTA GASTELUM
Claimant Name :
Inspection Location :

Appraisal Information

File Number : 06142013-1000026
Appraiser : Tony Nguyen
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-01
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2000
Make : Dodge
Model : Ram 1500
Sub-model : PICK UP QUAD CAB
VIN : 1B7HC13Y6YJ102832
Plate : 6G47921

State : California
Milage : 155866
Drivable : No
Primary POI :
Secondary POI :
Vehicle Condition : Fair
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation :	Total Loss
Estimate 1 Total :	5636.11
Estimate 2 Total :	0.00
Estimate 1 Betterment :	0.00
Estimate 2 Betterment :	0.00
Supplement 1 Total :	0.00
Supplement 1 Betterment :	0.00
Supplement 2 Total :	0.00
Supplement 2 Betterment :	0.00
Supplement 3 Total :	0.00
Supplement 3 Betterment :	0.00
Supplement 4 Total :	0.00
Supplement 4 Betterment :	0.00
Subtotal :	5636.11
Deductible :	0.00
Original Net Loss :	5636.11
Gross Total :	5636.11
Supplement Net Loss :	0.00

Tire Information

Make :
Size :
Tired Depth (in 32nds)
L/F R/F
L/R R/R
Spare :

Shop Information

Shop Name :

Address 1 :

Address 2 :

City :

State :

Zip :

Phone Number :

Fax :

Agreed Price :

Federal Tax ID # :

Miscellaneous

Towing Charges :

Storage Per Day :

Days :

Approximate Total :

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT RESIDENCE IN PERRIS ON 7/1/13. INSURED WAS NOT PRESENT BUT STATED FRONT END AS COLLISION DAMAGE. HE DIDN'T HAVE A CHOICE OF SHOP AT TIME OF INSPECTION. ESTIMATE WRITTEN AT AREAS PREVAILING RATES USING AVAILABLE OEM PARTS OVER LKQ PARTS. LKQ PARTS WILL LEAVE VEHICLE CLOSE TO A BORDERLINE TOTAL LOSS WITH VARIOUS ITEMS OPEN. I AM ANTICIPATING A LARGE SUPPLEMENT FOR HIDDEN DAMAGES FOR FRAME ASSY AND SUSPENSION. I ALSO HAVE ASSESSED DAMAGES THAT I FEEL MAY POSSIBLY BE FOUND AS DAMAGED AFTER TEARDOWN. WITH ABOVE MENTION AND POSSIBLE LARGE SUPPLEMENT FOR FRAME AND SUSPENSION DAMAGE I SUGGEST STRONGLY THIS VEHICLE BE DEEMED A TOTAL LOSS. HOOD WAS JAMMED AND UNABLE TO OPEN. PLEASE CALL IF YOU HAVE ANY QUESTIONS TONY NGUYEN 714-757-0906.



Used Vehicle Valuation Report

Report Date: 07/04/2013

Effective Dates: 07/04/2013 - 07/11/2013

2000 Dodge Ram 1500 Quad Cab Long Bed

VIN: 1B7HC13Y6YJ102832

Reference:

Base Values				
	Excellent	Very Good	Good	Fair
MSRP	\$23,030	--	--	--
Certified Pre-Owned	NA	--	--	--
Suggested Retail	\$6,150	--	--	--
Private Party	\$4,625	\$4,350	\$4,200	\$3,500
Lending Value	\$3,575	--	--	--
Auction	\$3,550	\$3,475	\$3,175	\$2,575
Trade-In	\$3,225	\$3,150	\$2,850	\$2,225
Value as of: 07/04/2013 Engine: V8, 5.2 Liter Included				
Zip Code: 92571 Transmission: Automatic Included				
Condition: Good Drivetrain: 2WD Included				
Mileage: 155,866 \$(75)/\$(75)				
Itemized Equipment				
(Lending Value / Suggested Retail)				
ABS (4-Wheel)	\$75/\$100	No Cassette	\$(25)/\$(35)	
Air Conditioning	Included	CD (Single Disc)	\$100/\$135	
Cruise Control	\$25/\$35	Dual Air Bags	\$0/\$0	
Power Steering	Included	Towing Pkg	\$125/\$165	
Tilt Wheel	\$50/\$65	Alloy Wheels	\$75/\$100	
No AM/FM Stereo	\$(50)/\$(65)			
Total Itemized Equipment:				\$375/\$500
Total Values including Mileage and Option adjustments				
	Excellent	Very Good	Good	Fair
MSRP	\$23,030	--	--	--
Certified Pre-Owned	NA	--	--	--
Suggested Retail	\$6,575	--	--	--
Private Party	\$5,050	\$4,775	\$4,625	\$3,925
Lending Value	\$3,875	--	--	--
Auction	\$3,850	\$3,775	\$3,475	\$2,875
Trade-In	\$3,525	\$3,450	\$3,150	\$2,525
-- Assumes excellent condition.				
Notes:				

©2013 Kelley Blue Book® Co., Inc. All rights reserved. 07/04/2013 - 07/11/2013 Edition for California 92571. The specific information required to determine the value for this particular vehicle was supplied by the person generating this report. Vehicle valuations are opinions and may vary from vehicle to vehicle. Actual valuations will vary based upon market conditions, specifications, vehicle condition or other particular circumstances pertinent to this particular vehicle or the transaction or the parties to the transaction. This report is intended for the individual use of the person generating this report only and shall not be sold or transmitted to another party. Kelley Blue Book® assumes no responsibility for errors or omissions. (v.13071)

CCC valuescope Basic Claim Information Form



CCC VALUESCOPE.

Report Retrieval Method	<input type="checkbox"/> Email	<input type="checkbox"/> Fax	<input type="checkbox"/> Other (Specify)
CCC Phone: 1-800-621-8070	CCC Fax: 1-800-621-7070	CCC Email: CCCValuescopeRequest@cccis.com	
Office ID Number	Claim Number C013010106		
Adjr Name (First & Last) DEBBIE HERNANDEZ	Appr Name (First & Last) TONY NGUYEN		
Adjr Contact# 714-738-1383	Insured's Name HORACIO COTA GASTELUM		
Owner's Name SAME	Owner's Phone 951-750-4517		
Loss ZIP Code 92571	Loss State CA		
Loss Type <input checked="" type="checkbox"/> Collision <input type="checkbox"/> Theft	Coverage code <input type="checkbox"/> Collision <input type="checkbox"/> Comprehensive <input type="checkbox"/> Liability <input type="checkbox"/> Other		
3rd Party Claim <input type="checkbox"/> Yes <input type="checkbox"/> No	Leased Vehicle <input type="checkbox"/> Yes <input type="checkbox"/> No		
Date of Loss 6-08-13	Exch#Policy #		
Adjuster ID#	Claim Class		
PA Appr ID#			
VIN 1B7HC13Y6YJ102832			
Year 2000	Make DODGE	Model RAM 1500 QUAD CAB	
Body Style <input checked="" type="checkbox"/> 2DR <input type="checkbox"/> 4DR <input type="checkbox"/> Hatchback <input type="checkbox"/> Convertible <input type="checkbox"/> Wagon <input checked="" type="checkbox"/> Pickup <input type="checkbox"/> Van <input type="checkbox"/> Utility			
<input type="checkbox"/> 1/2 Ton <input type="checkbox"/> 3/4 Ton <input type="checkbox"/> 1 Ton <input type="checkbox"/> Short Bed <input checked="" type="checkbox"/> Long Bed <input type="checkbox"/> Cab & Chassis <input type="checkbox"/> Fleetside <input type="checkbox"/> Fenderside			
Engine Size 5.2L Cylinders <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input checked="" type="checkbox"/> 8 <input type="checkbox"/> 10 <input type="checkbox"/> 12 <input type="checkbox"/> Turbo <input type="checkbox"/> Diesel			
Mileage ("UNK" if unknown) 155866			
Transmission <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> S6 <input type="checkbox"/> S5 <input type="checkbox"/> S4 <input type="checkbox"/> S3 <input type="checkbox"/> OD <input type="checkbox"/> 4W <input type="checkbox"/> PO			
Power Options <input checked="" type="checkbox"/> PS Power Steering <input checked="" type="checkbox"/> PB Power Brakes <input type="checkbox"/> PW Power Windows <input type="checkbox"/> PL Power Locks <input type="checkbox"/> SP Power Driver Seat <input type="checkbox"/> PC Power Passenger Seat <input type="checkbox"/> PA Power Antenna <input type="checkbox"/> PM Power Mirrors <input type="checkbox"/> PT Power Trunk/Tailgate <input type="checkbox"/> PP Power Adjustable Petals <input type="checkbox"/> PD Power Sliding Door <input type="checkbox"/> DP Dual Power Sliding Doors Décor/Convenience <input checked="" type="checkbox"/> AC Air Conditioning <input type="checkbox"/> DA Dual Air Conditioning <input type="checkbox"/> CL Climate Control <input type="checkbox"/> RD Rear Defogger <input checked="" type="checkbox"/> IW Intermittent Wipers <input checked="" type="checkbox"/> TW Tilt Wheel <input type="checkbox"/> TL Telescopic Wheel <input checked="" type="checkbox"/> CC Cruise Control <input type="checkbox"/> KE Keyless Entry <input checked="" type="checkbox"/> CN Console/Storage <input type="checkbox"/> CO Overhead Console <input type="checkbox"/> EC Entertainment Center <input type="checkbox"/> NV Navigation System <input type="checkbox"/> C2 Communications System <input type="checkbox"/> HU Heads Up Display <input type="checkbox"/> WT Wood Interior Trim <input type="checkbox"/> EI Electronic Instrumentation <input type="checkbox"/> IB On Board Computer <input type="checkbox"/> MC Message Center <input type="checkbox"/> MM Memory Package <input type="checkbox"/> RJ Remote Start	Seating <input checked="" type="checkbox"/> CS Cloth Seats <input type="checkbox"/> LS Leather Seats <input type="checkbox"/> RL Reclining/ Lounge Seats <input type="checkbox"/> BS Bucket Seats <input type="checkbox"/> SH Heated Seats (2) <input type="checkbox"/> RH Rear Heated Seats <input type="checkbox"/> 3S Third Row Seat <input type="checkbox"/> 3P Power Third Seat <input type="checkbox"/> R3 Retractable Seats <input type="checkbox"/> 2P 12 Passenger Seating <input type="checkbox"/> 5P 15 Passenger Seating <input type="checkbox"/> B2 Captain Chairs (2) <input type="checkbox"/> B4 Captain Chairs (4) <input type="checkbox"/> B6 Captain Chairs (6) Radio <input checked="" type="checkbox"/> AM AM Radio <input checked="" type="checkbox"/> FM FM Radio <input checked="" type="checkbox"/> ST Stereo <input type="checkbox"/> CA Cassette <input type="checkbox"/> SE Search/Seek <input checked="" type="checkbox"/> CD Compact Disc Player <input type="checkbox"/> SK CD Changer/Stacker <input type="checkbox"/> UR Premium Radio <input type="checkbox"/> XM Satellite Radio <input type="checkbox"/> TQ Steering Wheel Touch Controls <input type="checkbox"/> M3 Auxiliary Audio Connection <input type="checkbox"/> EQ Equalizer <input type="checkbox"/> CB CB Radio <input type="checkbox"/> 8T 8 Track Tape Player Wheels <input checked="" type="checkbox"/> AW Aluminum/Alloy Wheels <input type="checkbox"/> CJ Chrome Wheels <input type="checkbox"/> W2 20" or Larger Wheels <input type="checkbox"/> DC Deluxe Wheel Covers <input type="checkbox"/> FC Full Wheel Covers <input type="checkbox"/> SA Spoke Aluminum Wheels <input type="checkbox"/> SY Styled Steel Wheels <input type="checkbox"/> WW Wire Wheels <input type="checkbox"/> WC Wire Wheel Covers <input type="checkbox"/> RW Rally Wheels <input type="checkbox"/> KW Locking Wheels <input type="checkbox"/> LC Locking Wheel Covers	Roof <input type="checkbox"/> EG Electric Glass Roof <input type="checkbox"/> ES Electric Steel Roof <input type="checkbox"/> OR Skyview Roof <input type="checkbox"/> SD Dual Power Roofs <input type="checkbox"/> MS Manual Steel Roof <input type="checkbox"/> MG Manual Glass Roof <input type="checkbox"/> FR Flip Roof <input type="checkbox"/> TT T-Top/Panel <input type="checkbox"/> GT Glass T-Top/Panel <input type="checkbox"/> MV Manual Convertible Roof <input type="checkbox"/> VP Power Convertible Roof <input type="checkbox"/> RM Detachable Roof <input type="checkbox"/> VR Vinyl Roof <input type="checkbox"/> RF Cabriolet Roof <input type="checkbox"/> LR Landau Roof <input type="checkbox"/> LP Padded Landau Roof <input type="checkbox"/> PV Padded Vinyl Roof <input type="checkbox"/> CT Soft Top <input type="checkbox"/> HT Hard Top Safety/Brakes <input checked="" type="checkbox"/> AG Air Bag <input checked="" type="checkbox"/> RG Passenger Air Bag <input type="checkbox"/> XG Front Side Impact Air Bags <input type="checkbox"/> ZG Rear Side Impact Air Bags <input type="checkbox"/> DG Head/Roof Air Bags <input type="checkbox"/> TD Theft Deterrent/Alarm <input type="checkbox"/> VZ Night Vision <input type="checkbox"/> IC Intelligent Cruise <input type="checkbox"/> PJ Parking Sensors <input type="checkbox"/> PX Parking Sensors W/Equip <input checked="" type="checkbox"/> AB Anti-Lock Brakes (4) <input type="checkbox"/> A2 Anti-Lock Brakes (2) <input checked="" type="checkbox"/> DB 4-Wheel Disc Brakes <input type="checkbox"/> RB Rollover Protection <input type="checkbox"/> TX Traction Control <input type="checkbox"/> T1 Stability Control <input type="checkbox"/> AL Auto Level	Exterior/Paint/Glass <input type="checkbox"/> RR Luggage/Roof Rack <input type="checkbox"/> WG Woodgrain <input type="checkbox"/> WP Rear Window Wiper <input type="checkbox"/> 2T Two Tone Paint <input type="checkbox"/> D2 Deluxe 2 Tone Paint <input type="checkbox"/> HP Three Stage Paint <input checked="" type="checkbox"/> IP Clearcoat Paint <input type="checkbox"/> MP Metallic Paint <input type="checkbox"/> SL Rear Spoiler <input type="checkbox"/> FL Fog Lamps <input checked="" type="checkbox"/> TG Tinted Glass <input type="checkbox"/> DT Privacy Glass <input type="checkbox"/> BN Body Side Moldings <input checked="" type="checkbox"/> DM Dual Mirrors <input type="checkbox"/> HM Heated Mirrors <input type="checkbox"/> HV Headlamp Washers <input type="checkbox"/> MX Signal Integrated Mirrors Other <input type="checkbox"/> BD Running Board/Side Steps <input type="checkbox"/> UP Power Retractable Running Boards <input type="checkbox"/> XE Xenon Headlamps <input type="checkbox"/> AR Bed Rails <input type="checkbox"/> BL Bedliner <input type="checkbox"/> BY Bedliner (Spray On) <input type="checkbox"/> CP Fiberglass Cap <input type="checkbox"/> GG Grill Guard <input checked="" type="checkbox"/> SB Rear Step Bumper <input type="checkbox"/> SS Swivel Seats <input type="checkbox"/> SW Rear Sliding Window <input type="checkbox"/> PG Power Rear Window <input type="checkbox"/> TB Tool Box (Permanent) <input type="checkbox"/> TN Tonneau Cover – Soft <input type="checkbox"/> TZ Tonneau Cover – Hard <input checked="" type="checkbox"/> TP Trailing Package <input type="checkbox"/> WD Dual Rear Wheels <input type="checkbox"/> XT Auxiliary Fuel Tank <input type="checkbox"/> 3D 3rd Truck Door <input type="checkbox"/> 4D 4th Door Truck/Van <input type="checkbox"/> BC Bumper Cushions <input type="checkbox"/> BG Bumper Guards <input type="checkbox"/> EM California Emissions <input type="checkbox"/> SG Stone Guard <input type="checkbox"/> WI Winch

CCC Valuescope Basic Claim Information Form (Continued)

Office ID Number				Claim Number			
REFURBISHMENTS							
Transmission	Purchase Price		Mileage		Engine	Purchase Price	
Tires	Purchase Price		# of Tires				
Paint	<input type="checkbox"/> Basic	<input type="checkbox"/> Standard	<input type="checkbox"/> Custom	Date Painted	Purchase Price		
Interior	Purchase Price		Date	<input type="checkbox"/> Leather	<input type="checkbox"/> Vinyl	<input type="checkbox"/> Cloth	
Camper Shell	Purchase Price		Date	Carpet Kit	Purchase Price		Date
Special Wheels	Purchase Price		Date				
Other	Description				Purchase Price		Date
<input type="checkbox"/> Restored	Restored Amount						
Package/Special Features/Additional Options (XXXX=CALL BACK)							
CONDITION RATING: Rate each of the following 0=Below Average, 1=Normal, 2=Above Average, 3=Exceptional						COMMENTS	
Seats	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. Minimal fading, tears or burn marks		
Carpet	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No significant soiling or staining. Minimal tears, holes or burn marks. Light wear		
Dashboard	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No significant cracks, scratches or gouges. Components firmly intact. Light wear or fading		
Headliner	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Clean. No tears or sagging. Light fading		
Body	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Sheetmetal: No dents. Small/numerous dings. No significant surface rust. Trim: Minimal damage to components. Minimal peeling or fading. No rust apparent		
Glass	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	No scratches, pitting or chips. Seals are intact and watertight		
Paint	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Small/few chips or scratches. Slight fading		
Engine	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Minor seepage. Belts and hoses firm, show minimal wear. Minimal dirt and grease in engine compartment. No burn marks around tailpipe		
Transmission	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	Fluid slightly darkened. Minor seepage		
Front Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	5-7/32" of tread present. 41% to 68% of new. No signs of uneven wear		
Rear Tires	<input type="checkbox"/> 0	<input checked="" type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 3	5-7/32" of tread present. 41% to 68% of new. No signs of uneven wear		
ADJUSTMENTS							
Pre Tax Adjustment 1					Add	Deduct	
Pre Tax Adjustment 2					Add	Deduct	
Sales Tax %	Leave blank if using AutoTax				Deductible		
Post Tax Adjustment 1					Add	Deduct	
Post Tax Adjustment 2					Add	Deduct	

Date: 7/4/2013 12:33 PM
Estimate ID: CO13010106
Estimate Version: 0
Preliminary
Profile ID: * PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349

Damage Assessed By: TONY NGUYEN

Appraised For: DEBBIE HERNANDEZ / RMIS DLH
(714) 738-1383 ext. 2417

ROBERT MORENO INS
(714) 738-1383

Condition Code: Fair
Date of Loss: 6/8/2013
Deductible: 0.00
File Number: CO13010106
Claim Number: CO13010106

Type of Loss: Property Damage

Insured: HORACIO GASTELUM
Owner: HORACIO GASTELUM
Address: 275 TRADITION ST, PERRIS, CA 92571
Telephone: Home Phone: (951) 750-4517

Mitchell Service: 914527

Description: 2000 Dodge Pickup R1500
Body Style: 2D PkUpQua 8' Bed 155" WB
VIN: 1B7HC13Y6YJ102832
Mileage: 155,866
OEM/ALT: A
Color: SILVER
Options: PASSENGER AIRBAG, DRIVER AIRBAG, MANUAL AIR CONDITION, CRUISE CONTROL
TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS., ALUM/ALLOY WHEELS
TOW HITCH RECEIVER, AUTOMATIC TRANSMISSION, TINTED GLASS
VARIABLE ASSISTED STEERING, AM/FM STEREO CD, FRONT SPLIT BENCH SEAT
POWER DISC BRAKES

Vehicle Production Date: 7/99
Drive Train: 5.2L Inj 8 Cyl 2WD
License: 6G47921 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	AUTO	BDY	OVERHAUL	Frt Bumper Assy			1.4
2	436277	BDY	REMOVE/REPLACE	Frt Bumper Face Bar	55076599AG	469.00	INC
3	436202	BDY	REMOVE/REPLACE	Frt Bumper Filler Cover	55076610AB	106.00	INC
4	436205	BDY	REMOVE/REPLACE	Frt Lwr Bumper Filler Cover	55076614AC	149.00	INC
5	436285	BDY	REMOVE/REPLACE	Grille	55076550AB	402.00	INC #
6	436295	BDY	REMOVE/REPLACE	L Front Combination Lamp Assembly	ORDER FROM DEALER	212.00	INC #
7	AUTO	BDY	CHECK/ADJUST	Headlamps			0.4
8	436308	BDY	REMOVE/REPLACE	Hood Panel	55075923AD	797.00	1.3
9	AUTO	REF	REFINISH	Hood Outside			C 3.2
10	AUTO	REF	REFINISH	Add For Hood Underside			C 1.6

ESTIMATE RECALL NUMBER: 07/04/2013 12:33:39 CO13010106

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Software Version: 7.0.486

All Rights Reserved

Page 1 of 3

Date: 7/ 4/2013 12:33 PM
 Estimate ID: CO13010106
 Estimate Version: 0
 Preliminary
 Profile ID: * PDS

11	436310	BDY	REMOVE/REPLACE	L Hood Hinge	55075795AC	215.00	0.2	#
12	AUTO	REF	REFINISH	L Hinge			0.3	
13	AUTO	BDY	REMOVE/INSTALL	Hood Assy			INC	
14	402860	BDY	REMOVE/REPLACE	Upr Cooling Tie Bar	55275412AD	190.00	0.5	
15	AUTO	REF	REFINISH	Upper Tie Bar			0.5	
16	407310	BDY	REMOVE/REPLACE	L Fender Panel	55234709AG	565.00	3.9	#
17	AUTO	REF	REFINISH	L Fender Outside			C 1.6	
18	AUTO	REF	REFINISH	L Add To Edge Fender			C 0.8	
19	AUTO	REF	REFINISH	L Add For Fender Apron			0.5	
20	436455	BDY	REPAIR	R Fender Reinforcement	Existing		0.0*	
21	436456	BDY	REMOVE/REPLACE	L Fender Reinforcement	55275397AB	d40.20	0.3	
22	400622	BDY	REMOVE/REPLACE	L Fender Skirt	55346015	88.25	INC	#
23	436460	BDY	REMOVE/REPLACE	L Fender Apron Assy	55275311AH	220.00	INC	#
24	436464	BDY	REMOVE/REPLACE	L Fender Battery Tray	55275127AE	78.70	INC	#
25	436622	BDY	REMOVE/REPLACE	Wheel	Remanufactured	189.00*	0.3	
26	436625	BDY	REMOVE/REPLACE	Wheel Center Cap	ORDER FROM DEALER	25.95		
27	931105	MCH	ADD'L LABOR OP	FOUR WHEEL ALIGNMENT	Sublet	79.99	*	0.0*
28	400131	BDY	REMOVE/INSTALL	L Battery	Existing	0.00	INC	r
29	933006	FRM	ADD'L OPR	Frame/Rack Set Up			2.0*	
30	933021	BDY *	ADD'L OPR	De-Nib And Finesse			1.5*	
31	AUTO	REF	ADD'L OPR	Clear Coat			2.4	
32	933003	BDY *	ADD'L OPR	Tint Color			0.5*	
33	AUTO		ADD'L COST	Paint/Materials		370.60	*	

* - Judgment Item
 # - Labor Note Applies
 d - Discontinued by the Manufacturer
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary				Amount
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals					
Body	10.3	46.00	0.00	0.00	473.80	Taxable Parts			3,747.10	
Refinish	10.9	46.00	0.00	0.00	501.40	Sales Tax @ 8.000%			299.77	
Frame	2.0	60.00	0.00	0.00	120.00					
Mechanical	0.0	80.00	0.00	79.99	79.99	Total Replacement Parts Amount			4,046.87	
Non-Taxable Labor					1,175.19					
Labor Summary	23.2				1,175.19					
III. Additional Costs					Amount	IV. Adjustments				Amount
Taxable Costs					370.60	Insurance Deductible				0.00
Sales Tax @ 8.000%					29.65	Customer Responsibility				0.00
Total Additional Costs					400.25					

Paint Material Method: Rates
 Init Rate = 34.00 , Init Max Hours = 99.9, Addl Rate = 0.00

ESTIMATE RECALL NUMBER: 07/04/2013 12:33:39 CO13010106

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 2 of 3

Software Version: 7.0.486

All Rights Reserved

Date: 7/ 4/2013 12:33 PM
Estimate ID: CO13010106
Estimate Version: 0
Preliminary
Profile ID: * PDS

I.	Total Labor:	1,175.19
II.	Total Replacement Parts:	4,046.87
III.	Total Additional Costs:	400.25
	Gross Total:	5,622.31
IV.	Total Adjustments:	0.00
	Net Total:	5,622.31
		TOTAL LOSS

This is a preliminary estimate.
Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

15 Total Loss (P), 10 Left Front Side (S), 11 Left Front Corner (S)

Inspection Site: RESIDENCE
PERRIS, CA 92571
Inspection Date: 7/ 4/2013

COLLECT ALL FROM OWNER
***THIS IS NOT AN AUTHORIZATION FOR REPAIR OR
GUARANTEE OF PAYMENT.***
***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE
REINSPECTED PRIOR TO REPAIR BY THE APPRAISER
FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!!!!!***

***COPY OF THIS APPRAISAL/SUPPLEMENT ONLY IS *NOT* AN ACCEPTANCE OF
COVERAGE OR LIABILITY. ALL ISSUES OF COVERAGE OR LIABILITY ARE TO BE
DETERMINED BY ROBERT MORENO INSURANCE COMPANY.
THIS ESTIMATE/SUPPLEMENT IS SUBJECT TO AUDIT AND REVISION BY ROBERT
MORENO INSURANCE COMPANY.

Pursuant to California Code of Regulations Section 2695.8(g)
The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

ESTIMATE RECALL NUMBER: 07/04/2013 12:33:39 CO13010106

Mitchell Data Version: OEM: JUN_13_V

MAPP:JUN_13_V

Software Version:

7.0.486

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3













