

 **View Claim Summary - File Number: 07022013-1000021**[GO BACK](#)**Claim Summary been saved successfully...**

Property Damage Specialist
P.O. Box 2002, Indio
California, United States
92202

Claim Information

Claim Number : CO13010896
Policy Number :
Insurance Company : Robert Moreno Insurance
Adjuster : Stephanie Brown
Date of Loss : 2013-07-01
Whose Claim : Insured
Owner Name : TAMAURA A MUNTER
Insured Name : TAMAURA A MUNTER
Claimant Name :
Inspection Location : TOW YARD

Appraisal Information

File Number : 07022013-1000021
Appraiser : Colleen Washington
Reinspector : Not Assigned
Loss Type : Collision
Inspection Date : 2013-07-03
Assigned Date/Time :
Assignment Type : Full Appraisal
ERT (Days) :
Possible Supplement :

Vehicle Information

Year : 2010
Make : Chevrolet
Model : Impala
Sub-model : LT

VIN : 2G1WB5EN4A1186646
Plate : 6WCY281
State : California
Milage : 78164
Drivable : No
Primary POI : LT FRONT
Secondary POI : RT FRONT
Vehicle Condition : Good
Interior Condition :
Paint Condition :
Engine :

Repair Information

Recommendation : Repairable
Estimate 1 Total : 1145.32
Estimate 2 Total : 0.00
Estimate 1 Betterment : 124.26
Estimate 2 Betterment : 0.00
Supplement 1 Total : 0.00
Supplement 1 Betterment : 0.00
Supplement 2 Total : 0.00
Supplement 2 Betterment : 0.00
Supplement 3 Total : 0.00
Supplement 3 Betterment : 0.00
Supplement 4 Total : 0.00
Supplement 4 Betterment : 0.00
Subtotal : 1021.06
Deductible : 1000.00
Original Net Loss : 21.06
Gross Total : 1021.06
Supplement Net Loss : 0.00

Tire Information

Make :
Size : 225/60/16

Tired Depth (in 32nds)

L/F 2/32 R/F 6/32

L/R R/R

Spare :

Shop Information

Shop Name : PARKING AUTHORITY

Address 1 : 220 SOLANO AVE

Address 2 :

City : BAY POINT

State : California

Zip : 94565

Phone Number : 925-261-1180

Fax :

Agreed Price : No

Federal Tax ID # :

Miscellaneous

Towing Charges : 185

Storage Per Day : 85

Days : 10

Approximate Total : 1035.00

Rental Vehicle : Unknown

Total Rental Potential Cost :

Actual Rental Days :

Actual Rental Amount :

Style :

Claim Remarks

COMPLETED INSPECTION & ESTIMATE OF INSURED VEHICLE AT PARKING AUTHORITY ON 7/3/13. OBSERVED RECOVER THEFT DAMAGE. PARKING AUTHORITY CHARGES \$ 85/ DAY FOR STORAGE SINCE 6-24-13, TOWING 185. FRONT SUSPENSION ARE OPEN ITEMS PENDING TEAR-DOWN AND ALIGNMENT RESULTS. THERE IS ADDITIONAL DAMAGE TO THE VEHICLE THAT WE HAVE LISTED, AS PRIOR UNRELATED DAMAGE DUE WE COULD NOT GET A HOLD OF OWNER TO GO OVER THE VEHICLE AT TIME OF INSPECTION.

Date: 7/ 4/2013 11:34 PM
Estimate ID: CO13010896
Estimate Version: 0
Preliminary
Profile ID: * RMIS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Damage Assessed By: COLLEEN WASHINGTON

Appraised For: STEPHANIE BROWN 714-738-1383 X 2313

Condition Code: Good
Date of Loss: 7/ 1/2013
Deductible: 1,000.00
File Number: CO13010896
Claim Number: CO13010896

Type of Loss: Comprehensive

Insured: TAMAURAA MUNTHER
Owner: TAMAURAA MUNTHER
Address: 15 PONCTA CT, SACRAMENTO, CA 95823
Telephone: Home Phone: (510) 499-2269

Mitchell Service: 910565

Description: 2010 Chevrolet Impala LT
Body Style: 4D Sed
VIN: 2G1WB5EN4A1186646
Mileage: 78,164
OEM/ALT: O
Color: RED
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
POWER STEERING, REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL
TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
ALUM/ALLOY WHEELS, REMOTE IGNITION, NAVIGATION SYSTEM, AUXILIARY INPUT
SATELLITE RADIO, FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER, TELEMATIC SYSTEMS
ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, FRONT SIDE AIRBAG WITH HEAD PROTECTION
SIDE HEAD CURTAIN AIRBAGS, VEHICLE THEFT TRACKING/NOTIFICATION
DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER, FRONT BUCKET SEATS
INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES
POWER LIFTGATE\TRUNK, STEERING WHEEL MOUNTED CONTROLS

Vehicle Production Date: 1/10
Drive Train: 3.5L Inj 6 Cyl 4A FWD
License: 6WCY281 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	000413	MCH	REMOVE/REPLACE	R Lwr Frt Susp Control Arm Assy -M	22947663 GM PART	172.64	1.2 #
2	931015	MCH *	REPAIR	SAFETY CHECK	Existing		1.0*
3	000499	MCH	REMOVE/REPLACE	R Inr Steering Tie Rod -M	26021769 GM PART	72.97	2.8 #
4	002467	MCH	REMOVE/REPLACE	R Otr Steering Tie Rod End -M	26086580 GM PART	118.84	0.3
5	936010		ADD'L COST	DETAIL/CLEANUP		75.00 *	
6	936012		ADD'L COST	Hazardous Waste Disposal		3.00 *	

ESTIMATE RECALL NUMBER: 07/04/2013 23:34:37 CO13010896

Mitchell Data Version: OEM: MAY_13_V

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Software Version: 7.0.485

Page 1 of 3

7	900500	BDY *	REMOVE/REPLACE	LT/FT TIRE 225/60/16	** QUAL REPL PART	95.00	*	0.0*
8				TIRERACK.COM				
9				BETTERMENT TAKEN ON TIRE BASED ON REMAINING				
10				THREAD 2/32				
11			BETTERMENT - P	LT/FT TIRE 225/60/16 %70.00		66.50		
12	900500	BDY *	REMOVE/REPLACE	RT/FT TIRE 25/60/16	** QUAL REPL PART	95.00	*	0.0*
13				BETTERMENT TAKEN ON TIRE BASED ON REMAINING				
14				THREAD 6/32				
15			BETTERMENT - P	RT/FT TIRE 25/60/16 %50.00		47.50		
16	900500	MCH *	REMOVE/REPLACE	2 WHEEL ALIGNMENT	Sublet	59.95	*	0.0*
17	900500	MCH *	REMOVE/REPLACE	MOUNT & BALANCE 2@12.50	Sublet	25.00	*	0.0*

* - Judgment Item

- Labor Note Applies

Prior Damage:

REAR BUMPER , LT 1/4

Estimate Totals

		Units	Rate	Add'l Labor Amount	Sublet Amount	Totals					Amount
I.	Labor Subtotals						II.	Part Replacement Summary			
	Mechanical	5.3	70.00	0.00	0.00	371.00		Taxable Parts			554.45
								Sales Tax	@ 9.000%		49.90
								Non-Taxable Parts			84.95
	Labor Summary	5.3				371.00		Total Replacement Parts Amount			689.30
III.	Additional Costs						IV.	Adjustments			
	Taxable Costs					78.00		Betterment & Tax			124.26-
	Sales Tax			@ 9.000%		7.02		Insurance Deductible			1,000.00-
	Total Additional Costs					85.02		Customer Responsibility			1,124.26-
							I.	Total Labor:			371.00
							II.	Total Replacement Parts:			689.30
							III.	Total Additional Costs:			85.02
								Gross Total:			1,145.32
							IV.	Total Adjustments:			1,124.26-
								Net Total:			21.06

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

14 Unknown (P), 1 Right Front Corner (S), 11 Left Front Corner (S)

Insurance Co: ROBERT MORENO INSURANCE

Inspection Site: PARKING AUTHORITY
Address: 220 SOLANO AVE
BAY POINT , CA 94565
Inspection Date: 7/ 3/2013

Body Shop: OWNER CHOICE OF SHOP

COLLECT ALL FROM OWNER

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

***ANY DAMAGE NOT ON THIS ESTIMATE MUST BE REINSPECTED PRIOR TO REPAIR
BY THE APPRAISER. FAILURE TO HAVE REINSPECTION WILL RESULT IN
NON-PAYMENT!!!!!!!!***

Pursuant to California Code of Regulations Section 2695.8(g)

The insurance company named on this damage estimate warrants that all
non-original equipment replacement parts listed herein are of like,
kind, quality, safety, fit and performance as original equipment
manufacturer replacement crash parts.

Date: 7/ 4/2013 11:34 PM
Estimate ID: CO13010896
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * RMIS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795

PROPERTY DAMAGE SPECIALIST

PO BOX 2002, INDIO, CA 92202
(760) 275-6795
Fax: (760) 863-5349
Email: pds9593@verizon.net

Unrelated Prior Damage

Damage Assessed By: COLLEEN WASHINGTON

Appraised For: STEPHANIE BROWN 714-738-1383 X 2313

Condition Code: Good
Date of Loss: 7/ 1/2013

Type of Loss: Comprehensive

File Number: CO13010896
Claim Number: CO13010896

Insured: TAMAURAA MUNTHERR
Owner: TAMAURAA MUNTHERR
Address: 15 PONCTA CT, SACRAMENTO, CA 95823
Telephone: Home Phone: (510) 499-2269

Mitchell Service: 910565

Description: 2010 Chevrolet Impala LT
Body Style: 4D Sed
VIN: 2G1WB5EN4A1186646
Mileage: 78,164
OEM/ALT: O
Color: RED
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW
POWER STEERING, REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, CRUISE CONTROL
TILT STEERING COLUMN, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS
ALUM/ALLOY WHEELS, REMOTE IGNITION, NAVIGATION SYSTEM, AUXILIARY INPUT
SATELLITE RADIO, FRONT AIR DAM, TINTED GLASS, TRIP COMPUTER, TELEMATIC SYSTEMS
ANTI-THEFT SYSTEM, AUTOMATIC HEADLIGHTS, FRONT SIDE AIRBAG WITH HEAD PROTECTION
SIDE HEAD CURTAIN AIRBAGS, VEHICLE THEFT TRACKING/NOTIFICATION
DAYTIME RUNNING LIGHTS, AM/FM STEREO CD/MP3 PLAYER, FRONT BUCKET SEATS
INTERIOR AIR FILTER, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES
POWER LIFTGATE\TRUNK, STEERING WHEEL MOUNTED CONTROLS

Vehicle Production Date: 1/10
Drive Train: 3.5L Inj 6 Cyl 4A FWD
License: 6WCY281 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
--------------	-----------------	---------------	-----------	--------------------------	---------------------------	------------------	----------------

ESTIMATE RECALL NUMBER: 07/04/2013 23:34:37 CO13010896

Mitchell Data Version: OEM: MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

Date: 7/ 4/2013 11:34 PM
 Estimate ID: CO13010896
 Unrelated Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: * RMIS

1	002218	BDY	REPAIR	L Section Quarter Panel					2.0* #
2	AUTO	REF	REFINISH	L Quarter Panel Outside				C	2.4
3	AUTO	REF	REFINISH	L Add For Pillar				C	0.5
4	AUTO	BDY	OVERHAUL	Rear Bumper Assy					1.9 #
5	001841	BDY	REMOVE/REPLACE	Rear Bumper Cover	19120960	GM PART	496.25	INC	#
6	AUTO	REF	REFINISH	Rear Bumper Cover				C	2.9
7	AUTO	REF	ADD'L OPR	Clear Coat					1.7
8	AUTO		ADD'L COST	Paint/Materials			262.50	*	

* - Judgment Item

- Labor Note Applies

C - Included in Clear Coat Calc

Prior Damage:

REAR BUMPER , LT 1/4

Estimate Totals

I. Labor Subtotals						II. Part Replacement Summary			
	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals				Amount
Body	3.9	70.00	0.00	0.00	273.00	Taxable Parts			496.25
Refinish	7.5	70.00	0.00	0.00	525.00	Sales Tax	@	9.000%	44.66
Non-Taxable Labor					798.00	Total Replacement Parts Amount			540.91
Labor Summary	11.4				798.00				
III. Additional Costs					Amount	IV. Adjustments			
Taxable Costs					262.50	Total Adjustments:			
Sales Tax					23.63				
Total Additional Costs					286.13				
Paint Material Method: Rates									
Init Rate = 35.00 , Init Max Hours = 99.9, Addl Rate = 0.00									
						I.	Total Labor:		798.00
						II.	Total Replacement Parts:		540.91
						III.	Total Additional Costs:		286.13
							Gross Total:		1,625.04
						IV.	Total Adjustments:		0.00
							Unrelated Damage Net Total:		1,625.04

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

ESTIMATE RECALL NUMBER: 07/04/2013 23:34:37 CO13010896

Mitchell Data Version: OEM: MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 2 of 3

Date: 7/ 4/2013 11:34 PM
Estimate ID: CO13010896
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: * RMIS

Point(s) of Impact

14 Unknown (P), 1 Right Front Corner (S), 11 Left Front Corner (S)

Insurance Co: ROBERT MORENO INSURANCE

Inspection Site: PARKING AUTHORITY
Address: 220 SOLANO AVE
BAY POINT , CA 94565
Inspection Date: 7/ 3/2013


Body Shop: OWNER CHOICE OF SHOP


















GENERAL INFORMATION		VEHICLE INFORMATION		OWNER INFORMATION		APPROVAL		RELEASE		DISPOSITION		SIGNATURE	
1. MAKE	2. MODEL	3. YEAR	4. COLOR	5. VIN	6. LICENSE NO.	7. NAME	8. ADDRESS	9. CITY	10. STATE	11. ZIP	12. PHONE	13. SIGNATURE	14. DATE
15. MAKE	16. MODEL	17. YEAR	18. COLOR	19. VIN	20. LICENSE NO.	21. NAME	22. ADDRESS	23. CITY	24. STATE	25. ZIP	26. PHONE	27. SIGNATURE	28. DATE
<p>29. MAKE</p> <p>30. MODEL</p> <p>31. YEAR</p> <p>32. COLOR</p> <p>33. VIN</p> <p>34. LICENSE NO.</p> <p>35. NAME</p> <p>36. ADDRESS</p> <p>37. CITY</p> <p>38. STATE</p> <p>39. ZIP</p> <p>40. PHONE</p> <p>41. SIGNATURE</p> <p>42. DATE</p>													
<p>43. MAKE</p> <p>44. MODEL</p> <p>45. YEAR</p> <p>46. COLOR</p> <p>47. VIN</p> <p>48. LICENSE NO.</p> <p>49. NAME</p> <p>50. ADDRESS</p> <p>51. CITY</p> <p>52. STATE</p> <p>53. ZIP</p> <p>54. PHONE</p> <p>55. SIGNATURE</p> <p>56. DATE</p>													
<p>57. MAKE</p> <p>58. MODEL</p> <p>59. YEAR</p> <p>60. COLOR</p> <p>61. VIN</p> <p>62. LICENSE NO.</p> <p>63. NAME</p> <p>64. ADDRESS</p> <p>65. CITY</p> <p>66. STATE</p> <p>67. ZIP</p> <p>68. PHONE</p> <p>69. SIGNATURE</p> <p>70. DATE</p>													
<p>71. MAKE</p> <p>72. MODEL</p> <p>73. YEAR</p> <p>74. COLOR</p> <p>75. VIN</p> <p>76. LICENSE NO.</p> <p>77. NAME</p> <p>78. ADDRESS</p> <p>79. CITY</p> <p>80. STATE</p> <p>81. ZIP</p> <p>82. PHONE</p> <p>83. SIGNATURE</p> <p>84. DATE</p>													
<p>85. MAKE</p> <p>86. MODEL</p> <p>87. YEAR</p> <p>88. COLOR</p> <p>89. VIN</p> <p>90. LICENSE NO.</p> <p>91. NAME</p> <p>92. ADDRESS</p> <p>93. CITY</p> <p>94. STATE</p> <p>95. ZIP</p> <p>96. PHONE</p> <p>97. SIGNATURE</p> <p>98. DATE</p>													
<p>99. MAKE</p> <p>100. MODEL</p> <p>101. YEAR</p> <p>102. COLOR</p> <p>103. VIN</p> <p>104. LICENSE NO.</p> <p>105. NAME</p> <p>106. ADDRESS</p> <p>107. CITY</p> <p>108. STATE</p> <p>109. ZIP</p> <p>110. PHONE</p> <p>111. SIGNATURE</p> <p>112. DATE</p>													
<p>113. MAKE</p> <p>114. MODEL</p> <p>115. YEAR</p> <p>116. COLOR</p> <p>117. VIN</p> <p>118. LICENSE NO.</p> <p>119. NAME</p> <p>120. ADDRESS</p> <p>121. CITY</p> <p>122. STATE</p> <p>123. ZIP</p> <p>124. PHONE</p> <p>125. SIGNATURE</p> <p>126. DATE</p>													
<p>127. MAKE</p> <p>128. MODEL</p> <p>129. YEAR</p> <p>130. COLOR</p> <p>131. VIN</p> <p>132. LICENSE NO.</p> <p>133. NAME</p> <p>134. ADDRESS</p> <p>135. CITY</p> <p>136. STATE</p> <p>137. ZIP</p> <p>138. PHONE</p> <p>139. SIGNATURE</p> <p>140. DATE</p>													
<p>141. MAKE</p> <p>142. MODEL</p> <p>143. YEAR</p> <p>144. COLOR</p> <p>145. VIN</p> <p>146. LICENSE NO.</p> <p>147. NAME</p> <p>148. ADDRESS</p> <p>149. CITY</p> <p>150. STATE</p> <p>151. ZIP</p> <p>152. PHONE</p> <p>153. SIGNATURE</p> <p>154. DATE</p>													
<p>155. MAKE</p> <p>156. MODEL</p> <p>157. YEAR</p> <p>158. COLOR</p> <p>159. VIN</p> <p>160. LICENSE NO.</p> <p>161. NAME</p> <p>162. ADDRESS</p> <p>163. CITY</p> <p>164. STATE</p> <p>165. ZIP</p> <p>166. PHONE</p> <p>167. SIGNATURE</p> <p>168. DATE</p>													
<p>169. MAKE</p> <p>170. MODEL</p> <p>171. YEAR</p> <p>172. COLOR</p> <p>173. VIN</p> <p>174. LICENSE NO.</p> <p>175. NAME</p> <p>176. ADDRESS</p> <p>177. CITY</p> <p>178. STATE</p> <p>179. ZIP</p> <p>180. PHONE</p> <p>181. SIGNATURE</p> <p>182. DATE</p>													
<p>183. MAKE</p> <p>184. MODEL</p> <p>185. YEAR</p> <p>186. COLOR</p> <p>187. VIN</p> <p>188. LICENSE NO.</p> <p>189. NAME</p> <p>190. ADDRESS</p> <p>191. CITY</p> <p>192. STATE</p> <p>193. ZIP</p> <p>194. PHONE</p> <p>195. SIGNATURE</p> <p>196. DATE</p>													
<p>197. MAKE</p> <p>198. MODEL</p> <p>199. YEAR</p> <p>200. COLOR</p> <p>201. VIN</p> <p>202. LICENSE NO.</p> <p>203. NAME</p> <p>204. ADDRESS</p> <p>205. CITY</p> <p>206. STATE</p> <p>207. ZIP</p> <p>208. PHONE</p> <p>209. SIGNATURE</p> <p>210. DATE</p>													
<p>211. MAKE</p> <p>212. MODEL</p> <p>213. YEAR</p> <p>214. COLOR</p> <p>215. VIN</p> <p>216. LICENSE NO.</p> <p>217. NAME</p> <p>218. ADDRESS</p> <p>219. CITY</p> <p>220. STATE</p> <p>221. ZIP</p> <p>222. PHONE</p> <p>223. SIGNATURE</p> <p>224. DATE</p>													
<p>225. MAKE</p> <p>226. MODEL</p> <p>227. YEAR</p> <p>228. COLOR</p> <p>229. VIN</p> <p>230. LICENSE NO.</p> <p>231. NAME</p> <p>232. ADDRESS</p> <p>233. CITY</p> <p>234. STATE</p> <p>235. ZIP</p> <p>236. PHONE</p> <p>237. SIGNATURE</p> <p>238. DATE</p>													
<p>239. MAKE</p> <p>240. MODEL</p> <p>241. YEAR</p> <p>242. COLOR</p> <p>243. VIN</p> <p>244. LICENSE NO.</p> <p>245. NAME</p> <p>246. ADDRESS</p> <p>247. CITY</p> <p>248. STATE</p> <p>249. ZIP</p> <p>250. PHONE</p> <p>251. SIGNATURE</p> <p>252. DATE</p>													
<p>253. MAKE</p> <p>254. MODEL</p> <p>255. YEAR</p> <p>256. COLOR</p> <p>257. VIN</p> <p>258. LICENSE NO.</p> <p>259. NAME</p> <p>260. ADDRESS</p> <p>261. CITY</p> <p>262. STATE</p> <p>263. ZIP</p> <p>264. PHONE</p> <p>265. SIGNATURE</p> <p>266. DATE</p>													
<p>267. MAKE</p> <p>268. MODEL</p> <p>269. YEAR</p> <p>270. COLOR</p> <p>271. VIN</p> <p>272. LICENSE NO.</p> <p>273. NAME</p> <p>274. ADDRESS</p> <p>275. CITY</p> <p>276. STATE</p> <p>277. ZIP</p> <p>278. PHONE</p> <p>279. SIGNATURE</p> <p>280. DATE</p>													
<p>281. MAKE</p> <p>282. MODEL</p> <p>283. YEAR</p> <p>284. COLOR</p> <p>285. VIN</p> <p>286. LICENSE NO.</p> <p>287. NAME</p> <p>288. ADDRESS</p> <p>289. CITY</p> <p>290. STATE</p> <p>291. ZIP</p> <p>292. PHONE</p> <p>293. SIGNATURE</p> <p>294. DATE</p>													
<p>295. MAKE</p> <p>296. MODEL</p> <p>297. YEAR</p> <p>298. COLOR</p> <p>299. VIN</p> <p>300. LICENSE NO.</p> <p>301. NAME</p> <p>302. ADDRESS</p> <p>303. CITY</p> <p>304. STATE</p> <p>305. ZIP</p> <p>306. PHONE</p> <p>307. SIGNATURE</p> <p>308. DATE</p>													
<p>309. MAKE</p> <p>310. MODEL</p> <p>311. YEAR</p> <p>312. COLOR</p> <p>313. VIN</p> <p>314. LICENSE NO.</p> <p>315. NAME</p> <p>316. ADDRESS</p> <p>317. CITY</p> <p>318. STATE</p> <p>319. ZIP</p> <p>320. PHONE</p> <p>321. SIGNATURE</p> <p>322. DATE</p>													
<p>323. MAKE</p> <p>324. MODEL</p> <p>325. YEAR</p> <p>326. COLOR</p> <p>327. VIN</p> <p>328. LICENSE NO.</p> <p>329. NAME</p> <p>330. ADDRESS</p>													







