

Property Damage Specialist
P O Box 2002, Indio, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

APPRAISAL REPORT

DAMAGE ASSESSED BY: Roberta Kear

FILE NUMBER: CO13012352
CLAIM NUMBER: CO13012352
DATE OF LOSS: 8/6/2013
TYPE OF LOSS: Collision
APPRAISED FOR: ROBERT MORINO INS - BRIGETTE HEATH

ASSIGNMENT DATE: None
CONTACT DATE: None
INSPECTION DATE: 8/27/2013
REC'D DATE: None

Point(s) of Impact

5 Right Rear Corner (P)

INSURED: Manuel Flores
2323 Gatewood St.
Los Angeles,, CA 90031
(323) 517-4825

CLAIMANT: None

OWNER: Manuel Flores
2323 Gatewood St.
Los Angeles,, CA 90031
(323) 517-4825

BODY SHOP: None

INSPECTION SITE: Insured's Residence
2323 Gatewood St.
Los Angeles, CA 90031

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: No
VEHICLE DRIVEABLE: Yes

Prior Damage:

rear bumper cover, windshield

Comments:

08/27/2013 Inspected insured's 2010 Ford Focus at customer's residence at approx 9:15 am, I met with Manuel, I noted damage to the right side of the rear bumper cover, approx repair time is 2 days. This was a minor impact to the right rear of cust vehicle with no airbag deployment. The cust stated that the scooter that was involved did not impact his vehicle, only the person riding the scooter did, the person impact the right rear corner and knocked the bumper cover off. I noted prior damage to the rear bumper as well and wrote for related prior damage, I also noted prior damage to the windshield and completed an unrelated prior damage estimate. Open items include shop labor rates. This vehicle is repairable.

COMPARISON ESTIMATE:	0.00	TOWING:	0.00	ACTUAL CASH VALUE:	10,825.00
APPRaiser ESTIMATE:	0.00	STORAGE:	0.00	SALVAGE VALUE:	0.00
AGREED UPON AMOUNT:	0.00	DEDUCTIBLE:	500.00	SETTLEMENT:	0.00
				REPAIR VS. ACV:	0.00
DRAFT/CHECK NUMBER:	0			ESTIMATE FEE:	0.00
DRAFT/CHECK AMOUNT:	0.00			TRAVEL EXPENSE:	0.00
DATE ISSUED:	None			PHOTO EXPENSE:	0.00
				MISC EXPENSE:	0.00
				TOTAL CHARGES:	0.00

Date: 8/28/2013 09:54 AM
Estimate ID: CO13012352
Estimate Version: 0
Preliminary
Profile ID: PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795 OR EMAIL
PDS9593@VERIZON.NET

Property Damage Specialist

P O Box 2002, Indio, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORINO INS - BRIGETTE HEATH

Condition Code: Good
Date of Loss: 8/ 6/2013
Deductible: 500.00
File Number: CO13012352
Claim Number: CO13012352

Type of Loss: Collision

Insured: Manuel Flores
Owner: Manuel Flores
Address: 2323 Gatewood St., Los Angeles,, CA 90031
Telephone: Home Phone: (323) 517-4825

Mitchell Service: 911005

Description: 2010 Ford Focus SES
Body Style: 4D Sed
VIN: 1FAHP3GN2AW291946
Mileage: 107,441
OEM/ALT: A
Color: gray metallic
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, TILT STEERING COLUMN
ANTI-LOCK BRAKE SYS., FOG LIGHTS, ALUM/ALLOY WHEELS, AUXILIARY INPUT
SATELLITE RADIO, FRONT AIR DAM, TINTED GLASS, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD/MP3 PLAYER
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM
POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK, REAR SPOILER

Vehicle Production Date: 6/10
Drive Train: 2.0L Inj 4 Cyl 4A FWD
License: 6NRG321 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
<u>Rear Bumper</u>							
1	103016	REF	REFINISH	Rear Bumper Cover			C 2.7
2	103019	BDY	OVERHAUL	Rear Bumper Cover Assy			1.8 #
3	102951	BDY	REMOVE/REPLACE	Rear Bumper Cover	9S4Z 17K835 BAPTM	330.40	INC #
<u>ADDITIONAL OPERATIONS</u>							
4		REF	ADD'L OPR	Clear Coat			1.1
<u>Additional Costs & Materials</u>							
5			ADD'L COST	Paint/Materials		121.60	*

ESTIMATE RECALL NUMBER: 08/28/2013 09:54:25 CO13012352

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 3

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Prior Damage:

rear bumper cover, windshield

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary					Amount		
	Body	1.8	42.00	0.00	0.00	75.60		Taxable Parts					330.40		
	Refinish	3.8	42.00	0.00	0.00	159.60		Sales Tax @ 9.000%					29.74		
	Non-Taxable Labor					235.20		Total Replacement Parts Amount					360.14		
	Labor Summary	5.6				235.20									
III.	Additional Costs					Amount	IV.	Adjustments					Amount		
	Taxable Costs					121.60		Insurance Deductible					500.00-		
	Sales Tax		@	9.000%		10.94		Insurance Prepaid Amount					0.00		
	Total Additional Costs					132.54		Related Prior Damage					460.14-		
	Paint Material Method: Rates							Subtotal of Adjustments Exceeds Gross Total							
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00							Customer Responsibility					727.88-		
						</									

Date: 8/28/2013 09:54 AM
Estimate ID: CO13012352
Estimate Version: 0
Preliminary
Profile ID: PDS

Inspection Site: Insured's Residence
Address: 2323 Gatewood St.
Los Angeles, CA 90031
(323) 517-4825
Inspection Date: 8/27/2013

"THIS IS NOT AN AUTHORIZATION FOR REPAIR NOR A GUARANTEE OF PAYMENT.
YOU MUST CONTACT THE INSURANCE COMPANY TO CONFIRM COVERAGES AND
PAYMENT. THIS APPRAISAL IS SUBJECT TO REVIEW AND ADJUSTMENT."

Date: 8/28/2013 09:54 AM
 Estimate ID: CO13012352
 Related Prior Damage
 Estimate Version: 0
 Preliminary
 Profile ID: PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795 OR EMAIL
 PDS9593@VERIZON.NET

Property Damage Specialist

P O Box 2002, Indio, CA 92201
 (760) 275-6795
 Fax: (760) 863-5349
 Email: PDS9593@VERIZON.NET

Related Prior Damage

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORINO INS - BRIGETTE HEATH

Condition Code: Good
 Date of Loss: 8/ 6/2013

Type of Loss: Collision

File Number: CO13012352
 Claim Number: CO13012352

Insured: Manuel Flores
 Owner: Manuel Flores
 Address: 2323 Gatewood St., Los Angeles,, CA 90031
 Telephone: Home Phone: (323) 517-4825

Mitchell Service: 911005

Description: 2010 Ford Focus SES
 Body Style: 4D Sed
 VIN: 1FAHP3GN2AW291946
 Mileage: 107,441
 OEM/ALT: A
 Color: gray metallic
 Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
 REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, TILT STEERING COLUMN
 ANTI-LOCK BRAKE SYS., FOG LIGHTS, ALUM/ALLOY WHEELS, AUXILIARY INPUT
 SATELLITE RADIO, FRONT AIR DAM, TINTED GLASS, SIDE AIRBAGS, ANTI-THEFT SYSTEM
 SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD/MP3 PLAYER
 ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM
 POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK, REAR SPOILER

Vehicle Production Date: 6/10
 Drive Train: 2.0L Inj 4 Cyl 4A FWD
 License: 6NRG321 CA
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
				<u>Rear Bumper</u>			
1	102951	BDY	REPAIR	Rear Bumper Cover	Existing		4.0* #
2		REF	REFINISH	Rear Bumper Cover			C 2.7
				<u>ADDITIONAL OPERATIONS</u>			
3		REF	ADD'L OPR	Clear Coat			1.1
				<u>Additional Costs & Materials</u>			
4			ADD'L COST	Paint/Materials		121.60 *	

ESTIMATE RECALL NUMBER: 08/28/2013 09:54:25 CO13012352

Mitchell Data Version: OEM: MAY_13_V
 MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
 All Rights Reserved

Page 1 of 3

* - Judgment Item
- Labor Note Applies
C - Included in Clear Coat Calc

Recycler Information Section:

Prior Damage:
rear bumper cover, windshield

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary	Amount
	Body	4.0	42.00	0.00	0.00	168.00			
	Refinish	3.8	42.00	0.00	0.00	159.60		Total Replacement Parts Amount	0.00
	Non-Taxable Labor					327.60			
	Labor Summary	7.8				327.60			
III.	Additional Costs					Amount	IV.	Adjustments	Amount
	Taxable Costs					121.60		Total Adjustments:	0.00
	Sales Tax		@	9.000%		10.94			
	RL - Total Additional Costs					132.54			
	Paint Material Method: Rates								
	Init Rate = 32.00 , Init Max Hours = 99.9, Addl Rate = 0.00								
							I.	RL - Total Labor:	327.60
							II.	RL - Total Replacement Parts:	0.00
							III.	RL - Total Additional Costs:	132.54
								Gross Total:	460.14
							IV.	Total Adjustments:	0.00
								Related Prior - Net Total:	460.14

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact
5 Right Rear Corner (P)

Date: 8/28/2013 09:54 AM
Estimate ID: CO13012352
Related Prior Damage
Estimate Version: 0
Preliminary
Profile ID: PDS

Insurance Co: Robert Moreno Insurance Services
Address: P O Box 5185
Fullerton, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Inspection Site: Insured's Residence
Address: 2323 Gatewood St.
Los Angeles, CA 90031
(323) 517-4825
Inspection Date: 8/27/2013

ESTIMATE RECALL NUMBER: 08/28/2013 09:54:25 CO13012352

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 3 of 3

Date: 8/28/2013 09:54 AM
Estimate ID: CO13012352
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: PDS

FOR SUPPLEMENTS CALL RICH PEREA 760-275-6795 OR EMAIL
PDS9593@VERIZON.NET

Property Damage Specialist

P O Box 2002, Indio, CA 92201
(760) 275-6795
Fax: (760) 863-5349
Email: PDS9593@VERIZON.NET

Unrelated Prior Damage

Damage Assessed By: Roberta Kear

Appraised For: ROBERT MORINO INS - BRIGETTE HEATH

Condition Code: Good
Date of Loss: 8/ 6/2013

Type of Loss: Collision

File Number: CO13012352
Claim Number: CO13012352

Insured: Manuel Flores
Owner: Manuel Flores
Address: 2323 Gatewood St., Los Angeles,, CA 90031
Telephone: Home Phone: (323) 517-4825

Mitchell Service: 911005

Description: 2010 Ford Focus SES
Body Style: 4D Sed
VIN: 1FAHP3GN2AW291946
Mileage: 107,441
OEM/ALT: A
Color: gray metallic
Options: PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, POWER STEERING
REAR WINDOW DEFOGGER, MANUAL AIR CONDITION, TILT STEERING COLUMN
ANTI-LOCK BRAKE SYS., FOG LIGHTS, ALUM/ALLOY WHEELS, AUXILIARY INPUT
SATELLITE RADIO, FRONT AIR DAM, TINTED GLASS, SIDE AIRBAGS, ANTI-THEFT SYSTEM
SIDE HEAD CURTAIN AIRBAGS, AM/FM STEREO CD/MP3 PLAYER
ELECTRONIC STABILITY CONTROL, FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM
POWER HEATED EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK, REAR SPOILER

Vehicle Production Date: 6/10
Drive Train: 2.0L Inj 4 Cyl 4A FWD
License: 6NRG321 CA
Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
					<u>Windshield</u>		
1	100488	GLS	REMOVE/REPLACE	W/Shield Glass	8S4Z 5403100 A	284.68	2.6 #

- Labor Note Applies

ESTIMATE RECALL NUMBER: 08/28/2013 09:54:25 CO13012352

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 1 of 2

Date: 8/28/2013 09:54 AM
Estimate ID: CO13012352
Unrelated Prior Damage
Estimate Version: 0
Preliminary
Profile ID: PDS

Prior Damage:

rear bumper cover, windshield

Estimate Totals

I.	Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II.	Part Replacement Summary						Amount	
	Glass	2.6	42.00	0.00	0.00	109.20		Taxable Parts						284.68	
								Sales Tax @ 9.000%						25.62	
		Non-Taxable Labor				109.20		Total Replacement Parts Amount						310.30	
	Labor Summary	2.6				109.20									
III.	Additional Costs					Amount	IV.	Adjustments						Amount	
	Total Additional Costs					0.00		Total Adjustments:						0.00	
							I.	Total Labor:						109.20	
							II.	Total Replacement Parts:						310.30	
							III.	Total Additional Costs:						0.00	
								Gross Total:						419.50	
							IV.	Total Adjustments:						0.00	
								Unrelated Damage Net Total:						419.50	

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact

5 Right Rear Corner (P)

Insurance Co: Robert Moreno Insurance Services
Address: P O Box 5185
Fullerton, CA 92838
Telephone: (714) 578-3366
Fax Phone: (714) 738-5035

Inspection Site: Insured's Residence
Address: 2323 Gatewood St.
Los Angeles, CA 90031
(323) 517-4825
Inspection Date: 8/27/2013

ESTIMATE RECALL NUMBER: 08/28/2013 09:54:25 CO13012352

Mitchell Data Version: OEM: MAY_13_V
MAPP:MAY_13_V

Software Version: 7.0.485

Copyright (C) 1994 - 2013 Mitchell International
All Rights Reserved

Page 2 of 2






























UTO 08/22/2013 TO 08/22/2014 11 6NRG321

VEHICLE IDENTIFICATION NUMBER

1FAHP3GN2AW291946

BODY TYPE MODEL

4D

DATE ISSUED

07/30/2013

CYLS

DATE FIRST SOLD

00/00/2010

CLASS

EM

MAKE
FORD

Yr. Model

2010

TYPE VEH

120

MP

G

AX

WC

UNLADEN/GCCW

\$188

TOTAL FEES PAID

1900

REGISTERED
OWNER

FLORES MANUEL A
OR QUIJANO ESPERANZA
2323 GATEWOOD ST
LOS ANGELES CA 90031-1104

LIENHOLDERS
0

FORD MOTOR CRDT CO LLC
260 INTERSTATE N PKWY NW
ATLANTA

GA

30339

143071720131201

R0069

L0089

STATE OF CALIFORNIA

DEPARTMENT OF MOTOR VEHICLES

VALIDATED REGISTRATION CARD

READ REVERSE SIDE - IMPORTANT INSTRUCTIONS

08/27/2013
R0098510



